




report date: 2024-12-14

General information

Make	FORD
Model	FUSION ZETEC CLIMATE
Colour	Orange
Year of manufacture	2008
Top speed	101 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	78 BHP
Max. torque	124 Nm at 3.500 rpm
Engine capacity	1.388 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg
CO2 emission	154 g/km
CO2 label	G





MOT history

MOT expiry date	2025-08-05
MOT pass rate	71 %
MOT passed	15
Failed MOT tests	6
Total advice items	22
Total items failed	11

MOT #21	2024-07-29 07:30
MOT test number	176179529652
Result	✓ Passed
Next expiry date	2025-08-05

MOT #20	2023-07-24 12:57
MOT test number	402073577797
Result	✓ Passed

MOT #19	2023-07-24 07:08
MOT test number	303211239477
Result	✗ Failed
<b>Fail</b>	Offside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
<b>Fail</b>	Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #18	2022-08-04 07:06
MOT test number	158923436229
Result	✓ Passed

MOT #17	2021-08-06 07:02
MOT test number	241135518532
Result	✓ Passed



<b>MOT #16</b>	2020-09-18 15:06
<b>MOT test number</b>	208181529781
<b>Result</b>	✓ Passed
<b>Minor</b>	Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))

<b>MOT #15</b>	2020-09-18 10:14
<b>MOT test number</b>	874199407061
<b>Result</b>	✗ Failed
<b>Fail</b>	Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

<b>MOT #14</b>	2019-08-27 15:01
<b>MOT test number</b>	678647830409
<b>Result</b>	✓ Passed

<b>MOT #13</b>	2019-08-27 11:02
<b>MOT test number</b>	659509951922
<b>Result</b>	✗ Failed
<b>Advice</b>	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Fail</b>	Front Brakes imbalanced across an axle (1.2.1 (b) (i))

<b>MOT #12</b>	2018-08-24 09:30
<b>MOT test number</b>	567178513564
<b>Result</b>	✓ Passed



MOT #11 2018-08-21 09:07

MOT test number 641118932247

Result ✗ Failed

**Fail** Offside Front Brake pipe excessively corroded to rear (1.1.11 (c))

**Advice** Nearside Front Fuel Pipe/s corroded to rear

**Fail** Offside Front Brake pipe excessively corroded (1.1.11 (c))

**Fail** Nearside Front Brake pipe excessively corroded to rear (1.1.11 (c))

**Fail** Nearside Front Brake pipe excessively corroded (1.1.11 (c))

**Advice** Offside Front Fuel Pipe/s corroded to rear

**Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))

MOT #10 2017-08-25 15:41

MOT test number 524737576514

Result ✓ Passed

**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)

**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)

**Advice** Fuel Pipe/s corroded

**Advice** Offside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Brake pipe slightly corroded Front to rear (3.6.B.2c)

**Advice** Oil leak



<b>MOT #9</b>	2017-08-25 11:32
<b>MOT test number</b>	597052099051
<b>Result</b>	✗ Failed
<b>Advice</b>	Fuel Pipe/s corroded
<b>Advice</b>	Offside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)
<b>Advice</b>	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
<b>Advice</b>	Brake pipe slightly corroded Front to rear (3.6.B.2c)
<b>Advice</b>	Oil leak
<b>Fail</b>	Parking brake: efficiency below requirements (3.7.B.7)
<b>Advice</b>	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
<b>Advice</b>	Offside Front Brake pipe slightly corroded (3.6.B.2c)
<b>Advice</b>	Offside Rear Brake pipe slightly corroded (3.6.B.2c)

<b>MOT #8</b>	2016-09-02 08:49
<b>MOT test number</b>	489048514722
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Rear Direction indicators slightly discoloured (1.4.A.2f)
<b>Advice</b>	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

<b>MOT #7</b>	2015-09-01 14:35
<b>MOT test number</b>	856852656049
<b>Result</b>	✓ Passed

<b>MOT #6</b>	2014-12-12 10:24
<b>MOT test number</b>	755076544308
<b>Result</b>	✓ Passed



<b>MOT #5</b>	2014-12-12 10:24
<b>MOT test number</b>	889916244344
<b>Result</b>	✗ Failed
<b>Pass with rectification</b>	Nearside Front Headlamp aim too high (1.8)

<b>MOT #4</b>	2013-12-12 09:23
<b>MOT test number</b>	549556143350
<b>Result</b>	✓ Passed

<b>MOT #3</b>	2012-12-19 12:05
<b>MOT test number</b>	867634852300
<b>Result</b>	✓ Passed

<b>MOT #2</b>	2011-12-20 10:42
<b>MOT test number</b>	475324451368
<b>Result</b>	✓ Passed

<b>MOT #1</b>	2011-01-03 14:22
<b>MOT test number</b>	316213501022
<b>Result</b>	✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 August 2025

✓  
**MOT**

**Expires:**  
5 August 2025

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	194
<b>MOT expiry date</b>	5 August 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-




Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





**Vehicle valuation**

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

**More info** >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	VF57KXY
Plate since	2019-09-29
Current registration	VF57KXY
Plate since	2019-09-29

More info >



**Finance check**

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



Mileage check

<b>Odometer</b>	In miles
<b>Mileage registrations</b>	21
<b>First mileage registration</b>	2008-02-27
<b>Last registration</b>	2024-07-29
<b>Complete history</b>	<a href="#">See info</a>



<b>Registration #1</b>	2008-02-27	8 mi
<b>Registration #2</b>	2011-01-03	5.601 mi
<b>Registration #3</b>	2011-12-20	12.025 mi
<b>Registration #4</b>	2012-12-19	18.533 mi
<b>Registration #5</b>	2013-12-12	24.500 mi
<b>Registration #6</b>	2014-12-12	31.280 mi
<b>Registration #7</b>	2015-09-01	35.524 mi
<b>Registration #8</b>	2016-09-02	39.396 mi
<b>Registration #9</b>	2017-08-25	42.974 mi
<b>Registration #10</b>	2017-08-25	42.974 mi
<b>Registration #11</b>	2018-08-21	46.095 mi
<b>Registration #12</b>	2019-08-21	49.216 mi
<b>Registration #13</b>	2020-08-21	52.337 mi
<b>Registration #14</b>	2021-08-21	55.458 mi
<b>Registration #15</b>	2022-08-21	58.579 mi
<b>Registration #16</b>	2023-08-21	61.700 mi
<b>Registration #17</b>	2024-07-29	64.821 mi
<b>Registration #18</b>		
<b>Registration #19</b>		
<b>Registration #20</b>		
<b>Registration #21</b>		

[More info >](#)



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1161 kg
Max. allowed weight	1605 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

**Number of axles**

2

**Engine number**

7T66177