





report date: 2024-03-29

General information

Make	RENAULT
Model	MODUS PRIVILEGE 16V
Colour	Purple
Year of manufacture	2006
Top speed	114 mph
0 - 60 mph	12.3 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	113 BHP
Max. torque	150 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.2 mpg
Consumption extra urban	47.9 mpg
Consumption combined	37.7 mpg
CO2 emission	185 g/km
CO2 label	I



CarCheck.co.uk page 1/15



Internet history

	-	4	-	-	1
ᆮ	п	ш	г١	,	_

EIIII y I	
Date	2021-07-27
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/15



MOT history

MOT expiry date	2024-07-24
MOT pass rate	68 %
MOT passed	15
Failed MOT tests	7
Total advice items	24
Total items failed	16

MOT #22		2023-07-19 14:18
MOT test	number	388500629685
Result		✓ Passed
Next expi	ry date	2024-07-24
Advice	Offside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))	
Advice	Nearside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b)) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))	
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	

CarCheck.co.uk page 3/15



Fail

GX06XBC

report date: 2024-03-29

MOT #21 2023-07-19 11:30

MOT test number 916386552766

Result X Failed

Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Offside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))

Advice Offside Front Coil spring corroded (5.3.1 (b) (i))

Fail Oil leaking excessively from engine (8.4.1 (a) (i))

Advice Nearside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))

Advice Nearside Front Coil spring corroded (5.3.1 (b) (i))

Advice Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #20 2022-07-25 15:28

MOT test number 910450367407

Result
✓ Passed

Advice Undertrays fitted unable to fully inspect

MOT #19 2021-06-21 15:17

MOT test number 411947244419

Result

Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

CarCheck.co.uk page 4/15



report date: 2024-03-29

MOT #18 2021-06-21 09:59

MOT test number 684215998619

Result × Failed

Fail Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Fail Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #17 2020-07-06 14:16

MOT test number 944546671110

Result ✓ Passed

Advice Nearside Rear All direction indicators slightly affected by the operation of another lamp (4.4.3 (b))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #16 2019-10-26 08:30

MOT test number 793542136774

Result \(\sqrt{Passed} \)

MOT #15 2019-10-26 08:30

MOT test number 372444555777

Result × Failed

Pass with rectification Nearside Front Position lamp not working (4.2.1 (a) (ii))

Pass with rectification Offside Registration plate lamp inoperative in the case of a single lamp or all

lamps (4.7.1 (b) (ii))

MOT #14 2018-10-31 14:12

MOT test number 720742259738

CarCheck.co.uk page 5/15



report date: 2024-03-29

MOT test number

Fail Offside Front Position lamp not working (4.2.1 (a))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge void of tread (5.2.3 (e))

Advice Nearside Rear Tyre slightly damaged (5.2.3 (d) (ii))

Fail Front Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))

MOT #12 2018-07-27 15:17 **MOT** test number 265722257910 Result × Failed Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i)) Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i)) Fail Fail Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i)) **Advice** Front Vehicle structure is corroded but structural rigidity is not significantly reduced crossmember badly corroded (6.1.1 (c) (i))

MOT #11	2017-07-26 15:09
MOT test number	281057220827
Result	✓ Passed
Advice Offside Front Brake pad(s) wearing thin (3.5.1g)	

CarCheck.co.uk page 6/15



report date: 2024-03-29

MOT #10	2017-07-26 09:28
MOT test number	530096077229
Result	× Failed
Fail Registration plate lamp not working (1.1.C.1d) Advice Offside Front Brake pad(s) wearing thin (3.5.1g) Fail Offside Rear rear brake binding (3.7.B.1)	

MOT #9	2016-07-05 12:49
MOT test number	436750743403
Result	✓ Passed
MOT #8	2016-07-05 09:25
MOT test number	221565317318
Result	X Failed
Fail Offside Rear coil spring broken (2.4.C.1a)	

MOT #7	2015-07-13 08:56
MOT test number	178694695100
Result	✓ Passed
MOT #6	2014-05-28 09:24
MOT test number	846978044154
Result	✓ Passed
MOT #5	2013-06-04 14:46
MOT test number	379615853160
Result	✓ Passed

CarCheck.co.uk page 7/15



MOT #4 2012-05-29 08:56

MOT test number 885660052109

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2011-05-26 09:29

MOT test number 785016941139

Result ✓ Passed

MOT #2 2010-06-09 10:12

MOT test number 531330560189

Result ✓ Passed

MOT #1 2009-06-10 12:31

MOT test number 253751269448

CarCheck.co.uk page 8/15



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	24 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	1
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 9/15



report date: 2024-03-29

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



faste since

GX06XBC

report date: 2024-03-29

More info >

Owner history For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this RENAULT had different number plates. ober of plates

CarCheck.co.uk page 12/15



report date: 2024-03-29

Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >


CarCheck.co.uk page 13/15



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2006-06-22
Last registration	2023-07-19
Complete history	See info



Registration #1	2006-06-22	24 mi
Registration #2	2009-06-10	10.937 mi
Registration #3	2010-06-09	14.083 mi
Registration #4	2011-05-26	16.865 mi
Registration #5	2012-05-29	19.477 mi
Registration #6	2013-06-04	21.938 mi
Registration #7	2014-05-28	23.985 mi
Registration #8	2015-07-13	26.419 mi
Registration #9	2016-07-05	31.293 mi
Registration #10	2016-07-05	31.293 mi
Registration #11	2017-07-26	42.717 mi
Registration #12	2017-07-26	42.717 mi
Registration #13		11.777 es
Registration #14		71.777 es
Registration #15		71.777 es
Registration #16		71.777 es
Registration #17		11.777 es
Registration #18		71.777 es
Registration #19		11.777 es
Registration #20		71.777 es
Registration #21		71.777 es
Registration #22		71.777 es
Registration #23		11.777 es
Registration #24		70.777 au

More info >



Car features

S0225	Air conditionin
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1960 mm
Height	1589 mm
Length	3792 mm
Wheel base	2482 mm
Kerb weight	1205 kg
Max. allowed weight	1695 kg

Additional information

Fuel tank capacity	49
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 15/1:

Number of axles2Engine numberD014717