






General information

Make	KIA
Model	SOUL CRDI 2
Colour	Silver
Year of manufacture	2009
Top speed	113 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	126 BHP
Max. torque	260 Nm at 1.900 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	61.4 mpg
Consumption combined	54.3 mpg
CO2 emission	137 g/km
CO2 label	E







Internet history

Entry 1	
Date	2021-07-20
Pictures	19
Listing price	View report









source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-15
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	39
Total items failed	6

MOT #17	2024-01-24 14:50
MOT test number	803719579494
Result	✓ Passed
Next expiry date	2025-02-15
Minor Nearside Track rod end ball joint dust cover damaged or deteriorated, budirt (2.1.3 (g) (i))	It preventing the ingress of
Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice Oil leak, but not excessive Boost pipes (8.4.1 (a) (i))	
Advice Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
Minor Windscreen damaged but not adversely affecting driver's view Chip(s) (3	8.2 (a) (i))
Advice Nearside Front Coil spring corroded (5.3.1 (b) (i))	
Minor Offside Track rod end ball joint dust cover damaged or deteriorated, but dirt (2.1.3 (g) (i))	preventing the ingress of
Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened Both	n (1.1.14 (a) (ii))



MOT #16	2024-01-24 14:50
MOT test number	282651792181
Result	🗙 Failed
Advice Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))	
Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Minor Nearside Track rod end ball joint dust cover damaged or deteriorated, but preven dirt (2.1.3 (g) (i))	ting the ingress of
Advice Oil leak, but not excessive Boost pipes (8.4.1 (a) (i))	
Advice Nearside Front Coil spring corroded (5.3.1 (b) (i))	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14	(a) (ii))
Minor Windscreen damaged but not adversely affecting driver's view Chip(s) (3.2 (a) (i)))
Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Minor Offside Track rod end ball joint dust cover damaged or deteriorated, but prevention dirt (2.1.3 (g) (i))	ng the ingress of
Pass with rectificationOffside Rear Tyre has a cut in excess of the requirements deepthe ply or cords (5.2.3 (d) (i))	enough to reach

MOT #15		2023-02-14 12:56
MOT test	number	850780585387
Result		✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Nearside Rear Seat belt slightly damaged (7.1.2 (b) (i))		
Advice Nearside Front Tyre worn close to legal limit/worn on edge Wearing on inner edge (5.2.3 (e))		dge (5.2.3 (e))

MOT #14	2022-01-27 16:54
MOT test number	491626255121
Result	✓ Passed
Advice Nearside Rear Seat belt slightly damaged (7.1.2 (b) (i))	

MJ59ZWY

report date: 2024-03-28





MOT #13		2021-02-16 17:19
MOT test	number	533263275585
Result		✓ Passed
Advice Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))		
Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		L.1.14 (a) (ii))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	

MOT #12	2021-02-15 16:51	
MOT test number	376133145788	
Result	🗙 Failed	
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt		
Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))		
Advice Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))		
Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.	1.14 (a) (ii))	

MOT #11	2020-01-04 12:03
MOT test number	602109631967
Result	Passed
Advice Vehicles internal headlight adjuster altered to recheck lights	
MOT #10	2019-01-14 16:33
MOT test number	131546240576
Result	✓ Passed

Result

MOT #9	2018-07-12 11:57
MOT test number	719654882985
Result	✓ Passed





MOT #8	2017-10-16 08:28
MOT test number	701370691417
Result	✓ Passed
Advice Front brake disc worn, pitted or scored, but not seriously weakened pitted (3.5.1i)	d both inner faces corroded and
Advice N/s of front bumper damaged	
Advice Oil leak lower inter-cooler pipe area	
MOT #7	2016-10-17 11:20

MOT test number 105890692204
Result

МОТ #6	2015-10-16 12:50
MOT test number	279157538818
Result	✓ Passed

MOT #	5	2015-10-16 10:20
MOT te	st number	522734347232
Result		🗙 Failed
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Fail	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)	

MOT #4	2014-10-17 11:15
MOT test number	417590694281
Result	✓ Passed

MOT #3	2013-11-18 14:32
MOT test number	428902323421
Result	✓ Passed
Notice Front and rear brake discs worn / pitted	





MOT #2	2012-11-06 11:45
MOT test number	305931712317
Result	🗙 Failed
Pass with rectification Nearside Headlamp aim too high and too far to t	he left. (1.8)
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Pass with rectification Offside Headlamp aim too high (1.8)	
Notice Child seat fitted not allowing full inspection of adult belt	
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #1		2012-11-06 11:45
MOT test	number	566741412392
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	Child seat fitted not allowing full inspection of adult belt	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	



Tax & MOT check

✓ Taxed Tax due: 1 August 2024	✓ MOT Expires: 15 February 2025
Tax status	Valid until 1 August
Days left	94
MOT expiry date	15 February 2025
Full MOT history	<u>See MOT history</u>

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FET I
Category	AMP
Туре	
Damage 2	AMPLE
Damaye z	6 C C D D
Date	1. St
Category	AMP
Туре	

Extra KIA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this KIA had different number plates.	
Number of plates	,
Current registration	
Carrent registration Pieto since	
Carrent registration Fore circa Carrent registration	器 UK UK
Carrent registration Falo since Carrent registration Falo since	8775-25-29





Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-11-13
Last registration	2024-01-24
Complete history	See info



Registration #1	2009-11-13	6 mi
Registration #2	2012-11-06	28.214 mi
Registration #3	2013-11-18	31.798 mi
Registration #4	2014-10-17	37.309 mi
Registration #5	2015-10-16	42.997 mi
Registration #6	2015-10-16	42.997 mi
Registration #7	2016-10-17	48.110 mi
Registration #8	2017-10-16	53.023 mi
Registration #9	2018-07-12	55.422 mi
Registration #10		11.777 esi
Registration #11		11.777 esi
Registration #12		11.777 esi
Registration #13		11.777 esi
Registration #14		11.777 est
Registration #15		11.777 esi
Registration #16		11.777 est
Registration #17		11.777 mi
Registration #18		11.117 mi





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	87%
Children	86%
Pedestrian	39%
Safety systems	86%
Overall rating	77%
Video	see crash video



Dimensions & weight	
Width	1785 mm
Height	1610 mm
Length	4105 mm
Wheel base	2550 mm
Max. allowed weight	1780 kg
Additional information	

Fuel tank capacity	48 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats	5	
Number of axles CarCheck.co.uk	2	page 14/14

Engine number

D4FB9H514775