



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 D3 SE LUX
Colour	Red
Year of manufacture	2011
Top speed	127 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 2.750 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	61.4 mpg
Consumption combined	48.7 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-07-22
Pictures	1
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2022-09-16
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	5
Total items failed	2

MOT #9	2021-09-17 15:27
MOT test number	722761993170
Result	✓ Passed
Next expiry date	2022-09-16

MOT #8	2021-09-14 15:13
MOT test number	396501982524
Result	✗ Failed
Fail	Rear Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))
Fail	Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #7	2020-09-10 12:39
MOT test number	399484638815
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))



MOT #6	2019-09-14 13:17
---------------	------------------

MOT test number	982185104929
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
---------------	--

Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
---------------	---

MOT #5	2018-04-16 11:20
---------------	------------------

MOT test number	204382321968
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2017-07-31 15:13
---------------	------------------

MOT test number	537467719313
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2016-08-05 11:44
---------------	------------------

MOT test number	329880967590
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2015-08-04 13:27
---------------	------------------

MOT test number	389716615264
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2014-10-25 10:01
---------------	------------------

MOT test number	937328694272
------------------------	--------------

Result	✓ Passed
---------------	----------



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2011-10-13
Last registration	2021-09-17
Complete history	See info



Registration #1	2011-10-13	27 mi
Registration #2	2014-10-25	16.496 mi
Registration #3	2015-08-04	21.318 mi
Registration #4	2016-08-05	26.438 mi
Registration #5	2017-07-31	34.286 mi
Registration #6	2018-04-16	37.177 mi
Registration #7	2019-05-20	39.377 mi
Registration #8	2020-05-20	41.577 mi
Registration #9	2021-05-20	43.777 mi
Registration #10	2022-05-20	45.977 mi
Registration #11	2023-05-20	48.177 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1561 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	1026084
---------------	---------