



TOYOTA




report date: 2024-03-29

General information

Make	TOYOTA
Model	RAV4 D-4D T180
Colour	Green
Year of manufacture	2006
Top speed	124 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	174 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	33.2 mpg
Consumption extra urban	46.3 mpg
Consumption combined	40.4 mpg
CO2 emission	185 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-05-21
Pictures	1
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-06-19
MOT pass rate	71 %
MOT passed	15
Failed MOT tests	6
Total advice items	31
Total items failed	3

MOT #21	2023-06-20 12:41
MOT test number	763676820186
Result	✓ Passed
Next expiry date	2024-06-19
Advice	Floor rusty

MOT #20	2023-06-15 07:30
MOT test number	951906832096
Result	✗ Failed
MAJOR	Nearside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
MAJOR	Central Rear Seat belt buckle missing (7.1.2 (d))
Advice	Floor rusty
MAJOR	Offside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #19	2022-06-09 08:25
MOT test number	680611508326
Result	✓ Passed
Advice	O/s number plate lamp bulb holder insecure
Advice	Some underbody rust
Advice	Fuel filler pipe corroding

**MOT #18**

2022-06-06 09:18

**MOT test number**

103567808972

**Result****✗ Failed****MAJOR** Windscreen washer not working (3.5 (a))**Advice** Some underbody rust**Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))**MAJOR** Seat belt anchorage prescribed area strength or continuity significantly reduced both inner sills (7.1.1 (a) (i))**Advice** Fuel filler pipe corroding**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #17**

2021-06-14 07:44

**MOT test number**

910781389309

**Result****✓ Passed****MOT #16**

2021-06-04 10:51

**MOT test number**

211031499789

**Result****✗ Failed****DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MAJOR** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))**DANGEROUS** Nearside Rear Anti-roll bar linkage ball joint likely to become detached (5.3.4 (a) (ii))**MOT #15**

2020-10-09 08:53

**MOT test number**

926421762498

**Result****✓ Passed****Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #14** 2019-09-26 07:30**MOT test number** 333887568238**Result** ✓ Passed**MOT #13** 2019-09-23 09:13**MOT test number** 423815170278**Result** ✗ Failed**MAJOR** Nearside Brake pipe excessively corroded main (1.1.11 (c))**MAJOR** Offside Rear Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))**MAJOR** Offside Brake pipe excessively corroded main (1.1.11 (c))**MOT #12** 2018-10-19 08:12**MOT test number** 885530569924**Result** ✓ Passed**MOT #11** 2017-10-06 08:38**MOT test number** 341480397759**Result** ✓ Passed**MOT #10** 2016-09-23 09:30**MOT test number** 194936932444**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #9** 2015-09-30 13:39**MOT test number** 136067633487**Result** ✓ Passed

**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #8** 2015-09-30 09:10**MOT test number** 987577463550**Result** ✗ Failed

**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Fail** Centre Exhaust has a major leak of exhaust gases (7.1.2)

**MOT #7** 2014-10-21 09:39**MOT test number** 539164694241**Result** ✓ Passed

**Notice** Engine covers fitted obscuring some components in the engine bay

**Notice** Under-trays fitted obscuring some underside components

**Notice** Rear silencer box has slight corrosion.

**MOT #6** 2014-01-06 16:44**MOT test number** 986936404003**Result** ✓ Passed

**Notice** Tyre pressure monitoring warning lamp on

**Notice** Both front tyres worn on inner edges



<b>MOT #5</b>	2012-10-29 12:07
---------------	------------------

<b>MOT test number</b>	509903502340
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #4</b>	2011-10-05 12:28
---------------	------------------

<b>MOT test number</b>	339428571257
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2011-09-16 11:45
---------------	------------------

<b>MOT test number</b>	707769251222
------------------------	--------------

<b>Result</b>	✗ Failed
---------------	----------

<b>Fail</b>	Nearside Rear Anti-roll bar linkage insecure (2.4.G.1)
-------------	--

<b>MOT #2</b>	2010-09-08 12:01
---------------	------------------

<b>MOT test number</b>	273931150278
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #1</b>	2009-08-18 11:40
---------------	------------------

<b>MOT test number</b>	311020339220
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
19 June 2024

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	305
<b>MOT expiry date</b>	19 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	<b>NM56FYB</b>
Plate since	2024-03-29
Current registration	<b>NM56FYB</b>
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2006-09-02
Last registration	2023-06-20
Complete history	<a href="#">See info</a>



Registration #1	2006-09-02	25 mi
Registration #2	2009-08-18	27.345 mi
Registration #3	2010-09-08	34.416 mi
Registration #4	2011-09-16	41.226 mi
Registration #5	2011-10-05	41.677 mi
Registration #6	2012-10-29	49.744 mi
Registration #7	2014-01-06	56.228 mi
Registration #8	2014-10-21	56.970 mi
Registration #9	2015-09-30	63.624 mi
Registration #10	2015-09-30	63.624 mi
Registration #11	2016-09-23	71.198 mi
Registration #12	2017-10-06	82.089 mi
Registration #13	2018-06-20	95.557 mi
Registration #14	2018-06-20	95.557 mi
Registration #15	2018-06-20	95.557 mi
Registration #16	2018-06-20	95.557 mi
Registration #17	2018-06-20	95.557 mi
Registration #18	2018-06-20	95.557 mi
Registration #19	2018-06-20	95.557 mi
Registration #20	2018-06-20	95.557 mi
Registration #21	2018-06-20	95.557 mi
Registration #22	2018-06-20	95.557 mi
Registration #23	2018-06-20	95.557 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1815 mm
Height	1685 mm
Length	4395 mm
Wheel base	2560 mm
Kerb weight	1595 kg
Max. allowed weight	2190 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	2AD0064421