



report date: 2024-03-28

General information

Make	CITROEN
Model	GRAND C4 PICASSO HDI XTR
Colour	White
Year of manufacture	2011
Top speed	107 mph
0 - 60 mph	14.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	58.9 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E






Internet history

Entry 2


Date	2021-07-15
Pictures	17
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 1

Date	2021-06-29
Pictures	13
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-05-04
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	24
Total items failed	2

MOT #13 2023-05-02 14:58

MOT test number 335465670854

Result ✓ Passed

Next expiry date 2024-05-04

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #12 2022-05-05 08:05

MOT test number 106022721292

Result ✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Direction indicator slightly discoloured Both rear (4.4.3 (a))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Minor** Central Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))

**MOT #11** 2021-04-30 15:59**MOT test number** 197155613576**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2019-07-08 14:13**MOT test number** 996368004700**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2019-07-08 09:18**MOT test number** 706074407083**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Front Direction indicator incorrect colour (4.4.3 (a))**MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #8** 2018-06-30 10:42**MOT test number** 390034368222**Result** ✓ Passed**MOT #7** 2018-06-30 09:02**MOT test number** 932307673183**Result** ✗ Failed**MAJOR** Nearside Front Position lamp not working (4.2.1 (a))**MAJOR** Offside Front Position lamp not working (4.2.1 (a))



<b>MOT #6</b>	2017-07-06 08:53
<b>MOT test number</b>	930260457367
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

<b>MOT #5</b>	2017-07-06 08:53
<b>MOT test number</b>	160013075043
<b>Result</b>	✗ Failed
<b>Pass with rectification</b>	Registration plate lamp not working (1.1.C.1d)
<b>Advice</b>	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
<b>Pass with rectification</b>	Windscreen washer provides insufficient washer liquid (8.2.3)

<b>MOT #4</b>	2016-07-04 10:16
<b>MOT test number</b>	237529836050
<b>Result</b>	✓ Passed

<b>MOT #3</b>	2015-05-30 11:16
<b>MOT test number</b>	357720455190
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
<b>Advice</b>	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
<b>Advice</b>	Offside Front Tyre worn close to the legal limit (4.1.E.1)

<b>MOT #2</b>	2014-05-29 16:26
<b>MOT test number</b>	278019744194
<b>Result</b>	✓ Passed



MOT #1	2014-03-19 12:25
MOT test number	236048674019
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>DK11ZZC</b>
Plate since	2024-03-28
Current registration	<b>DK11ZZC</b>
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-05-11
Last registration	2023-05-02
Complete history	<a href="#">See info</a>



Registration #1	2011-05-11	22 mi
Registration #2	2014-03-19	20.505 mi
Registration #3	2014-05-29	21.460 mi
Registration #4	2015-05-30	51.973 mi
Registration #5	2016-07-04	67.247 mi
Registration #6	2017-07-06	73.847 mi
Registration #7	2017-07-06	73.847 mi
Registration #8	2018-06-30	82.538 mi
Registration #9	2019-05-29	91.277 mi
Registration #10	2019-05-29	91.277 mi
Registration #11	2019-05-29	91.277 mi
Registration #12	2019-05-29	91.277 mi
Registration #13	2019-05-29	91.277 mi
Registration #14	2019-05-29	91.277 mi
Registration #15	2019-05-29	91.277 mi
Registration #16	2023-05-02	91.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1810 mm
Height	1803 mm
Length	4380 mm
Wheel base	2728 mm
Kerb weight	1426 kg
Max. allowed weight	2065 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBEV3007920