



report date: 2024-03-28

General information

Make	NISSAN
Model	ALMERA S
Colour	Blue
Year of manufacture	2003
Top speed	108 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	121 BHP
Max. torque	128 Nm at 2.800 rpm
Engine capacity	1.497 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.8 mpg
CO2 emission	160 g/km
CO2 label	G





## Internet history

### Entry 4

Date	2022-07-11
Pictures	12
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

### Entry 3

Date	2022-01-22
Pictures	12
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

### Entry 2

Date	2021-07-27
Pictures	12
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

### Entry 1


Date	2021-02-02
------	------------

Pictures

10

Listing price

[View report](#)



source: [autoonline.co.uk](http://autoonline.co.uk)



## MOT history

MOT expiry date	2022-06-01
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	23
Total items failed	6

MOT #19	2021-06-02 13:44
MOT test number	182080748152
Result	✓ Passed
Next expiry date	2022-06-01

MOT #18	2021-06-02 13:44
MOT test number	814433865378
Result	✗ Failed
Pass with rectification	Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Pass with rectification	Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #17	2019-11-26 09:25
MOT test number	320220066607
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Minor	Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
Advice	Front cross member corroded
Minor	Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**MOT #16**

2018-11-27 14:56

**MOT test number**

472328720911

**Result**

✓ Passed

- Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Front cross member corroded & holed
- Advice** Rear Engine mounting damaged but not to excess (6.1.8 (a) (i))

**MOT #15**

2018-11-23 11:27

**MOT test number**

284394547086

**Result**

✗ Failed

- Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Advice** Rear Engine mounting damaged but not to excess (6.1.8 (a) (i))
- Advice** Front both top suspension mounting noisy in operation
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Front cross member corroded & holed
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))

**MOT #14**

2017-10-30 14:36

**MOT test number**

428869774812

**Result**

✓ Passed

- Advice** Parking brake only just met required efficiency 19%
- Advice** Nearside Front Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)

**MOT #13** 2016-11-30 15:28**MOT test number** 786619132869**Result** ✓ Passed**MOT #12** 2016-11-30 10:39**MOT test number** 516293207980**Result** ✗ Failed**Fail** Front registration plate delaminated (6.3.1d)**MOT #11** 2015-11-18 09:20**MOT test number** 444861692936**Result** ✓ Passed**Advice** Slight damage to n/s head lamp mountings**Advice** Slight blow to rear box**Advice** Slight damage to front number plate.**MOT #10** 2015-01-06 09:09**MOT test number** 106626705056**Result** ✓ Passed**MOT #9** 2014-01-10 09:00**MOT test number** 599820414008**Result** ✓ Passed**MOT #8** 2013-01-14 09:52**MOT test number** 527404413020**Result** ✓ Passed

**MOT #7** 2012-01-06 09:07**MOT test number** 789486502049**Result** ✓ Passed**MOT #6** 2010-12-06 12:20**MOT test number** 470790640436**Result** ✓ Passed**MOT #5** 2010-01-04 15:52**MOT test number** 583054100082**Result** ✓ Passed**MOT #4** 2008-12-12 12:51**MOT test number** 954307748397**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2007-12-18 09:21**MOT test number** 583062657323**Result** ✓ Passed**MOT #2** 2006-12-20 17:24**MOT test number** 424804256401**Result** ✓ Passed



MOT #1	2006-12-20 11:45
MOT test number	990174856355
Result	✗ Failed
Fail	Offside Front Headlamp not working on dipped beam (1.7.5a)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)





Tax & MOT check

✕  
Untaxed

Tax expired:  
26 September 2020

✕  
MOT

Expired:  
1 June 2022

Tax status

Expired at 26 September

Days left

1310 days too late

MOT expiry date

1 June 2022

Full MOT history

[See MOT history](#)

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2003-11-28
Last registration	2021-06-02
Complete history	<a href="#">See info</a>



Registration #1	2003-11-28	17 mi
Registration #2	2006-12-20	24.102 mi
Registration #3	2006-12-20	24.102 mi
Registration #4	2007-12-18	29.100 mi
Registration #5	2008-12-12	34.191 mi
Registration #6	2010-01-04	39.139 mi
Registration #7	2010-12-06	43.815 mi
Registration #8	2012-01-06	53.575 mi
Registration #9	2013-01-14	59.369 mi
Registration #10	2014-01-10	64.972 mi
Registration #11	2015-01-06	69.850 mi
Registration #12	2015-11-18	74.374 mi
Registration #13	2016-01-01	75.000 mi
Registration #14	2016-01-01	75.000 mi
Registration #15	2016-01-01	75.000 mi
Registration #16	2016-01-01	75.000 mi
Registration #17	2016-01-01	75.000 mi
Registration #18	2016-01-01	75.000 mi
Registration #19	2016-01-01	75.000 mi
Registration #20	2016-01-01	75.000 mi
Registration #21	2016-01-01	75.000 mi
Registration #22	2016-01-01	75.000 mi
Registration #23	2016-01-01	75.000 mi
Registration #24	2016-01-01	75.000 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1706 mm
Height	1448 mm
Length	4184 mm
Wheel base	2535 mm
Kerb weight	1170 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	197826