



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	COROLLA VERSO D-4D T2
Colour	Silver
Year of manufacture	2008
Top speed	122 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	310 Nm at 2.800 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.8 mpg
CO2 emission	167 g/km
CO2 label	H






Internet history

Entry 1

Date	2022-05-15
Pictures	33
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2024-05-05
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	23
Total items failed	4

MOT #16	2023-05-06 09:56
MOT test number	664271212689
Result	✓ Passed
Next expiry date	2024-05-05
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #15	2023-05-06 09:56
MOT test number	510857124188
Result	✗ Failed
Pass with rectification	Offside Headlamp aim too low (4.1.2 (a))
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #14	2022-05-05 11:17
MOT test number	373015704657
Result	✓ Passed

MOT #13	2021-03-17 13:35
MOT test number	629457725645
Result	✓ Passed

**MOT #12** 2021-03-17 13:35**MOT test number** 515296496102**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #11** 2020-03-25 13:33**MOT test number** 301010909221**Result** ✓ Passed**Minor** Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))**MOT #10** 2019-03-22 15:28**MOT test number** 803181860591**Result** ✓ Passed**Advice** Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**Advice** Offside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**MOT #9** 2018-03-23 09:35**MOT test number** 345404224558**Result** ✓ Passed**Advice** Rearmost seats unable to be unfolded due to dog guard fitment so not inspected. (7 Seat vehicle)**Advice** Offside Rear Tyre sidewall slight damage; no exposed inner cords.

**MOT #8** 2018-03-23 09:35**MOT test number** 925645673003**Result** ✗ Failed**Advice** Rearmost seats unable to be unfolded due to dog guard fitment so not inspected. (7 Seat vehicle)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Rear Tyre sidewall slight damage; no exposed inner cords.**MOT #7** 2017-03-24 09:34**MOT test number** 439221817337**Result** ✓ Passed**Advice** Offside Rear Tyre has cut in sidewall below requirements and no exposed inner cords**Advice** Nearside Front Tyre has cut in sidewall below requirements and no exposed cords**MOT #6** 2016-03-22 15:44**MOT test number** 818443541769**Result** ✓ Passed**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2015-03-25 09:22**MOT test number** 706454085014**Result** ✓ Passed**Notice** Offside rear tyre slight damage to sidewall; no exposed inner cords

**MOT #4** 2014-03-26 09:23**MOT test number** 165535384040**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Offside front tyre has damage to sidewall; no exposed inner cords.**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Nail in nearside rear tyre**MOT #3** 2013-03-05 09:27**MOT test number** 657014263048**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #2** 2012-03-26 09:29**MOT test number** 197636682462**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**MOT #1** 2011-03-28 14:54**MOT test number** 986307881028**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
5 May 2024

Tax status	Valid until 1 June
Days left	34
MOT expiry date	5 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-03-26
Last registration	2023-05-06
Complete history	See info



Registration #1	2008-03-26	29 mi
Registration #2	2011-03-28	23.460 mi
Registration #3	2012-03-26	31.312 mi
Registration #4	2013-03-05	38.565 mi
Registration #5	2014-03-26	46.316 mi
Registration #6	2015-03-25	54.105 mi
Registration #7	2016-03-22	62.300 mi
Registration #8	2017-03-24	71.072 mi
Registration #9	2018-03-23	77.799 mi
Registration #10	2019-03-22	85.377 mi
Registration #11	2020-03-22	93.377 mi
Registration #12	2021-03-22	101.377 mi
Registration #13	2022-03-22	109.377 mi
Registration #14	2023-03-22	117.377 mi
Registration #15	2024-03-22	125.377 mi
Registration #16	2025-03-22	133.377 mi
Registration #17	2026-03-22	141.377 mi
Registration #18	2027-03-22	149.377 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1660 mm
Length	4360 mm
Wheel base	2750 mm
Kerb weight	1495 kg
Max. allowed weight	2160 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	2AD5364188