



General information

Make	MINI
Model	MINI (R58) ONE D
Colour	Red
Year of manufacture	2011
Top speed	114 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	215 Nm at 1.750 rpm
Engine capacity	1.600 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-11-07
Pictures	4
Listing price	View report



source: cargurus.co.uk





MOT history

MOT expiry date	2024-12-13
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	28
Total items failed	6

MOT #13	2023-12-14 15:20
MOT test number	508645136545
Result	✓ Passed
Next expiry date	2024-12-13
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front side lamp condensation inside lamp
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Outer Road wheel slightly distorted (5.2.2 (c) (i))

MOT #12	2023-12-12 11:23
MOT test number	514388881741
Result	✗ Failed
Advice	Nearside Front Outer Road wheel slightly distorted (5.2.2 (c) (i))
Advice	Half reverse lamp working os inop
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Fail	Nearside Front Position lamp not working full of water (4.2.1 (a) (ii))
Advice	Offside Front side lamp condensation inside lamp
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #11** 2022-01-20 10:54**MOT test number** 175026513327**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**MOT #10** 2020-10-01 11:03**MOT test number** 896324442006**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened N/S AND O/S (1.1.14 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened N/S AND O/S (1.1.14 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2019-10-30 16:19**MOT test number** 158282514747**Result** ✓ Passed**Advice** Brake disc worn, pitted or scored, but not seriously weakened all (1.1.14 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2019-10-30 09:56**MOT test number** 517535004879**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Brake disc worn, pitted or scored, but not seriously weakened all (1.1.14 (a) (ii))

**MOT #7** 2018-10-30 15:59**MOT test number** 801866006997**Result** ✓ Passed**Advice** Nearside Rear tyre sidewalls cracked and tread cuts**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #6** 2018-10-29 11:35**MOT test number** 546222697694**Result** ✗ Failed**Advice** Nearside Rear tyre sidewalls cracked and tread cuts**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm outer edge (5.2.3 (e))**Fail** Driver's view of an obligatory external mirror materially affected by an obstruction (3.1 (a) (ii))**MOT #5** 2017-10-28 08:18**MOT test number** 535551603326**Result** ✓ Passed**Advice** Nearside Rear tyre sidewalls cracked**Advice** Nearside Rear brake slight bind**Advice** Nearside Rear tyre sidewalls cracked**Advice** Nearside Rear tyre sidewalls cracked**MOT #4** 2016-10-18 13:07**MOT test number** 179659907793**Result** ✓ Passed



MOT #3	2016-10-18 08:50
MOT test number	636141530267
Result	✗ Failed
<div><div>Fail</div>Windscreen washer provides insufficient washer liquid (8.2.3)</div>	

MOT #2	2015-10-28 11:42
MOT test number	413780406364
Result	✓ Passed

MOT #1	2014-10-21 09:46
MOT test number	679094194263
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
13 December 2024

Tax status	Valid until 1 January
Days left	247
MOT expiry date	13 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-28
Current registration	
Plate since	2019-09-28

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-12-06
Last registration	2023-12-14
Complete history	See info



Registration #1	2011-12-06	11 mi
Registration #2	2014-10-21	11.009 mi
Registration #3	2015-10-28	16.933 mi
Registration #4	2016-10-18	24.259 mi
Registration #5	2016-10-18	24.259 mi
Registration #6	2017-10-28	32.467 mi
Registration #7	2018-10-29	39.628 mi
Registration #8	2018-10-30	39.635 mi
Registration #9	2019-10-29	39.635 mi
Registration #10	2019-10-29	39.635 mi
Registration #11	2019-10-29	39.635 mi
Registration #12	2019-10-29	39.635 mi
Registration #13	2019-10-29	39.635 mi
Registration #14	2019-10-29	39.635 mi
Registration #15	2019-10-29	39.635 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1090 kg
Max. allowed weight	1540 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	70967993