





report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOURAN S 5 STR
Colour	Blue
Year of manufacture	2008
Top speed	111 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	148 Nm at 3.800 rpm
Engine capacity	1.595 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.4 mpg
Consumption extra urban	44.1 mpg
Consumption combined	34.9 mpg
CO2 emission	193 g/km
CO2 label	J



CarCheck.co.uk page 1/12



report date: 2024-03-29

MOT history

MOT expiry date	2023-11-14
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	28
Total items failed	9

MOT #18	2022-11-15 13:55
MOT test number	844120543724
Result	✓ Passed
Next expiry date	2023-11-14

MOT #17		2021-09-04 09:20
MOT test	number	761392404567
Result		✓ Passed
Advice	Offside Rear Tyre has a cut but not deep enough to reach the ply or cords	(5.2.3 (d) (i))
Advice Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))		
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Advice (5.3.4 (a) (Offside Front Inner Suspension arm pin or bush worn but not resulting in e	excessive movement

MOT #16		2020-07-13 09:49
MOT test	number	406155952500
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 2/12



LM08KTX report date: 2024-03-29

MOT #15 2020-07-10 12:06

MOT test number 634354502776

Result X Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14 2019-05-31 09:20

MOT test number 970604411352

Result ✓ Passed

Advice Nearside Front Tyre slightly damaged/cracking or perishing plus worn on inner edge (5.2.3 (d) (ii))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #13 2019-05-28 08:07

MOT test number 318354285164

Result ★ Failed

Minor Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Advice Nearside Front Tyre slightly damaged/cracking or perishing plus worn on inner edge (5.2.3 (d) (ii))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #12 2018-06-04 11:56

MOT test number 429978107090

Result \rightarrow Passed

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #11 2017-06-17 10:36

MOT test number 563999554210

Result ✓ Passed

MOT #10 2017-06-07 10:22

MOT test number 347358591030

Result X Failed

Fail Electronic stability system warning lamp indicates a fault (3.4.1c)

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #9 2016-06-11 09:56

MOT test number 254237871704

Result ✓ Passed

Advice Eml lights displayed

MOT #8 2016-06-10 10:53

MOT test number 692993087614

Result X Failed

Fail Registration plate lamp not working (1.1.C.1d)

Fail Nearside Front Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

MOT #7 2015-06-22 12:04

MOT test number 216233775444

Result

Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Notice Mil light on

Advice Rear Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT test number

Result

Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Notice

Condenstion on off side rear lamp

Advice

Rear Brake pad(s) wearing thin (3.5.1g)

Notice

Mil light on

MOT #5	2013-06-12 16:53
MOT test number	487963763113
Result	✓ Passed
MOT #4	2013-06-12 12:37
MOT test number	516123663126
Result	X Failed
Fail Nearside Rear reflector more than 50% obscured (1.5.1b)	
Notice ENGINE MANAGEMENT LIGHT ON	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice NEARSIDE REAR TYRE PERISHING	

MOT #3		2012-06-22 09:41
MOT test	number	475064072180
Result		✓ Passed
Notice	TOWING EYE FITTED TO FRONT OF VEHICLE	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	Child seat fitted not allowing full inspection of adult belt	
Notice	ENGINE MANAGEMENT LIGHT ON	

CarCheck.co.uk page 5/12



LM08KTX report date: 2024-03-29

MOT #2 2011-06-24 09:04

MOT test number 995505971123

Result ✓ Passed

MOT #1 2011-03-03 17:54

MOT test number 848862761039

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date

Category

Type

Date

Damage 2

Category

Type



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this VOLKSWAGEN had different number plates. mber of plates. -More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-04-21
Last registration	2022-11-15
Complete history	See info



Registration #1	2008-04-21	24 mi
Registration #2	2011-03-03	25.400 mi
Registration #3	2011-06-24	27.183 mi
Registration #4	2012-06-22	32.921 mi
Registration #5	2013-06-12	37.668 mi
Registration #6	2013-06-12	37.668 mi
Registration #7	2014-06-12	41.891 mi
Registration #8	2015-06-22	46.067 mi
Registration #9	2016-06-10	49.541 mi
Registration #10	2016-06-11	49.541 mi
Registration #10 Registration #11	2016-06-11	49.541 mi
_	2016-06-11	49.541 mi
Registration #11	2016-06-11	49.541 mi
Registration #11 Registration #12	2016-06-11	49.541 mi
Registration #11 Registration #12 Registration #13	2016-06-11	49.541 mi
Registration #11 Registration #12 Registration #13 Registration #14	2016-06-11	49.541 mi
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15	2016-06-11	49.541 mi
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15 Registration #16	2016-06-11	49.541 mi

More info >

CarCheck.co.uk page 11/12



LM08KTX report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1472 kg
Max. allowed weight	2140 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	5
CarChaeleeaule	maga 12/12

CarCheck.co.uk page 12/12

Number of seats	7
Engine number	BSE 714177