





report date: 2024-03-28

General information

Make	VAUXHALL
Model	COMBO 2000 L1H1 CDTI SPORTIVE
Colour	White
Year of manufacture	2012
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	67.3 mpg
Consumption combined	56.5 mpg



CarCheck.co.uk page 1/11



Internet history

_	_	_		_	-
드	n	C	ľν	7	1

ciitiy 1	
Date	2021-02-05
Pictures	0
Listing price	View report

source: autoonline.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2021-10-06
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	10
Total items failed	5

MOT #9	2020-10-07 11:48
MOT test number	850022236125
Result	✓ Passed
Next expiry date	2021-10-06
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #8	2020-10-07 11:48
MOT test number	624613306218
Result	X Failed
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Pass with rectification Offside Stop lamp(s) not working (4.3.1 (a) (ii))	

MOT #7	2019-03-27 15:12
MOT test number	513658683070
Result	✓ Passed
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

CarCheck.co.uk page 3/11



LR12VDF

report date: 2024-03-28

MOT #6

MOT test number

907832025413

Result

Advice Front wipers slightly smearing

Advice Front Oil leak

MOT test number

Result

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Front Oil leak

Fail Front Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)

Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

 MOT #4
 2017-03-23 19:46

 MOT test number
 476642648793

 Result
 ✓ Passed

 MOT #3
 2016-03-29 17:43

 MOT test number
 344501495560

 Result
 ✓ Passed

MOT #2

MOT test number

Result

Notice Oil leak from engine


Notice Nsf tyre worn

CarCheck.co.uk page 4/11



LR12VDF

report date: 2024-03-28



CarCheck.co.uk page 5/11



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category

Type

Damage 2

Date

Category

Type



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

Owner history	
For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downlo here.	
NAME OF TAXABLE PARTY O	

99999999	

	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	UK NE
Plate since	
Current registration	UK NE
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info


More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2012-03-28
Last registration	2020-10-07
Complete history	See info



Registration #1	2012-03-28	6 mi
Registration #2	2015-03-20	53.577 mi
Registration #3	2016-03-29	63.285 mi
Registration #4	2017-03-23	74.379 mi
Registration #5	2018-03-22	86.201 mi
Registration #6		11.777 es
Registration #6 Registration #7		11.777 es
-		11.77 m
Registration #7		11.777 es 11.777 es 11.777 es

More info >

CarCheck.co.uk page 10/11



Additional information

Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	4457930

CarCheck.co.uk page 11/11