



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	AVENSIS D-CAT T4
Colour	Grey
Year of manufacture	2012
Top speed	127 mph
0 - 60 mph	9.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	150 BHP
Max. torque	340 Nm at 2.800 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	53.3 mpg
Consumption combined	45.6 mpg
CO2 emission	165 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-09-21
Pictures	1
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-31
MOT pass rate	56 %
MOT passed	9
Failed MOT tests	7
Total advice items	29
Total items failed	9

MOT #16	2023-05-30 16:13
MOT test number	398996047542
Result	✓ Passed
Next expiry date	2024-05-31
Advice	Offside Front Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Offside Front Tyre worn close to legal limit/worn on edge worn on edges (5.2.3 (e))
Advice	Fluid leak, but not excessive signs of water leak under car (8.4.1 (a) (i))

MOT #15	2023-05-30 08:56
MOT test number	915662275968
Result	✗ Failed
Advice	Nearside Front fog lamp not working
Advice	Offside Front Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Offside Front Tyre worn close to legal limit/worn on edge worn on edges (5.2.3 (e))
Advice	Fluid leak, but not excessive signs of water leak under car (8.4.1 (a) (i))

**MOT #14** 2022-05-04 16:42**MOT test number** 350058622142**Result** ✓ Passed**Advice** Offside Front Washer jet low, but still clearing screen**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #13** 2022-05-04 16:42**MOT test number** 475637210469**Result** ✗ Failed**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Pass with rectification** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Offside Front Washer jet low, but still clearing screen**MOT #12** 2021-05-19 12:27**MOT test number** 287756707607**Result** ✓ Passed**MOT #11** 2020-06-01 12:58**MOT test number** 672679162626**Result** ✓ Passed**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside washer jet not working but nearside provides sufficient water**MOT #10** 2019-05-31 15:23**MOT test number** 107396045436**Result** ✓ Passed

**MOT #9** 2019-05-31 12:14**MOT test number** 834303461224**Result** ✗ Failed**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened nearside and offside (1.1.14 (a) (ii))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #8** 2018-05-24 15:43**MOT test number** 350241408731**Result** ✓ Passed**MOT #7** 2018-05-24 13:42**MOT test number** 277571972287**Result** ✗ Failed**Fail** Nearside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Windscreen washer not working (3.5 (a))**MOT #6** 2017-05-22 14:58**MOT test number** 120700479842**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #5** 2017-05-22 13:32**MOT test number** 169304919079**Result** ✗ Failed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside Front Tyre worn close to the legal limit badly worn (4.1.E.1)**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #4** 2016-06-03 11:31**MOT test number** 716478835216**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened nearside and offside in poor condition (3.5.1i)**MOT #3** 2016-06-03 10:08**MOT test number** 925955381201**Result** ✗ Failed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened nearside and offside in poor condition (3.5.1i)**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #2** 2015-05-26 11:29**MOT test number** 196596945176**Result** ✓ Passed**Notice** Wiper blades smearing



MOT #1	2015-05-26 10:16
MOT test number	749876845129
Result	✗ Failed
Notice	Wiper blades smearing
Fail	Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
31 May 2024

Tax status	Valid until 1 November
Days left	187
MOT expiry date	31 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	FD12GVE
Plate since	2024-03-28
Current registration	FD12GVE
Plate since	2024-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2012-06-06
Last registration	2023-05-30
Complete history	See info



Registration #1	2012-06-06	24 mi
Registration #2	2015-05-26	37.804 mi
Registration #3	2015-05-26	37.804 mi
Registration #4	2016-06-03	50.601 mi
Registration #5	2016-06-03	50.601 mi
Registration #6	2017-05-22	60.861 mi
Registration #7	2017-05-22	60.861 mi
Registration #8	2018-05-24	70.108 mi
Registration #9	2018-05-24	70.108 mi
Registration #10	2019-05-29	75.377 mi
Registration #11	2019-05-29	75.377 mi
Registration #12	2019-05-29	75.377 mi
Registration #13	2019-05-29	75.377 mi
Registration #14	2019-05-29	75.377 mi
Registration #15	2019-05-29	75.377 mi
Registration #16	2019-05-29	75.377 mi
Registration #17	2019-05-29	75.377 mi
Registration #18	2019-05-29	75.377 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	53%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1480 mm
Length	4710 mm
Wheel base	2700 mm
Kerb weight	1650 kg
Max. allowed weight	2140 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2

Engine number

2AD5667241