



report date: 2024-03-29

General information

Make	SUZUKI
Model	SWIFT SZ3 DDIS
Colour	Blue
Year of manufacture	2011
Top speed	103 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	190 Nm at 1.750 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	78.5 mpg
Consumption combined	67.3 mpg
CO2 emission	109 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-02-04
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-07-19
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	32
Total items failed	18

MOT #13	2023-07-20 08:35
MOT test number	840372468851
Result	✓ Passed
Next expiry date	2024-07-19
Advice	Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Advice	Dpf light on, but engine light not illuminated
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Play in steering rack inner joint(s)

**MOT #12**

2023-07-19 10:46

MOT test number

427506031912

Result

✗ Failed

Fail Fuel system component leaking Fuel filter (6.1.3 (b) (i))**Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Fail** Nearside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rearmost (5.3.4 (a) (i))**Advice** Dpf light on, but engine light not illuminated**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Play in steering rack inner joint(s)**MOT #11**

2022-03-25 09:15

MOT test number

902861758271

Result

✓ Passed

Advice Nearside Front coil spring not correctly mounted but secure**Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**MOT #10**

2021-03-26 10:04

MOT test number

265849183921

Result

✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9**

2021-03-24 15:45

MOT test number

202019215994

Result**✗ Failed**

- Fail** Nearside Rear Brake pipe excessively corroded (1.1.11 (c))
- Fail** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Fail** Offside Rear Inner Brake pipe excessively corroded front too rear (1.1.11 (c))
- Fail** Offside Front Brake pipe excessively corroded (1.1.11 (c))
- Advice** Offside Rear Nail in tyre
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Headlamp aim too high (4.1.2 (a))
- Fail** Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))
- Fail** Nearside Front Brake pipe excessively corroded (1.1.11 (c))
- Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Headlamp aim too high (4.1.2 (a))

**MOT #8** 2019-11-25 11:15**MOT test number** 172918374143**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**Advice** Nearside Front Upper Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))**Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2019-11-25 11:15**MOT test number** 871677462932**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Nearside Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**Advice** Nearside Front Upper Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #6** 2018-06-14 12:25**MOT test number** 451901927914**Result** ✓ Passed**Advice** Nearside Play in steering rack inner joint(s)

**MOT #5** 2018-06-13 14:03**MOT test number** 265823290489**Result** ✗ Failed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Play in steering rack inner joint(s)**Fail** Front Brakes imbalanced across an axle (1.2.1 (b) (i))**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Nearside Front Position lamp not working (4.2.1 (a))**MOT #4** 2017-06-10 11:38**MOT test number** 662860316071**Result** ✓ Passed**MOT #3** 2016-06-17 15:22**MOT test number** 664414900815**Result** ✓ Passed**MOT #2** 2015-06-05 15:55**MOT test number** 825846555161**Result** ✓ Passed**Notice** Rear wiper split**MOT #1** 2014-06-07 11:12**MOT test number** 168648254176**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
19 July 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	19 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	SY11XEC
Plate since	2019-03-29
Current registration	SY11XEC
Plate since	2019-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-06-23
Last registration	2023-07-20
Complete history	See info



Registration #1	2011-06-23	17 mi
Registration #2	2014-06-07	15.822 mi
Registration #3	2015-06-05	28.337 mi
Registration #4	2016-06-17	40.719 mi
Registration #5	2017-06-10	52.629 mi
Registration #6	2018-06-13	66.658 mi
Registration #7	2018-06-14	66.661 mi
Registration #8	2019-11-25	79.462 mi
Registration #9	2020-06-07	92.277 mi
Registration #10	2021-06-07	105.092 mi
Registration #11	2022-06-07	117.907 mi
Registration #12	2023-06-07	130.722 mi
Registration #13	2024-06-07	143.537 mi
Registration #14	2025-06-07	156.352 mi
Registration #15	2026-06-07	169.167 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	62%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1510 mm
Length	3850 mm
Wheel base	2430 mm
Kerb weight	1170 kg
Max. allowed weight	1560 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	D13A-1615222