





report date: 2024-03-28

#### General information

| Make                | AUDI           |
|---------------------|----------------|
| Model               | A3 TDI         |
| Colour              | White          |
| Year of manufacture | 2008           |
| Top speed           | 115 mph        |
| 0 - 60 mph          | 12.3 seconds   |
| Gearbox             | 5 speed Manual |

### Engine & fuel consumption

| Power                   | 103 BHP             |
|-------------------------|---------------------|
| Max. torque             | 250 Nm at 1.900 rpm |
| Engine capacity         | 1.896 сс            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 44.1 mpg            |
| Consumption extra urban | 65.7 mpg            |
| Consumption combined    | 55.4 mpg            |
| CO2 emission            | 134 g/km            |
| CO2 label               | E                   |



CarCheck.co.uk page 1/11



SE08NCY report date: 2024-03-28

MOT history

| MOT expiry date    | 2021-08-02 |
|--------------------|------------|
| MOT pass rate      | 77 %       |
| MOT passed         | 10         |
| Failed MOT tests   | 3          |
| Total advice items | 9          |
| Total items failed | 8          |

| MOT #13  |        | 2020-07-29 13:37         |
|--|--------|--------------------------|
| MOT test   | number | 609327880847             |
| Result   |        | ✓ Passed                 |
| Next expiry date 2021-08-0   |        | 2021-08-02               |
| Advice Offside Front Tyre worn close to legal limit/worn on edge wearing on inner edge (5.2.3 (e)) |        |                          |
| Advice Nearside Rear Tyre worn close to legal limit/worn on edge wearing on inner edge (5.2.3 (e)) |        | n inner edge (5.2.3 (e)) |

| MOT #12  | 2020-07-28 14:26 |  |
|--|------------------|--|
| MOT test number  | 865719866800     |  |
| Result   | <b>×</b> Failed  |  |
| Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))                       |                  |  |
| Advice Nearside Rear Tyre worn close to legal limit/worn on edge wearing on inner edge (5.2.3 (e)) |                  |  |
| Fail Offside Front Anti-roll bar linkage ball joint excessively worn droplink (5.3.4 (a) (i))      |                  |  |
| Advice Offside Front Tyre worn close to legal limit/worn on edge wearing on inner edge.            | dge (5.2.3 (e))  |  |

CarCheck.co.uk page 2/11



report date: 2024-03-28

| MOT #11   | 2019-08-03 09:43                             |
|---|--|
| MOT test number   | 174092026531                                 |
| Result  | ✓ Passed                                     |
| Advice Offside Front Anti-roll bar linkage  | e ball joint has slight play (5.3.4 (a) (i)) |
| Advice Nearside Front Tyre worn close t   | to legal limit/worn on edge (5.2.3 (e))      |
| Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) |  |
| Advice Offside Front Tyre worn close to   | legal limit/worn on edge (5.2.3 (e))         |

| MOT #10         | 2018-07-26 11:41 |
|-----------------|------------------|
| MOT test number | 810663716075     |
| Result          | <b>√</b> Passed  |
|                 |                  |
| MOT #9          | 2017-06-10 08:56 |
| MOT test number | 635213189767     |
| Result          | <b>√</b> Passed  |
|                 |                  |
| MOT #8          | 2017-06-10 08:56 |

| MOT #8 | 3                  |  | 2017-06-10 08:56 |
|--------|--------------------|--|------------------|
| MOT te | st number          |  | 766700444615     |
| Result |                    |  | <b>×</b> Failed  |
| Pass   | with rectification | Nearside Rear Stop lamp not working (1.2.1b)                 |                  |
| Pass   | with rectification | Nearside Rear Registration plate lamp not working (1.1.C.1d) |                  |

| MOT #7  | 2016 06 24 00:12 |
|---|------------------|
| MOT #7  | 2016-06-24 09:13 |
| MOT test number   | 709832442357     |
| Result  | ✓ Passed         |
| Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1) |                  |

CarCheck.co.uk page 3/11



MOT #1

Result

**MOT** test number

**SE08NCY** 

report date: 2024-03-28

2011-06-30 16:11

428641181119

✓ Passed

| MOT #6  | 2015-07-08 09:14                 |
|---|----------------------------------|
| MOT test number   | 767339285132                     |
| Result  | ✓ Passed                         |
|   |                                  |
| MOT #5  | 2014-08-01 11:52                 |
| MOT test number   | 936823714216                     |
| Result  | ✓ Passed                         |
| NOT #4  | 2012 07 21 16:22                 |
| MOT #4 MOT test number  | 2013-07-31 16:23<br>409672113238 |
| Result  | <b>√</b> Passed                  |
| Result  | <b>V</b> 1 03360                 |
| MOT #3  | 2013-07-30 15:07                 |
| MOT test number   | 607901513211                     |
| Result  | <b>×</b> Failed                  |
| Fail Offside Inner Front Brake pad(s) less than 1.5 mm thick (3.5.1g) |                                  |
| Fail Nearside Rear Registration plate lamp not working (1.1.C.1d)     |                                  |
| Fail Inner Brake pad(s) less than 1.5 mm thick (3.5.1g)               |                                  |
| Fail Offside Rear Stop lamp not working (1.2.1b)                      |                                  |
|   |                                  |
| MOT #2  | 2012-07-27 12:22                 |
| MOT test number   | 325659502283                     |
| Result  | ✓ Passed                         |

CarCheck.co.uk page 4/11



report date: 2024-03-28

#### Tax & MOT check

Tax expired: 31 March 2021



X MOT

Expired: 2 August 2021

| Tax status       | Expired at 31 March 2021 |
|------------------|--------------------------|
| Days left        | 1125 days too late       |
| MOT expiry date  | 2 August 2021            |
| Full MOT history | See MOT history          |

#### Tax calculation

| Vehicle class                           | 49         |
|---|------------|
| Band                                    | Е          |
| Single payment (12 months)              | £ 180,00,- |
| Single six month payment                | £ 99,00,-  |
| Total payable by 12 monthly instalments | £ 189,00,- |

CarCheck.co.uk page 5/11



report date: 2024-03-28

#### Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

| Owner history   |             |
|---|-------------|
| For how long did the current and previous owner(s) have this AUDI? How many owners defined the premium report and see all owner registrations. Download the full report |             |
| ***************************************   |             |
|   |             |
| ***************************************   |             |
| ***************************************   |             |
|   |             |
| ***************************************   |             |
|   | More info > |
| Plate changes   |             |
| See in this check if this AUDI had different number plates.   |             |
| Number of plates  |             |
| Current registration  | NK NK       |
| Plate since   | mm.n.n      |
| Current registration  | UK UK       |
| Plate since   |             |
|   | More info > |
|   |             |

CarCheck.co.uk page 8/11



report date: 2024-03-28

#### Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Courte at Info    |  |

**Contact info** 

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

### Mileage check

Registration #14

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 14         |
| First mileage registration | 2008-08-06 |
| Last registration          | 2020-07-29 |
| Complete history           | See info   |



| Registration #1  | 2008-08-06 | 16 mi     |
|------------------|------------|-----------|
| Registration #2  | 2011-06-30 | 25.899 mi |
| Registration #3  | 2012-07-27 | 35.165 mi |
| Registration #4  | 2013-07-30 | 45.030 mi |
| Registration #5  | 2013-07-31 | 45.030 mi |
| Registration #6  | 2014-08-01 | 54.120 mi |
| Registration #7  | 2015-07-08 | 62.149 mi |
| Registration #8  |            | 11.777 es |
| Registration #9  |            | 11.177 mi |
| Registration #10 |            | 11.777 es |
| Registration #11 |            | 11.777 es |
| Registration #12 |            | 11.177 es |
|                  |            |           |
| Registration #13 |            | 11.777 es |

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 10/11



SE08NCY report date: 2024-03-28

### Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 |                  |
| 50482 |                  |
| 50501 |                  |
| 50566 |                  |
| 50567 |                  |
| 50569 |                  |

## Safety ratings

| NCAP rating | ****            |
|-------------|-----------------|
| Video       | see crash video |



### Dimensions & weight

| Width               | 1765 mm |
|---------------------|---------|
| Height              | 1424 mm |
| Length              | 4238 mm |
| Wheel base          | 2578 mm |
| Kerb weight         | 1425 kg |
| Max. allowed weight | 1925 kg |

# Additional information

| Fuel tank capacity                | 55 I             |
|-----------------------------------|------------------|
| Fuel delivery                     | Direct Injection |
| Number of doors                   | 2                |
| Number of seats<br>CarCheck.co.uk | 4 page 11/       |

Number of axles 2

Engine number BLS 693870