





report date: 2024-03-29

#### General information

Make	FORD
Model	FUSION ZETEC CLIMATE
Colour	Silver
Year of manufacture	2008
Top speed	98 mph
0 - 60 mph	16.3 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	67 BHP
Max. torque	159 Nm at 2.000 rpm
Engine capacity	1.399 сс
Cylinders	4
Fuel type	Diesel
Consumption city	50.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	120 g/km
CO2 label	С



CarCheck.co.uk page 1/13



# Internet history


#### Entry 1

Date 2021-06-13 2

**Pictures** 

Listing price View report





source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-03-30
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	13
Total items failed	4

MOT #16	2024-03-05 16:18
MOT test number	451244741181
Result	✓ Passed
Next expiry date	2025-03-30

MOT #15	2023-03-31 17:48
MOT test number	814114904095
Result	✓ Passed

MOT #14	2022-06-06 16:03
MOT test number	629872321422
Result	<b>X</b> Failed
Fail Electronic stability control warning lamp indicates a fault (7.12 (e))	
Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	

MOT #13	2021-07-09 12:59
MOT test number	992793697548
Result	✓ Passed
Advice Electronic stability control warning lamp not working (7.12 (e))	

CarCheck.co.uk page 3/13



**MOT #12** 2020-06-18 14:08

**MOT test number** 601587371828

**Result** ✓ Passed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #11** 2020-06-18 14:08

MOT test number 647910280562

**Result** X Failed

Pass with rectification Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #10** 2019-06-12 11:03

MOT test number 789148884780

Result 

Passed

MOT #9 2018-06-14 10:48

MOT test number 733095352047

Advice Rear Tyre has a cut but not deep enough to reach the ply or cords both sides (5.2.3 (d) (i))

CarCheck.co.uk page 4/13



MOT #8 2018-06-14 10:48

**MOT test number** 997455624917

**Result** X Failed

Advice Rear Tyre has a cut but not deep enough to reach the ply or cords both sides (5.2.3 (d) (i))

Pass with rectification Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #7 2017-06-02 10:03

**MOT test number** 223371104221

**Result** 
✓ Passed

MOT #6 2016-06-15 11:32

**MOT test number** 941878804351

Result \rightarrow Passed

MOT #5 2015-06-16 14:00

**MOT test number** 269897365128

**Result** ✓ Passed

MOT #4 2014-06-18 15:06

**MOT test number** 197359764120

**Result** 
✓ Passed

MOT #3 2013-06-13 11:25

**MOT test number** 405754463178

Result 

Passed

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/13



MOT #2	2012-06-15 11:06
MOT test number	646967962195
Result	<b>✓</b> Passed
MOT #1	2011-06-17 15:50
MOT test number	617938261157

CarCheck.co.uk page 6/13



# Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	30 March 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-


CarCheck.co.uk page 7/13



#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



# Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report <u>k</u>	
*********	
************	
**********	
***************************************	
	More info >
Plate changes	
Coo in this shook if this FORD had different number plates	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	NK SIES
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >

CarCheck.co.uk page 11/13



# Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-06-04
Last registration	2024-03-05
Complete history	See info



Registration #1	2008-06-04	16 mi
Registration #2	2011-06-17	29.931 mi
Registration #3	2012-06-15	30.741 mi
Registration #4	2013-06-13	31.645 mi
Registration #5	2014-06-18	32.588 mi
Registration #6	2015-06-16	33.436 mi
Registration #7	2016-06-15	34.134 mi
Registration #8	2017-06-02	34.732 mi
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		9.39 es
Registration #14		11.777 es
Registration #15		11.777 mi
Registration #16		10.777 au

More info >

CarCheck.co.uk page 12/13



# Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Max. allowed weight	1640 kg

# Additional information

Fuel tank capacity	43 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 13/13