





report date: 2024-03-29

General information

Make	JAGUAR
Model	X-TYPE V6 SPORT
Colour	Silver
Year of manufacture	2007
Top speed	137 mph
0 - 60 mph	8.9 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	194 BHP
Max. torque	244 Nm at 3.000 rpm
Engine capacity	2.496 cc
Cylinders	6
Fuel type	Petrol
Consumption city	19.0 mpg
Consumption extra urban	37.2 mpg
Consumption combined	27.4 mpg
CO2 emission	244 g/km
CO2 label	L



CarCheck.co.uk page 1/17



report date: 2024-03-29

Internet history

Entry 1

Date 2021-09-22

Pictures 19

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/17



MOT history

MOT expiry date	2024-06-04
MOT pass rate	64 %
MOT passed	14
Failed MOT tests	8
Total advice items	59
Total items failed	20

MOT #22	2023-06-05 13:28
MOT test number	549909161451
Result	✓ Passed
Next expiry date	2024-06-04

CarCheck.co.uk page 3/17



report date: 2024-03-29

MOT #21 2023-05-26 08:06

MOT test number 625970652204

Result X Failed

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Fail Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

Fail Offside Headlamp aim too low (4.1.2 (a))

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Fail Offside Front Brake hose excessively damaged (1.1.12 (b) (ii))

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail
Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Nearside Front Direction indicator incorrect colour (4.4.3 (a))

Minor Windscreen wiper blade defective (3.4 (b) (i))

Fail Nearside Headlamp aim too low (4.1.2 (a))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Fail Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #20 2022-09-27 08:09

MOT test number 964503498291

Result

Passed

Advice Vehicles internal headlight adjuster altered to recheck lights

CarCheck.co.uk page 4/17



report date: 2024-03-29

MOT #19 2021-04-22 15:38

MOT test number 458697783337

Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #18 2021-04-21 10:35

MOT test number 175616607191

Result × Failed

Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Fail Nearside Rear Outer Tyre has a bulge, caused by separation or partial failure of its structure 225/45/17 (5.2.3 (d) (ii))

Fail Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 225/45/17 (5.2.3 (d) (i))

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

CarCheck.co.uk page 5/17



report date: 2024-03-29

MOT #17 2020-05-12 11:34

MOT test number 650374333932

MOT #16 2020-05-11 09:52

MOT test number 175797856175

Result × Failed

Fail Nearside Rear Service brake excessively fluctuating (1.2.1 (e))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #15 2019-03-26 10:41

MOT test number 457459488048

Result \rightarrow Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #14 2018-02-27 10:51

MOT test number 240028626383

Result

Passed

MOT #13 2017-05-15 14:16

MOT test number 257764244072

Result ✓ Passed

Advice Nearside Rear Nail in tyre

Advice Nearside Rear Shock absorber has a light misting of oil (2.7.3)


Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Misting of oil on engine/gearbox area.

CarCheck.co.uk page 6/17



report date: 2024-03-29



MOT #11		2016-05-26 11:04
MOT test	number	272201976569
Result		✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit 225/45/17 (4.1.E.1)	
Advice	Offside Rear nail in tyre	
Advice	Nearside Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Temperature warning light on dash	

MOT #10	2015-05-27 11:48
MOT test number	489877145193
Result	✓ Passed
Notice Engine warning light on.	
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 7/17



report date: 2024-03-29

MOT #9 2015-05-26 10:15

MOT test number 865476745165

Result X Failed

Notice Coolant leak

Fail Nearside Front Brake hose twisted (found during steering lock to lock check) (2.2.D.2b)

Notice Engine warning light on.

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #8 2014-03-14 13:43

MOT test number 506963474037

Result \(\sqrt{Passed} \)

Notice Engine covers fitted obscuring some components in the engine bay

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Notice Under-trays fitted obscuring some underside components

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 8/17



report date: 2024-03-29

179912473450

MOT #7 2014-03-14 10:27

MOT test number 485253774016

Result × Failed

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Notice Engine covers fitted obscuring some components in the engine bay

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Notice Under-trays fitted obscuring some underside components

Fail Nearside Outer Front Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #6 2013-03-13 11:18

MOT test number 925052673094

Result × Failed

Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #5 2013-03-13 11:18

Result \(\sigma\) Passed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT test number

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 9/17



report date: 2024-03-29

MOT #4 2012-03-12 16:13

MOT test number 199572972007

Result
✓ Passed

MOT #3 2011-03-19 10:18

MOT test number 177958371091

Result
✓ Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

MOT #2 2010-03-10 13:12

MOT test number 651089160035

Advice Rear Brake pad(s) wearing thin (3.5.1g)

MOT #1 2010-03-09 09:35

MOT test number 561008560092

Result X Failed

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Advice Nearside Front constant velocity joint gaiter deteriorated (2.5.C.1a)

CarCheck.co.uk page 10/17



Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	4 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-

CarCheck.co.uk page 11/17



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 12/17



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 13/17



Owner history

o mile motory	
For how long did the current and previous owner(s) have this JAGUAR? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.	

	More info >
Plate changes	
See in this check if this JAGUAR had different number plates.	
Number of plates	
Current registration	IIK SIE
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 14/17



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 15/17



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2007-03-15
Last registration	2023-06-05
Complete history	See info



Registration #1	2007-03-15	22 mi
Registration #2	2010-03-09	14.761 mi
Registration #3	2010-03-10	14.761 mi
Registration #4	2011-03-19	22.127 mi
Registration #5	2012-03-12	28.056 mi
Registration #6	2013-03-13	33.332 mi
Registration #7	2014-03-14	39.132 mi
Registration #8	2014-03-14	39.132 mi
Registration #9	2015-05-26	44.866 mi
Registration #10	2015-05-27	44.866 mi
Registration #11	2016-05-26	49.605 mi
Registration #12	2017-05-15	52.993 mi
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.777 es
Registration #23		73.777 au

More info >

CarCheck.co.uk page 16/17



Safety ratings

NCAP rating	HARRY
-------------	--------------

Video <u>see crash video</u>



Dimensions & weight

Width	2003 mm
Height	1392 mm
Length	4672 mm
Wheel base	2710 mm
Kerb weight	1595 kg
Max. allowed weight	2080 kg

Additional information

Fuel tank capacity	61 I
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	548873414XB

CarCheck.co.uk page 17/17