





#### General information

Make	FIAT
Model	DOBLO 16V SX MULTIJET
Colour	Blue
Year of manufacture	2015
Top speed	98 mph
0 - 60 mph	5.2 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Demor	
Power	90 BHP
Max. torque	200 Nm at 1.750 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.1 mpg
Consumption extra urban	65.7 mpg
Consumption combined	57.6 mpg
CO2 emission	126 g/km
CO2 label	D







# Internet history


Entry 1

Date Pictures 2022-06-29

18

Listing price

View report









source: cargurus.co.uk




# MOT history

MOT expiry date	2024-10-30
MOT pass rate	50 %
MOT passed	6
Failed MOT tests	6
Total advice items	19
Total items failed	18

MOT #12	2023-10-31 15:36
MOT test number	281504182144
Result	🗸 Passed
Next expiry date	2024-10-30
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Trays and covers fitted	
Minor Central Front Windscreen damaged but not adversely affecting driver's view (3.2	(a) (i))





MOT #10	2022-06-22 07:57
MOT test number	923807433614
Result	✓ Passed

MOT #9		2022-06-22 07:57
MOT test number		431211862899
Result		🗙 Failed
Pass with rectification	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))	

1151

report date: 2024-03-29





MOT #8	2021-08-26 12:03
MOT test number	564619476479
Result	✓ Passed
MOT #7	2021-08-26 10:38
MOT test number	528869143752
Result	🗙 Failed
<b>Fail</b> Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))	
MOT #6	2020-08-28 09:28
<b>MOT test number</b> 95480524317	
Result	✓ Passed
MOT #5	2020-08-26 08:53
MOT test number Result	742740616708
Kesuit	🗙 Failed
Advice Rear Tyre slightly damaged/cracking or perishing Both sides (5.2.3 (d) (ii))	
Fail Offside Front Macpherson strut top bush or bearing has excessive wear or free p	lay (5.3.4 (a) (i))
<b>Fail</b> Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Fail Exhaust shield missing where fitted as original equipment creating a risk of fire (6.1.3 (e))	
Advice Rear Suspension arm pin or bush worn but not resulting in excessive movement Both sides (5.3.4 (a) (i))	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

MOT #4	2019-06-21 12:11
MOT test number	241480844270
Result	✓ Passed
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	





MOT #3	2019-06-20 14:09
MOT test number	143917042333
Result	🗙 Failed
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (	ii))
Fail Exhaust emissions exceed default limit of 0.7m-1 (8.2.2.2 (b))	
Fail Front Windscreen washer provides insufficient washer liquid (3.5 (a))	
Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

MOT #2	2018-06-01 13:32
MOT test number	126571232872
Result	✓ Passed
Advice Spare tyre defective	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #1		2018-06-01 13:32
MOT test number		619704708448
Result		🗙 Failed
Pass with rectification	Windscreen washer provides insufficient washer liquid (3.5 (a))	
Advice Spare tyre defee	ctive	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		



Tax & MOT check

X Untaxed Tax expired: 10 April 2024	✓ MOT Expires: 30 October 2024
Tax status	Expired at 10 April 2024
Days left	19 days too late
MOT expiry date	30 October 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-





#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Dumage 2	E E E E
Date	J.
Category	amer
Туре	

#### Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info  $\rightarrow$ 





## Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

*******	
**********	
*******	
******	
*********	
*******	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info  $\rightarrow$ 





# Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2015-06-05
Last registration	2023-10-31
Complete history	<u>See info</u>



Registration #1	2015-06-05	28 mi
Registration #2	2018-06-01	67.071 mi
Registration #3	2018-06-01	67.071 mi
Registration #4	2019-06-20	84.879 mi
Registration #5	2019-06-21	84.880 mi
Registration #6	2020-08-26	90.184 mi
Registration #7	2020-08-28	90.186 mi
Registration #8		11.777 esi
Registration #9		
Registration #5		
Registration #10		11.000 es
-		0.000 es
Registration #10		0.000 es
Registration #10 Registration #11		0.000 es

More info >





## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

**NCAP** rating

Video

see crash video



Dimensions & weight	
Width	1832 mm
Height	1845 mm
Length	4390 mm
Kerb weight	1345 kg
Max. allowed weight	2355 kg
Additional information	
Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number CarCheck.co.uk	5656639 page 13/13