



General information

Make	FIAT
Model	500C SPORT
Colour	White
Year of manufacture	2010
Top speed	99 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 6.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.1 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg
CO2 emission	113 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-01-29
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)

**MOT history**

<b>MOT expiry date</b>	2025-03-17
<b>MOT pass rate</b>	69 %
<b>MOT passed</b>	11
<b>Failed MOT tests</b>	5
<b>Total advice items</b>	45
<b>Total items failed</b>	10

**MOT #16** 2024-03-18 14:28**MOT test number** 413085074921**Result** Passed**Next expiry date** 2025-03-17**Advice** Exhaust flexi poor condition**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Both front fog lights not working**MOT #15** 2023-03-16 11:27**MOT test number** 762584076773**Result** Passed**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #14**

2022-03-15 14:17

**MOT test number**

471394281461

**Result**

✓ Passed

**Minor** Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front Front fog lights not working**MOT #13**

2022-03-14 14:55

**MOT test number**

767782521623

**Result**

✗ Failed

**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Nearside Front Front passenger door cannot be opened from outside the vehicle (6.2.3 (a))**Advice** Front Front fog lights not working**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #12**

2021-03-04 10:02

**MOT test number**

516355096316

**Result**

✓ Passed

**MOT #11**

2019-09-03 09:01

**MOT test number**

919716231137

**Result**

✓ Passed

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**Advice** Rear silencer showing signs of corrosion

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Shock absorbers light misting of oil or has limited damping effect both front (5.3.2 (b))

**Advice** Oil leak, but not excessive gearbox (8.4.1 (a) (i))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

**MOT #10**

2019-09-03 09:01

**MOT test number**

904130222601

**Result**

✗ Failed

**Pass with rectification** Central Stop lamp(s) not working (4.3.1 (a) (ii))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Shock absorbers light misting of oil or has limited damping effect both front (5.3.2 (b))

**Advice** Oil leak, but not excessive gearbox (8.4.1 (a) (i))

**Advice** Rear silencer showing signs of corrosion

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**MOT #9**

2018-06-14 14:47

**MOT test number**

949745175324

**Result**

✓ Passed

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**Advice** Oil leak, but not excessive gearbox (8.4.1 (a) (i))

**MOT #8** 2018-06-14 14:47**MOT test number** 446664454412**Result** ✗ Failed

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**Pass with rectification** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**Advice** Oil leak, but not excessive gearbox (8.4.1 (a) (i))

**Pass with rectification** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

**MOT #7** 2017-06-19 07:57**MOT test number** 256690313076**Result** ✓ Passed

**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

**MOT #6** 2017-06-12 15:39**MOT test number** 355483023494**Result** ✗ Failed

**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

**Fail** Nearside Front Headlamp not working on dipped beam (1.7.5a)

**Fail** Offside Front Inner Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

**Fail** Nearside Front Inner Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #5** 2016-05-31 10:54**MOT test number** 622108510706**Result** ✓ Passed**Advice** Centre stop light not working**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**MOT #4** 2015-06-11 15:58**MOT test number** 678782765189**Result** ✓ Passed**Notice** Advise high level brake light inop**MOT #3** 2015-05-28 16:52**MOT test number** 209288545166**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Notice** Centre stop lamp not working**MOT #2** 2014-05-23 11:55**MOT test number** 497173444191**Result** ✓ Passed**Notice** High level stop light inop**MOT #1** 2013-05-23 10:08**MOT test number** 389703143134**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
17 March 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	306
<b>MOT expiry date</b>	17 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-





Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-05-28
Last registration	2024-03-18
Complete history	<a href="#">See info</a>



Registration #1	2010-05-28	28 mi
Registration #2	2013-05-23	12.739 mi
Registration #3	2014-05-23	21.888 mi
Registration #4	2015-05-28	34.647 mi
Registration #5	2015-06-11	35.263 mi
Registration #6	2016-05-31	48.024 mi
Registration #7	2017-06-12	59.690 mi
Registration #8	2017-06-19	59.953 mi
Registration #9	2018-06-14	67.635 mi
Registration #10	2019-06-14	75.317 mi
Registration #11	2020-06-14	83.000 mi
Registration #12	2021-06-14	90.683 mi
Registration #13	2022-06-14	98.365 mi
Registration #14	2023-06-14	106.048 mi
Registration #15	2024-03-18	113.731 mi
Registration #16	2024-03-18	121.414 mi
Registration #17	2024-03-18	129.097 mi
Registration #18	2024-03-18	136.780 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	865 kg
Max. allowed weight	1305 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	6058766