





report date: 2024-03-28

## General information

Make	PEUGEOT
Model	207 S
Colour	Red
Year of manufacture	2010
Top speed	106 mph
0 - 60 mph	15.7 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	74 BHP
Max. torque	118 Nm at 3.300 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.8 mpg
CO2 emission	145 g/km
CO2 label	F



CarCheck.co.uk page 1/13



# Internet history

## Entry 1

Date 2021-05-24

Pictures 6

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-01-21
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	13
Total items failed	5

MOT #16	2024-01-02 09:42
MOT test number	368639536807
Result	✓ Passed
Next expiry date	2025-01-21
Advice Nearside Rear tyre's outer sidewall cracked/ perished	

MOT #15	2023-01-05 16:59
MOT test number	889399363646
Result	✓ Passed
Advice Exhaust rear hanger corroded off but still secure	

MOT #14	2023-01-05 08:39
MOT test number	464566410101
Result	<b>X</b> Failed
Advice Exhaust rear hanger corroded off but still secure  Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #13	2022-01-13 08:42
MOT test number	114902741089
Result	<b>✓</b> Passed
Advice O/s/r tyre's low on tread 2mm	

CarCheck.co.uk page 3/13



**Advice** 

EY60YDL report date: 2024-03-28

MOT #12

MOT test number

Result

Advice

Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11

MOT test number

S48396804184

Result

Advice Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

 MOT #10
 2019-03-14 09:41

 MOT test number
 397042304613

 Result
 ✓ Passed

MOT #9

MOT test number

Result

Rear Exhaust silencer insecure (8.1.1 (b) (i))

MOT #8

MOT test number

Result

Advice Oil leak

Advice Exhaust bracket corroded

CarCheck.co.uk page 4/13



EY60YDL

report date: 2024-03-28

MOT #7 2017-03-28 08:37

**MOT test number** 508616985770

**Result** ✓ Passed

**MOT #6** 2017-03-27 11:46

**MOT test number** 549374305439

Result X Failed

Fail Nearside Windscreen washer provides insufficient washer liquid (8.2.3)

**Fail** Offside Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #5 2016-07-20 15:22

**MOT test number** 641714122136

Result \rightarrow Passed

**MOT #4** 2015-07-21 09:44

**MOT test number** 119072805252

**Result** 
✓ Passed

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #3 2014-07-22 08:48

**MOT test number** 489353704252

**Result** ✓ Passed

**MOT #2** 2014-07-22 08:48

**MOT test number** 699413204246

Result × Failed

**Pass with rectification** Headlamp aim too low (1.8)

CarCheck.co.uk page 5/13



MOT #1 2013-08-05 10:51

**MOT test number** 848427313266

**Result** ✓ Passed

CarCheck.co.uk page 6/13





# Tax & MOT check



Tax status	Valid until 1 December
Days left	216
MOT expiry date	21 January 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 7/13



## Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



## Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

· ·		
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		GEOT
***************************************		
***************************************		
***************************************		
***************************************		
	More info	>
Plate changes		
See in this check if this PEUGEOT had different number plates.		
Number of plates		,
Current registration	UK NEW YEAR	
Plate since		
Current registration	OK SIES	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



## Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

**Contact info** 

More info >

CarCheck.co.uk page 11/13



N/III	leag	0	h c c	1/
1411	IE a U	IE (.	HEC.	ĸ

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-09-01
Last registration	2024-01-02
Complete history	See info



Registration #1	2010-09-01	7 mi
Registration #2	2013-08-05	24.201 mi
Registration #3	2014-07-22	28.134 mi
Registration #4	2015-07-21	31.895 mi
Registration #5	2016-07-20	33.763 mi
Registration #6	2017-03-27	35.006 mi
Registration #7	2017-03-28	35.010 mi
Registration #8	2018-03-19	44.498 mi
Registration #9	2019-03-14	54.492 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		D.777 es
Registration #17		

More info >

CarCheck.co.uk page 12/13



# Car features

S0225	Air conditioning
50295	
50482	
50501	
60566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1972 mm
Height	1502 mm
Length	4030 mm
Wheel base	2540 mm
Kerb weight	1215 kg
Max. allowed weight	1617 kg

# Additional information

Fuel tank capacity	50
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/

Number of axles 2

Engine number FSW86309213