



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN TDI SE DSG 7 STR
Colour	Silver
Year of manufacture	2005
Top speed	123 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	33.6 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.8 mpg
CO2 emission	178 g/km
CO2 label	I






Internet history

Entry 1

Date	2021-09-30
Pictures	15
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-18
MOT pass rate	73 %
MOT passed	16
Failed MOT tests	6
Total advice items	47
Total items failed	5

MOT #22	2024-03-19 11:13
MOT test number	134128094815
Result	✓ Passed
Next expiry date	2025-03-18
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Rear Sub frame and suspension components slightly corroded
Advice	Covers and under trays fitted obscuring some testable components

MOT #21	2024-03-15 16:10
MOT test number	669199184344
Result	✗ Failed
Advice	Rear Sub frame and suspension components slightly corroded
MAJOR	Nearside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
Advice	Covers and under trays fitted obscuring some testable components
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #20**

2023-03-17 15:05

MOT test number

714077613158

Result

✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge worn inner edge (5.2.3 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing inner wall cracking (5.2.3 (d) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn inner edge (5.2.3 (e))**MOT #19**

2022-03-14 12:30

MOT test number

355332226728

Result

✓ Passed

Advice Front Tyre worn close to legal limit/worn on edge both side front (5.2.3 (e))**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement both side front (5.3.4 (a) (i))**Advice** Rear Suspension spring mounting prescribed area is corroded but not considered excessive both side rear (5.3.6 (a) (i))**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Rear Vehicle structure is corroded but structural rigidity is not significantly reduced both side rear (6.1.1 (c) (i))**Advice** Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**MOT #18**

2021-03-18 13:39

MOT test number

859131222537

Result

✓ Passed

Advice Rear Brake disc worn, but not excessively both side (1.1.14 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both side (1.1.14 (a) (ii))**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement both side lower suspension arm rear bush (5.3.4 (a) (i))

**MOT #17** 2021-03-17 11:39**MOT test number** 171547078530**Result** ✗ Failed**MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement both side lower suspension arm rear bush (5.3.4 (a) (i))**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Rear Brake disc worn, but not excessively both side (1.1.14 (a) (i))**MOT #16** 2020-07-02 11:28**MOT test number** 229027923804**Result** ✓ Passed**MOT #15** 2018-12-21 15:58**MOT test number** 988052127336**Result** ✓ Passed**MOT #14** 2017-10-26 15:18**MOT test number** 398977898963**Result** ✓ Passed**MOT #13** 2016-05-03 10:28**MOT test number** 465422021529**Result** ✓ Passed**Advice** Chip in o/s windscreen out side of zone a

**MOT #12** 2016-05-03 10:28**MOT test number** 730105117205**Result** ✗ Failed**Advice** Chip in o/s windscreen out side of zone a**Pass with rectification** Offside Stop lamp not working + o/s/r light (1.2.1b)**MOT #11** 2015-04-16 11:32**MOT test number** 707826705147**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #10** 2014-04-16 16:44**MOT test number** 439926804166**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Disabled turning control fitted to steering wheel**Advice** Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #9** 2013-04-17 09:40**MOT test number** 425347503191**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Slight weep from drive shaft retaining clips front nearside and offside**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Notice** 3rd row rear seats not presented at time of test

**MOT #8** 2013-04-17 09:40**MOT test number** 449677503117**Result** ✗ Failed**Pass with rectification** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Notice** Slight weep from drive shaft retaining clips front nearside and offside**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Notice** 3rd row rear seats not presented at time of test**Pass with rectification** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #7** 2012-05-01 14:46**MOT test number** 265472822413**Result** ✓ Passed**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #6** 2011-04-13 09:30**MOT test number** 208313301483**Result** ✓ Passed**MOT #5** 2011-04-13 09:30**MOT test number** 705253201182**Result** ✗ Failed**Pass with rectification** Nearside Front constant velocity joint gaiter insecurely mounted to its housing (2.5.C.1a)



MOT #4 2010-04-27 17:06

MOT test number 891067010196

Result ✓ Passed

Advice Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

MOT #3 2010-04-26 12:25

MOT test number 290266110151

Result ✗ Failed

Advice Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

Advice Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Nearside Front constant velocity joint gaiter split (2.5.C.1a)

MOT #2 2009-05-01 15:00

MOT test number 273221829181

Result ✓ Passed

MOT #1 2008-04-15 13:00

MOT test number 344996708123

Result ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
18 March 2025

Tax status	Valid until 1 October
Days left	156
MOT expiry date	18 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXX
Plate since	2024-03-28
Current registration	 XXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2005-05-01
Last registration	2024-03-19
Complete history	See info



Registration #1	2005-05-01	9 mi
Registration #2	2008-04-15	37.066 mi
Registration #3	2009-05-01	47.747 mi
Registration #4	2010-04-26	52.727 mi
Registration #5	2010-04-27	52.727 mi
Registration #6	2011-04-13	55.225 mi
Registration #7	2012-05-01	58.775 mi
Registration #8	2013-04-17	60.970 mi
Registration #9	2014-04-16	64.052 mi
Registration #10	2015-04-16	67.482 mi
Registration #11	2016-05-03	71.050 mi
Registration #12	2017-05-03	75.277 mi
Registration #13	2018-05-03	79.277 mi
Registration #14	2019-05-03	83.277 mi
Registration #15	2020-05-03	87.277 mi
Registration #16	2021-05-03	91.277 mi
Registration #17	2022-05-03	95.277 mi
Registration #18	2023-05-03	99.277 mi
Registration #19	2024-03-19	103.277 mi
Registration #20		
Registration #21		
Registration #22		

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1794 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Max. allowed weight	2290 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles

2

Engine number

BKD 271331