





report date: 2024-03-28

#### General information

Make	JAGUAR
Model	XK8 CONVERTIBLE
Colour	Green
Year of manufacture	1997
Top speed	155 mph
0 - 60 mph	6.4 seconds
Gearbox	5 speed automatic

#### Engine & fuel consumption

Power	290 BHP
Max. torque	393 Nm at 4.250 rpm
Engine capacity	3.980 сс
Cylinders	8
Fuel type	Petrol
Consumption city	15.9 mpg
Consumption extra urban	33.4 mpg
Consumption combined	23.9 mpg



CarCheck.co.uk page 1/13



report date: 2024-03-28

#### Internet history

#### Entry 1

Date 2021-11-12

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

### MOT history

MOT expiry date	2024-12-06
MOT pass rate	79 %
MOT passed	19
Failed MOT tests	5
Total advice items	28
Total items failed	12

MOT #24		2023-12-07 17:23
MOT test	number	865936381269
Result		✓ Passed
Next expi	ry date	2024-12-06
Advice	Nearside Play in steering rack inner joint(s)	
Advice	Nearside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))	
Advice	Offside Play in steering rack inner joint(s)	
Advice	Offside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))	

MOT #23	2023-11-27 15:39
MOT test number	678196643251
Result	<b>★</b> Failed
Fail Nearside Front Vehicle structure strengthening plate or fastening so insecure that seriously reduced (6.1.1 (b) (ii))	structural rigidity is
Advice Offside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))	
Advice Offside Play in steering rack inner joint(s)	
<b>Fail</b> Offside Front Vehicle structure strengthening plate or fastening so insecure that strengthening reduced (6.1.1 (b) (ii))	tructural rigidity is
Advice Nearside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))	
Fail Offside Front Upper Suspension arm pin or bush excessively worn upper/rear (5.3.	.4 (a) (i))
Advice Nearside Play in steering rack inner joint(s)	

CarCheck.co.uk page 3/13



report date: 2024-03-28

**MOT #22** 2023-11-09 16:39

MOT test number 175120140928

Result X Failed

Advice Rear Suspension component corroded but not seriously weakened both sides (5.3.3 (b) (i))

**Advice** Rear Shock absorbers has a slightly worn bush both sides (5.3.2 (c))

**Advice** Offside Front Play in steering rack inner joint(s)

Fail Offside Front Wheel bearing has excessive play (5.1.3 (a) (i))

**Advice** Rear Coil spring corroded both sides (5.3.1 (b) (i))

**MOT #21** 2022-11-07 15:35

MOT test number 487310132995

Result \rightarrow Passed

**Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

Advice Nearside Rear Shock absorbers has a slightly worn bush bottom bush (5.3.2 (c))

MOT #20 2022-11-01 12:57

MOT test number 108024684287

Result × Failed

Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

Fail Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Nearside Rear Shock absorbers has a slightly worn bush bottom bush (5.3.2 (c))

**MOT #19** 2021-11-11 17:28

**MOT test number** 460149765738

Result \( \sqrt{Passed} \)

Advice Front Foot Well Repaired/Painted, Beyond Prescibed Area Both Sides

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT test number
975669107954

Result

Advice
(i))

Advice
Rear Coil spring corroded Both (5.3.1 (b) (i))

Advice
(i))

Offside Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c)
(i))

MOT #17	2020-11-19 14:54
MOT test i	number 247339577713
Result	✓ Passed
Advice	Nearside Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c)
Advice	Offside Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c)

Advice Offside Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c)		
(i))		
MOT #16	2019-10-15 13:14	
MOT test number	725888059857	
Result	✓ Passed	
MOT #15	2018-10-30 14:16	
MOT test number	132765148470	
Result	✓ Passed	
MOT #14	2017-12-04 09:59	
MOT test number	436939987581	
Result	<b>√</b> Passed	

MOT #13	2016-10-10 10:52
MOT test number	590564791990
Result	<b>✓</b> Passed

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #12		2015-10-06 13:59
MOT test	number	398238089460
Result		✓ Passed
Advice	Offside Rear Body has slight corrosion (6.1.B.2)	
Advice	Nearside Rear Vehicle structure has slight corrosion (6.1.B.2)	
Advice	Nearside Rear Body has slight corrosion (6.1.B.2)	
Advice	Offside Rear Vehicle structure has slight corrosion (6.1.B.2)	

MOT #11	2014-11-03 11:08
MOT test number	636557804363
Result	✓ Passed
MOT #10	2013-11-05 09:58
MOT test number	289699203387
Result	✓ Passed
MOT #9	2013-11-04 16:09
MOT test number	945968303391
Result	<b>X</b> Failed
Fail Offside Registration plate lamp not working (1.1.C.1d)	
Fail Offside Front Brake pipe excessively corroded (3.6.B.2c)	
Fail Nearside Registration plate lamp not working (1.1.C.1d)	
Fail Nearside Front Brake pipe excessively corroded (3.6.B.2c)	

MOT #8	2012-10-23 09:46
MOT test number	439117992212
Result	✓ Passed
Advice Brake pipe slightly corroded (3.6.B.2c)	

CarCheck.co.uk page 6/13



MOT #4

**R490BNH** 

report date: 2024-03-28

2008-10-20 16:17

MOT #7	2011-10-20 10:58
MOT test number	927803591257
Result	✓ Passed
MOT #6	2010-09-24 15:34
MOT test number	360787160428
Result	✓ Passed
MOT #5	2009-09-25 11:09
MOT test number	240568669200
Result	✓ Passed
Advice Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT test number		340174798494
Result		✓ Passed
MOT #3		2008-10-20 16:17
MOT test number		483194398245
Result		<b>×</b> Failed
Pass with rectification	Offside Rear Direction indicator incorrect colour (1.4.A.2f)	
Pass with rectification	Nearside Front position lamp(s) not working (1.1.A.3b)	

MOT #2	2007-11-06 12:03
MOT test number	522770817397
Result	<b>√</b> Passed
MOT #1	2006-11-06 11:10
MOT test number	710250516322
Result	<b>✓</b> Passed

CarCheck.co.uk page 7/13



report date: 2024-03-28

See MOT history

#### Tax & MOT check

**Full MOT history** 



CarCheck.co.uk page 8/13



report date: 2024-03-28

#### Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner	history
OWITCH	THISCOL 9

e mier metery	
For how long did the current and previous owner(s) have this JAGUAR? How many owner have? Check it in the premium report and see all owner registrations. Download the full	
MANAGEMENT CONTRACTOR	
***************************************	
***************************************	
***************************************	
**************************************	
	More info >
Plate changes	
See in this check if this JAGUAR had different number plates.	
Number of plates	,
Current registration	NK SIX
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

#### Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

### Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	1997-08-01
Last registration	2023-12-07
Complete history	See info



Registration #1	1997-08-01	29 mi
Registration #2	2006-11-06	47.016 mi
Registration #3	2007-11-06	48.476 mi
Registration #4	2008-10-20	49.827 mi
Registration #5	2009-09-25	50.809 mi
Registration #6	2010-09-24	51.718 mi
Registration #7	2011-10-20	52.712 mi
Registration #8	2012-10-23	53.127 mi
Registration #9	2013-11-04	53.770 mi
Registration #10	2013-11-05	53.770 mi
Registration #11	2014-11-03	54.498 mi
Registration #12	2015-10-06	55.415 mi
Registration #13	2016-10-10	55.801 mi
Registration #14		11.777 au
Registration #14 Registration #15		11.77 44
		11.77 m
Registration #15		11.77 es 11.77 es 11.77 es
Registration #15 Registration #16		1.77 m
Registration #15 Registration #16 Registration #17		11.77 m
Registration #15 Registration #16 Registration #17 Registration #18		11.77 es 11.77 es 11.77 es 11.77 es 11.77 es
Registration #15 Registration #16 Registration #17 Registration #18 Registration #19		11.77 es 11.77 es 11.77 es 11.77 es 11.77 es 11.77 es
Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20		11.77 es 11.77 es 11.77 es 11.77 es 11.77 es 11.77 es
Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21		11.77 es 11.77 es 11.77 es 11.77 es 11.77 es 11.77 es 11.77 es
Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22		11.777 es 11.777 es 11.777 es 11.777 es 11.777 es 11.777 es 11.777 es 11.777 es
Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22 Registration #22		11.777 es 11.777 es 11.777 es 11.777 es 11.777 es 11.777 es 11.777 es 11.777 es



report date: 2024-03-28

Additional information

Fuel tank capacity	75 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	CE9701071248

CarCheck.co.uk page 13/13