



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	FOX URBAN FOX
Colour	Red
Year of manufacture	2007
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	146 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-10-08
Pictures	5
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-27
MOT pass rate	88 %
MOT passed	15
Failed MOT tests	2
Total advice items	20
Total items failed	0

MOT #17	2024-02-23 15:08
MOT test number	710156424727
Result	✓ Passed
Next expiry date	2025-02-27

MOT #16	2023-02-21 13:00
MOT test number	925326375435
Result	✓ Passed

MOT #15	2022-02-17 15:12
MOT test number	180845982214
Result	✓ Passed

MOT #14	2021-02-15 10:43
MOT test number	343555418855
Result	✓ Passed

- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Central Front Exhaust has a minor leak of exhaust gases flexi pipe (6.1.2 (a))

**MOT #13** 2020-02-19 17:06**MOT test number** 123523944634**Result** ✓ Passed**MOT #12** 2020-02-19 10:10**MOT test number** 314237795427**Result** ✗ Failed**MAJOR** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MAJOR** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MAJOR** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MAJOR** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MOT #11** 2019-02-11 16:00**MOT test number** 972242420921**Result** ✓ Passed**Advice** Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #10** 2019-02-09 10:00**MOT test number** 688897741699**Result** ✗ Failed**MAJOR** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**MOT #9** 2018-02-12 10:32**MOT test number** 691251873703**Result** ✓ Passed

Advice Offside Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

MOT #8 2017-02-28 12:48**MOT test number** 528539199083**Result** ✓ Passed**MOT #7** 2016-02-03 09:39**MOT test number** 847301964378**Result** ✓ Passed**MOT #6** 2015-02-13 10:12**MOT test number** 539624445039**Result** ✓ Passed**MOT #5** 2014-01-21 17:53**MOT test number** 735911624031**Result** ✓ Passed**MOT #4** 2013-02-11 15:55**MOT test number** 967082343026**Result** ✓ Passed

Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

Notice All 4 tyre sidewalls perishing



MOT #3	2012-02-06 14:38
MOT test number	108667032430
Result	✓ Passed
Advice	Parking brake lever has little reserve travel (3.1.6b)
Notice	Vehicle's internal headlight adjuster altered to recheck lights

MOT #2	2011-02-14 12:36
MOT test number	189035541468
Result	✓ Passed

MOT #1	2010-03-01 16:17
MOT test number	140390960419
Result	✓ Passed
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
27 February 2025

Tax status	Valid until 1 October
Days left	156
MOT expiry date	27 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 VK07ZXJ
Plate since	2019-09-29
Current registration	 VK07ZXJ
Plate since	2019-09-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-03-22
Last registration	2024-02-23
Complete history	See info



Registration #1	2007-03-22	26 mi
Registration #2	2010-03-01	7.670 mi
Registration #3	2011-02-14	10.047 mi
Registration #4	2012-02-06	13.507 mi
Registration #5	2013-02-11	15.983 mi
Registration #6	2014-01-21	19.306 mi
Registration #7	2015-02-13	24.031 mi
Registration #8	2016-02-03	27.918 mi
Registration #9	2017-02-28	35.822 mi
Registration #10	2018-03-01	35.822 mi
Registration #11	2019-03-01	35.822 mi
Registration #12	2020-03-01	35.822 mi
Registration #13	2021-03-01	35.822 mi
Registration #14	2022-03-01	35.822 mi
Registration #15	2023-03-01	35.822 mi
Registration #16	2024-02-23	35.822 mi
Registration #17	2024-02-23	35.822 mi
Registration #18	2024-02-23	35.822 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BMD 313622