



report date: 2024-03-28

General information

Make	VAUXHALL
Model	TIGRA SRI 16V
Colour	Blue
Year of manufacture	2005
Top speed	112 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	125 Nm at 4.000 rpm
Engine capacity	1.364 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.8 mpg
Consumption extra urban	49.6 mpg
Consumption combined	39.2 mpg
CO2 emission	146 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-05-19
Pictures	32
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-11-16
MOT pass rate	85 %
MOT passed	17
Failed MOT tests	3
Total advice items	29
Total items failed	5

MOT #20	2023-11-14 15:56
MOT test number	819600064556
Result	✓ Passed
Next expiry date	2024-11-16
Advice	Central Front Track rod end ball joint has slight play both sides (2.1.3 (b) (i))
Advice	Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
Advice	Front Anti-roll bar linkage ball joint has slight play both sides (5.3.4 (a) (i))

MOT #19	2022-11-09 08:06
MOT test number	781658583335
Result	✓ Passed
Advice	Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

MOT #18	2021-11-17 14:41
MOT test number	868398905479
Result	✓ Passed

**MOT #17**

2020-09-08 07:32

MOT test number

722847598349

Result

✓ Passed

- Advice** Brake fluid ageing
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened scored/corroded (1.1.14 (a) (ii))
- Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** INSP lamp illuminated

MOT #16

2019-09-19 16:47

MOT test number

213031296069

Result

✓ Passed

- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Service due msg illuminated (insp).
- Advice** Brake fluid ageing

MOT #15

2018-10-05 08:03

MOT test number

397439142815

Result

✓ Passed

- Advice** 205/50/16 ALL TYRES DETERIORATED
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #14** 2018-10-05 07:04**MOT test number** 267778868715**Result** ✗ Failed**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Boot lid cannot be secured in the closed position (6.2.1 (e))**Advice** 205/50/16 ALL TYRES DETERIORATED**MOT #13** 2017-10-10 08:57**MOT test number** 108406222856**Result** ✓ Passed**Advice** 205/50/16 ALL TYRES DETERIORATED**MOT #12** 2016-09-27 15:20**MOT test number** 335015677670**Result** ✓ Passed**Advice** 205/50/16 ALL TYRES DETERIORATED**MOT #11** 2015-08-28 15:07**MOT test number** 368723523485**Result** ✓ Passed**Advice** ALL TYRES DETERIORATED**MOT #10** 2014-08-15 11:23**MOT test number** 407207924203**Result** ✓ Passed

**MOT #9** 2014-08-15 11:23**MOT test number** 735207324209**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (1.8)**Pass with rectification** Offside Headlamp aim too low and too far to the right. (1.8)**MOT #8** 2013-09-14 12:55**MOT test number** 506767553260**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Inner Front Track rod end ball joint has slight play (2.2.B.1f)**Advice** Nearside Inner Front Track rod end ball joint has slight play (2.2.B.1f)**MOT #7** 2013-09-13 12:34**MOT test number** 737346753263**Result** ✗ Failed**Fail** Offside Front Windscreen wiper not operating automatically when switched on (8.2.1b)**Advice** Offside Inner Front Track rod end ball joint has slight play (2.2.B.1f)**Fail** Nearside Front Windscreen wiper not operating automatically when switched on (8.2.1b)**Advice** Nearside Inner Front Track rod end ball joint has slight play (2.2.B.1f)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2012-10-30 14:08**MOT test number** 728264402313**Result** ✓ Passed

**MOT #5** 2011-07-13 08:59**MOT test number** 419554991128**Result** ✓ Passed**Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Notice** Front discs inner face rusty and worn**MOT #4** 2010-12-21 10:11**MOT test number** 994615950361**Result** ✓ Passed**Advice** Centre Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #3** 2009-12-22 12:16**MOT test number** 770846659343**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2008-12-12 14:28**MOT test number** 373867648383**Result** ✓ Passed**MOT #1** 2008-01-02 11:09**MOT test number** 954032808023**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
16 November 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	16 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 GL54RFY
Plate since	2024-03-28
Current registration	 GL54RFY
Plate since	2024-03-28

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-01-08
Last registration	2023-11-14
Complete history	See info



Registration #1	2005-01-08	24 mi
Registration #2	2008-01-02	17.851 mi
Registration #3	2008-12-12	23.078 mi
Registration #4	2009-12-22	28.683 mi
Registration #5	2010-12-21	32.390 mi
Registration #6	2011-07-13	33.284 mi
Registration #7	2012-10-30	34.309 mi
Registration #8	2013-09-13	34.944 mi
Registration #9	2013-09-14	34.956 mi
Registration #10	2014-08-15	35.650 mi
Registration #11	2015-08-28	36.082 mi
Registration #12	2016-05-20	36.277 mi
Registration #13	2016-05-20	36.277 mi
Registration #14	2016-05-20	36.277 mi
Registration #15	2016-05-20	36.277 mi
Registration #16	2016-05-20	36.277 mi
Registration #17	2016-05-20	36.277 mi
Registration #18	2016-05-20	36.277 mi
Registration #19	2016-05-20	36.277 mi
Registration #20	2016-05-20	36.277 mi
Registration #21	2016-05-20	36.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1955 mm
Height	1440 mm
Length	3817 mm
Wheel base	2491 mm
Kerb weight	1133 kg
Max. allowed weight	1530 kg

Additional information

Fuel tank capacity	44 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	19FC6425