





report date: 2024-03-28

## General information

Make	HONDA
Model	FR-V I-VTEC ES
Colour	Grey
Year of manufacture	2009
Top speed	118 mph
0 - 60 mph	10.6 seconds
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	138 BHP
Max. torque	174 Nm at 4.300 rpm
Engine capacity	1.799 сс
Cylinders	4
Fuel type	Petrol
Consumption city	30.1 mpg
Consumption extra urban	44.8 mpg
Consumption combined	37.7 mpg
CO2 emission	177 g/km
CO2 label	I



CarCheck.co.uk page 1/12



report date: 2024-03-28

# Internet history

## Entry 1

Date 2022-02-20

Pictures 10

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

B 4	$\sim$ $-$		
10.71	$\alpha$	hic:	tory
101	C) I	1115	I U I V
	•		,

MOT expiry date	2024-03-24
MOT pass rate	100 %
MOT passed	11
Failed MOT tests	0
Total advice items	11
Total items failed	0
****	****
MOT #11	2023-03-25 09:07
MOT test number	359469859392
Result	<b>✓</b> Passed
Next expiry date	2024-03-24
MOT #10	2022-03-18 13:17
MOT test number	669068301357
Result	<b>✓</b> Passed
MOT #9	2021-03-01 15:09
MOT test number	867841230379
Result	<b>✓</b> Passed

MOT #8	2019-09-16 12:46
MOT test number	108015159053
Result	✓ Passed

MOT #7	2018-06-06 13:52
MOT test number	586176934274
Result	✓ Passed

CarCheck.co.uk page 3/12



Advice

Notice

**Advice** 

MW09CVO

report date: 2024-03-28

MOT #6

MOT test number

231498197840

Result

Advice Offside Front Nail in tyre

**MOT #5** 2016-06-11 10:49 **MOT** test number 756577632615 Result ✓ Passed **MOT #4** 2015-07-27 15:26 **MOT** test number 757408105229 Result ✓ Passed **Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g) Notice Items removed from driver's view prior to test Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Offside Front Brake pad(s) wearing thin (3.5.1g)

MOT #3

MOT test number

Result

Advice Offside Front Shock absorber has a light misting of oil (2.7.3)

Notice Items removed from driver's view prior to test

Advise front brake discs worn advise o/s wiperblade worn advise n/s/r tyre slighty distorted

Rear registration plate deteriorated but not likely to be misread (6.3.1d)

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #2 2013-07-19 16:17
MOT test number 707670803202

**Notice** Advise front tyres worn on edges

**Notice** Items removed from driver's view prior to test

MOT #1 2012-07-16 11:49
MOT test number 305238792199

Result ✓ Passed

CarCheck.co.uk page 5/12





report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	24 March 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 6/12




report date: 2024-03-28

#### Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

# Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full	
***************************************	
	More info >
Plate changes	
See in this check if this HONDA had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	OK SIE
Plate since	
	More info

CarCheck.co.uk page 9/12



report date: 2024-03-28

#### Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2009-08-12
Last registration	2023-03-25
Complete history	See info



Registration #1	2009-08-12	11 mi
Registration #2	2012-07-16	35.337 mi
Registration #3	2013-07-19	47.513 mi
Registration #4	2014-07-26	57.114 mi
Registration #5	2015-07-27	69.575 mi
Registration #6	2016-06-11	76.538 mi
Registration #7	2017-05-22	82.386 mi
Registration #8		71.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		10.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

# Safety ratings

NCAP rating	***
Video	see crash video



# Dimensions & weight

Width	1810 mm
Height	1610 mm
Length	4285 mm
Wheel base	2680 mm
Kerb weight	1423 kg

# Additional information

Fuel tank capacity	58 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	6
Number of axles	2
Engine number	R18A13301962

CarCheck.co.uk page 12/12