



report date: 2024-03-28

General information

Make	MAZDA
Model	MX-5 SPORT
Colour	Red
Year of manufacture	2006
Top speed	130 mph
0 - 60 mph	7.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	166 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.5 mpg
Consumption extra urban	43.5 mpg
Consumption combined	34.5 mpg
CO2 emission	193 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-05-23
Pictures	4
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT expiry date	2025-04-20
MOT pass rate	84 %
MOT passed	16
Failed MOT tests	3
Total advice items	21
Total items failed	7

MOT #19	2024-04-08 07:57
MOT test number	519517159434
Result	✓ Passed
Next expiry date	2025-04-20

MOT #18	2023-04-21 11:29
MOT test number	231466904476
Result	✓ Passed

MOT #17	2022-02-04 09:19
MOT test number	718656273131
Result	✓ Passed

- Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a) (ii))
- Minor** Offside Front Windscreen wiper blade defective split on ends (3.4 (b) (i))
- Advice** General corrosion to underside

MOT #16	2021-02-08 14:44
MOT test number	179930660100
Result	✓ Passed

**MOT #15**

2020-11-25 12:13

MOT test number

594869841798

Result

✗ Failed

Fail Offside Rear Seat belt anchorage prescribed area strength or continuity significantly reduced inner sill area (7.1.1 (a) (i))

Advice Front brake discs corroding

Fail Nearside Rear Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Slight bind rear brakes

Advice General corrosion to underside

Fail Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

Fail Offside Rear Inner Seat belt anchorage prescribed area strength or continuity significantly reduced wheel arch area (7.1.1 (a) (i))

Advice Both front tyres cracking

MOT #14

2019-10-30 19:52

MOT test number

946763506488

Result

✓ Passed

MOT #13

2018-10-18 08:36

MOT test number

788471913745

Result

✓ Passed

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive inner sill (5.3.6 (a) (i))

Advice Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**MOT #12** 2018-10-17 08:50**MOT test number** 727543866116**Result** ✗ Failed**Minor** Nearside Rear Tyre obviously under inflated (5.2.3 (h) (i))**Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive inner sill (5.3.6 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Lower Suspension component mounting prescribed area excessively corroded significantly reducing structural strength inner wheel arch (5.3.6 (a) (i))**Advice** Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength inner sill (5.3.6 (a) (i))**MOT #11** 2017-10-13 14:04**MOT test number** 520403295727**Result** ✓ Passed**MOT #10** 2017-10-13 07:46**MOT test number** 427288985388**Result** ✗ Failed**Fail** Nearside Rear coil spring broken (2.4.C.1a)**MOT #9** 2016-11-01 08:39**MOT test number** 723073674090**Result** ✓ Passed**Advice** Nearside Rear tyre cracked and perished**MOT #8** 2015-09-30 08:00**MOT test number** 208331660942**Result** ✓ Passed

**MOT #7** 2014-09-09 09:55**MOT test number** 905082154275**Result** ✓ Passed**Notice** Items removed from driver's view prior to test**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2013-10-02 11:20**MOT test number** 788185373222**Result** ✓ Passed**MOT #5** 2012-09-26 09:28**MOT test number** 645210972222**Result** ✓ Passed**MOT #4** 2011-08-09 09:25**MOT test number** 389171621471**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2010-07-28 09:26**MOT test number** 844579200289**Result** ✓ Passed**MOT #2** 2009-07-30 12:41**MOT test number** 983341719209**Result** ✓ Passed



MOT #1	2009-02-19 13:21
MOT test number	712280059077
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
20 April 2025

Tax status		Valid until 1 November
Days left		185
MOT expiry date		20 April 2025
Full MOT history		See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled. If not, and you buy this MAZDA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-03-11
Last registration	2024-04-08
Complete history	See info



Registration #1	2006-03-11	17 mi
Registration #2	2009-02-19	25.983 mi
Registration #3	2009-07-30	28.601 mi
Registration #4	2010-07-28	33.109 mi
Registration #5	2011-08-09	35.836 mi
Registration #6	2012-09-26	39.211 mi
Registration #7	2013-10-02	42.033 mi
Registration #8	2014-09-09	44.693 mi
Registration #9	2015-09-30	47.670 mi
Registration #10	2016-11-01	50.125 mi
Registration #11	2017-10-13	53.579 mi
Registration #12	2018-05-20	55.277 mi
Registration #13	2018-05-20	55.277 mi
Registration #14	2018-05-20	55.277 mi
Registration #15	2018-05-20	55.277 mi
Registration #16	2018-05-20	55.277 mi
Registration #17	2018-05-20	55.277 mi
Registration #18	2018-05-20	55.277 mi
Registration #19	2018-05-20	55.277 mi
Registration #20	2018-05-20	55.277 mi
Registration #21	2018-05-20	55.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1720 mm
Height	1245 mm
Length	3995 mm
Wheel base	2330 mm
Kerb weight	1155 kg
Max. allowed weight	1355 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	LF 677125