





report date: 2024-03-29

General information

Make	BMW
Model	X5 XDRIVE30D M SPORT
Colour	Black
Year of manufacture	2015
Top speed	142 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	255 BHP
Max. torque	560 Nm at 1.500 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption city	41.5 mpg
Consumption extra urban	51.4 mpg
Consumption combined	47.1 mpg
CO2 emission	158 g/km
CO2 label	G



CarCheck.co.uk page 1/11



GV15DKE

report date: 2024-03-29

Internet history

Entry 1

Date 2021-05-23

Pictures 4

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-06-02
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	8
Total items failed	2

MOT #7	2023-06-01 14:33
MOT test number	339058368443
Result	✓ Passed
Next expiry date	2024-06-02

MOT #6		2022-06-03 09:48
MOT test	number	258830097356
Result		✓ Passed
Advice	Nearside Rear Tyre has a cut but not deep enough to reach the ply o	r cords (5.2.3 (d) (i))

MOT #5		2021-05-24 11:51
MOT test	number	947280329576
Result		✓ Passed
Advice	Tyre worn close to legal limit/worn on edge Both nearside and offside r	rear (5.2.3 (e))

MOT #4	2020-05-12 09:16
MOT test number	763115367759
Result	✓ Passed

CarCheck.co.uk page 3/11



GV15DKE

report date: 2024-03-29

MOT test number

Result

Advice Nearside rear tyre worn down to 2.6mm.

Advice Offside rear tyre worn down to 2.3mm.

Advice Covers impede parts of the inspection.

MOT #2

MOT test number

534799359154

Result

Advice Front bumper dented

MOT test number

Result

Advice Front bumper dented

Fail Offside Rear Tyre has ply or cords exposed (4.1.D.1b)

Advice Offside Rear Tyre has ply or cords exposed (4.1.D.1b)

Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 June
Days left	32
MOT expiry date	2 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra BMW salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

o mile mesery	
For how long did the current and previous owner(s) have this BMW? How many owners defined the current and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this BMW had different number plates.	
See in this check if this BMW had different humber plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



GV15DKE

report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2015-05-27
Last registration	2023-06-01
Complete history	See info



Registration #1	2015-05-27	21 mi
Registration #2	2018-05-15	34.402 mi
Registration #3	2018-05-22	34.679 mi
Registration #4	2019-04-30	51.962 mi
Registration #5	2020-05-12	63.706 mi
Registration #6		71.777 66
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
50566	
S0567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1938 mm
Height	1762 mm
Length	4886 mm
Wheel base	2933 mm
Kerb weight	2070 kg
Max. allowed weight	2785 kg

Additional information

Fuel tank capacity	85 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page	11/11

Number of axles2Engine number68329292