



report date: 2024-03-28

General information

Make	VAUXHALL
Model	COMBO 2000 CDTI CREWVAN
Colour	White
Year of manufacture	2010
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	240 Nm at 2.300 rpm
Engine capacity	1.686 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	64.2 mpg
Consumption combined	54.3 mpg



LABEL UNKNOWN



MOT history

MOT expiry date	2025-02-14
MOT pass rate	58 %
MOT passed	11
Failed MOT tests	8
Total advice items	43
Total items failed	16

MOT #19	2024-02-15 12:54
MOT test number	730574733401
Result	✓ Passed
Next expiry date	2025-02-14

MOT #18	2024-01-25 13:27
MOT test number	733393067043
Result	✗ Failed
MAJOR Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))	

MOT #17	2023-02-01 11:17
MOT test number	158646331225
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened Both Front (1.1.14 (a) (ii))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

**MOT #16** 2022-01-26 10:47**MOT test number** 181715412488**Result** ✓ Passed**Advice** Central Rear Spare wheel loose**Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #15** 2020-10-22 14:10**MOT test number** 532578511854**Result** ✓ Passed**MOT #14** 2019-08-23 10:56**MOT test number** 912015492227**Result** ✓ Passed**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))



MOT #132019-08-22 13:48

MOT test number622494234246

Result

Failed

Advice

Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MAJOR

Nearside Front Suspension arm pin or bush excessively worn REAR (5.3.4 (a) (i))

DANGEROUS

Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MAJOR

Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

DANGEROUS

Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice

Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MAJOR

Offside Front Suspension arm pin or bush excessively worn REAR (5.3.4 (a) (i))

DANGEROUS

Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))



MOT #12

2018-08-30 14:59

MOT test number

682995670686

Result		✓ Passed
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))	
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Gearbox mounting defective	
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))	



MOT #11 2018-08-29 11:16

MOT test number 951879339642

Result ✗ Failed

- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Gearbox mounting defective
- MAJOR** Rear Exhaust has a major leak of exhaust gases back box (6.1.2 (a))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Pass with rectification** Fuel cap/sealing device missing (6.1.3 (b) (i))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Nearside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))
- DANGEROUS** Bonnet seriously at risk of opening inadvertently (3.1 (b) (ii))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #10 2017-08-30 15:52

MOT test number 863101176142

Result ✓ Passed

**MOT #9** 2017-08-30 10:24**MOT test number** 575547261316**Result** ✗ Failed

- Fail** Offside Front Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)
- Fail** Offside Front Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Front coil spring broken (2.4.C.1a)
- Fail** Nearside Rear coil spring broken (2.4.C.1a)
- Fail** Nearside Front Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)
- Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)
- Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)
- Fail** Offside Front coil spring broken (2.4.C.1a)
- Fail** Offside Rear coil spring broken (2.4.C.1a)

MOT #8 2016-10-07 15:30**MOT test number** 540823347763**Result** ✓ Passed**MOT #7** 2016-10-07 15:30**MOT test number** 797081420352**Result** ✗ Failed

- Pass with rectification** Nearside Front Road wheel fractured (4.2.B.1a)

MOT #6 2015-10-06 08:46**MOT test number** 534466630034**Result** ✓ Passed

**MOT #5** 2015-10-06 08:46**MOT test number** 686476522716**Result** ✗ Failed**Pass with rectification** Seat belt locking mechanism does not secure or release coin (5.2.5a)**MOT #4** 2014-06-24 14:21**MOT test number** 245425074160**Result** ✓ Passed**MOT #3** 2014-06-24 14:21**MOT test number** 917425474157**Result** ✗ Failed**Pass with rectification** Exhaust tailpipe not capable of allowing the emission probe to be inserted (7.4.B.1)**Pass with rectification** Nearside Track rod end ball joint has excessive play (2.2.B.1f)**MOT #2** 2013-03-09 12:02**MOT test number** 125238263033**Result** ✓ Passed**MOT #1** 2013-03-09 12:02**MOT test number** 688558463043**Result** ✗ Failed**Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)**Pass with rectification** Nearside Rear Front position lamp(s) not working (1.1.A.3b)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
14 February 2025

Tax status		Valid until 1 September
Days left		125
MOT expiry date		14 February 2025
Full MOT history		See MOT history



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	DL10DXZ
Plate since	2019-06-29
Current registration	DL10DXZ
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-06-18
Last registration	2024-02-15
Complete history	See info



Registration #1	2010-06-18	8 mi
Registration #2	2013-03-09	48.987 mi
Registration #3	2014-06-24	58.098 mi
Registration #4	2015-10-06	68.101 mi
Registration #5	2015-10-06	68.101 mi
Registration #6	2016-10-07	77.011 mi
Registration #7	2016-10-07	77.011 mi
Registration #8	2017-08-30	82.212 mi
Registration #9	2017-08-30	82.212 mi
Registration #10	2019-05-29	95.377 mi
Registration #11	2019-05-29	95.377 mi
Registration #12	2019-05-29	95.377 mi
Registration #13	2019-05-29	95.377 mi
Registration #14	2019-05-29	95.377 mi
Registration #15	2019-05-29	95.377 mi
Registration #16	2019-05-29	95.377 mi
Registration #17	2019-05-29	95.377 mi
Registration #18	2019-05-29	95.377 mi

More info >



Dimensions & weight

Width	1892 mm
Height	1801 mm
Length	4323 mm
Kerb weight	1329 kg
Max. allowed weight	1995 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Engine number	2086685