



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	206 ZEST 3
Colour	Blue
Year of manufacture	-
Top speed	98 mph
0 - 60 mph	15.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	60 BHP
Max. torque	94 Nm at 2.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	34.4 mpg
Consumption extra urban	56.5 mpg
Consumption combined	45.6 mpg



LABEL UNKNOWN



Internet history

Entry 1	
Date	2021-05-25
Pictures	8
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #18	2021-09-09 15:57
MOT test number	135411535556
Result	✓ Passed
Next expiry date	2022-09-27
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #17	2020-09-11 11:54
MOT test number	431973145650
Result	✓ Passed
Advice	Rear Tyre slightly damaged/cracking or perishing both cracking (5.2.3 (d) (ii))
Advice	Rear Position lamp slightly affected by the operation of another lamp both (4.2.3 (c))
Advice	Play in steering rack inner joint(s)
Advice	Offside Front Direction indicator slightly discoloured (4.4.3 (a))

MOT #16	2020-09-11 10:55
MOT test number	145953154623
Result	✗ Failed
Advice	Play in steering rack inner joint(s)
Advice	Offside Front Direction indicator slightly discoloured (4.4.3 (a))
Advice	Rear Position lamp slightly affected by the operation of another lamp both (4.2.3 (c))
Advice	Rear Tyre slightly damaged/cracking or perishing both cracking (5.2.3 (d) (ii))
MAJOR	Tailgate insecure (6.2.1 (a) (i))

**MOT #15** 2019-09-13 14:18**MOT test number** 781424371889**Result** ✓ Passed

- Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Tyre worn close to legal limit/worn on edge both tyres worn edges (5.2.3 (e))
- Advice** Play in steering rack inner joint(s)

MOT #14 2019-09-13 10:49**MOT test number** 689469361567**Result** ✗ Failed

- Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Play in steering rack inner joint(s)
- MAJOR** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Front Tyre worn close to legal limit/worn on edge both tyres worn edges (5.2.3 (e))

MOT #13 2018-09-28 16:13**MOT test number** 764042019768**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

**MOT #12**

2018-09-28 10:45

MOT test number

106752842249

Result

✗ Failed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**MAJOR** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Spare tyre soft**MAJOR** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #11**

2017-07-03 12:00

MOT test number

744327327285

Result

✓ Passed

Advice Oil leak Gearbox**Advice** Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)**MOT #10**

2016-07-04 11:47

MOT test number

510886339696

Result

✓ Passed

Advice Items removed from driver's view prior to test**Advice** Oil leak

**MOT #9** 2016-07-03 15:07**MOT test number** 926028273522**Result** ✗ Failed**Advice** Nearside rear tyre perished outer edges**Fail** Offside Rear Tyre has ply or cords exposed outer edges (4.1.D.1b)**Advice** Both front tyres wearing out edges**Advice** Oil leak**MOT #8** 2015-06-22 12:51**MOT test number** 536543575108**Result** ✓ Passed**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #7** 2014-06-19 12:38**MOT test number** 816810574127**Result** ✓ Passed**MOT #6** 2013-06-24 15:16**MOT test number** 476225173182**Result** ✓ Passed**MOT #5** 2012-07-02 15:27**MOT test number** 618104382124**Result** ✓ Passed**MOT #4** 2011-06-30 15:07**MOT test number** 136671081124**Result** ✓ Passed



MOT #3	2010-07-05 09:27
MOT test number	784486580143
Result	✓ Passed

MOT #2	2009-07-06 11:09
MOT test number	241347589487
Result	✓ Passed
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)

MOT #1	2008-07-07 15:32
MOT test number	514969388131
Result	✓ Passed



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-07-06
Last registration	2021-09-09
Complete history	See info



Registration #1	2005-07-06	26 mi
Registration #2	2008-07-07	20.926 mi
Registration #3	2009-07-06	27.698 mi
Registration #4	2010-07-05	33.677 mi
Registration #5	2011-06-30	36.269 mi
Registration #6	2012-07-02	39.202 mi
Registration #7	2013-06-24	42.892 mi
Registration #8	2014-06-19	47.937 mi
Registration #9	2015-06-22	53.859 mi
Registration #10	2016-07-03	60.165 mi
Registration #11	2017-06-29	65.377 mi
Registration #12	2018-06-29	70.589 mi
Registration #13	2019-06-29	75.801 mi
Registration #14	2020-06-29	81.013 mi
Registration #15	2021-06-29	86.225 mi
Registration #16	2022-06-29	91.437 mi
Registration #17	2023-06-29	96.649 mi
Registration #18	2024-06-29	101.861 mi
Registration #19	2025-06-29	107.073 mi
Registration #20	2026-06-29	112.285 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	985 kg
Max. allowed weight	1405 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number

FP7N4789506