



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	RAV-4 VVTI XT5
Colour	Blue
Year of manufacture	2006
Top speed	109 mph
0 - 60 mph	12.0 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	150 BHP
Max. torque	194 Nm at 4.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	24.4 mpg
Consumption extra urban	38.2 mpg
Consumption combined	31.4 mpg
CO2 emission	212 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-10-06
Pictures	24
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2022-10-17
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	31
Total items failed	12

MOT #18	2021-10-18 14:35
MOT test number	926515981709
Result	✓ Passed
Next expiry date	2022-10-17

MOT #17	2021-10-08 15:34
MOT test number	303354818461
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Minor	Nearside Front Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #16** 2020-09-30 16:32**MOT test number** 643921790269**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin Both sides (1.1.13 (a) (ii))**Minor** Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt Both sides (2.1.3 (g) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Battery light on**MOT #15** 2020-09-30 10:17**MOT test number** 845957805427**Result** ✗ Failed**Pass with rectification** Front Headlamp aim too low Both sides (4.1.2 (a))**Advice** Battery light on**Advice** Nearside Rear Nail in tyre 2256517**Advice** Rear Brake pad(s) wearing thin Both sides (1.1.13 (a) (ii))**Minor** Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt Both sides (2.1.3 (g) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Fail** Front Tyre tread depth below requirements of 1.6mm Both sides 2256517 (5.2.3 (e))**MOT #14** 2019-04-02 13:15**MOT test number** 852528541716**Result** ✓ Passed

**MOT #13**

2018-03-23 17:22

MOT test number

166799273011

Result

✓ Passed

- Advice** Offside Rear Nail in tyre
- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)

MOT #12

2018-03-23 14:56

MOT test number

638170650781

Result

✗ Failed

- Fail** Offside Front Track rod end ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.2.C.1c)
- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)
- Fail** Offside Front Front suspension has excessive movement at a wishbone pin or bush (2.5.A.1c)
- Advice** Offside Rear Nail in tyre
- Fail** Nearside Front Front suspension has excessive movement at a wishbone pin or bush (2.5.A.1c)

MOT #11

2018-03-19 14:43

MOT test number

898122430625

Result

✗ Failed

- Fail** Nearside Front Inner Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Advice** Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Uneven brake wear to rear
- Fail** Offside Front Outer Track rod end ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.2.C.1c)
- Fail** Offside Front Inner Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Advice** Offside Rear Nail in tyre

**MOT #10** 2017-02-22 17:29**MOT test number** 850789439760**Result** ✓ Passed**Advice** Nearside rear tyre is cracking on sidewall.**Advice** Both rear shock lower bushes have started to crack.**MOT #9** 2016-02-23 14:18**MOT test number** 682941188777**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases centre pipe (7.1.2)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #8** 2015-03-09 15:09**MOT test number** 747208465001**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #7** 2015-03-09 15:09**MOT test number** 169478065444**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)



MOT #6	2014-06-17 11:28
---------------	------------------

MOT test number	457768964149
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2013-07-02 11:00
---------------	------------------

MOT test number	639723283151
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	---

Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	--

MOT #4	2012-07-06 09:54
---------------	------------------

MOT test number	317618382153
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2011-06-22 13:10
---------------	------------------

MOT test number	476333671109
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2010-06-23 11:01
---------------	------------------

MOT test number	252444470143
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2009-06-19 10:14
---------------	------------------

MOT test number	762920979140
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

✕
Untaxed

Tax expired:
30 November 2021

✕
MOT

Expired:
17 October 2022

Tax status	Expired at 30 November 2021
Days left	880 days too late
MOT expiry date	17 October 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	GP06NJU
Plate since	2024-03-29
Current registration	GP06NJU
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-07-01
Last registration	2021-10-18
Complete history	See info



Registration #1	2006-07-01	20 mi
Registration #2	2009-06-19	32.091 mi
Registration #3	2010-06-23	42.445 mi
Registration #4	2011-06-22	48.167 mi
Registration #5	2012-07-06	57.865 mi
Registration #6	2013-07-02	67.859 mi
Registration #7	2014-06-17	75.945 mi
Registration #8	2015-03-09	82.283 mi
Registration #9	2016-02-23	88.641 mi
Registration #10	2017-02-22	96.328 mi
Registration #11	2018-03-20	96.328 mi
Registration #12	2019-03-20	96.328 mi
Registration #13	2020-03-20	96.328 mi
Registration #14	2021-03-20	96.328 mi
Registration #15	2022-03-20	96.328 mi
Registration #16	2023-03-20	96.328 mi
Registration #17	2024-03-20	96.328 mi
Registration #18	2025-03-20	96.328 mi
Registration #19	2026-03-20	96.328 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1815 mm
Height	1720 mm
Length	4395 mm
Wheel base	2560 mm
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

1AZ5424542