



AM08WSJ

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	PASSAT HIGHLINE TDI
Colour	Blue
Year of manufacture	2008
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Engine capacity	1.986 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	156 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-10-18
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	48
Total items failed	12

MOT #19	2023-10-09 14:11
MOT test number	481109526084
Result	✓ Passed
Next expiry date	2024-10-18
Advice	Nearside Front Steering rack has slight free play detected at steering wheel (2.3 (a) (i))

MOT #18	2022-10-17 07:49
MOT test number	815402934936
Result	✓ Passed
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Play in steering rack inner joint(s)

**MOT #17** 2022-10-17 07:49**MOT test number** 384274142207**Result** ✗ Failed**Pass with rectification** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Advice** Nearside Front Play in steering rack inner joint(s)**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #16** 2021-10-19 09:39**MOT test number** 866325158886**Result** ✓ Passed**Advice** Rear Suspension arm attachment bracket/mounting corroded but its strength is not seriously reduced (5.3.3 (b) (i))**MOT #15** 2021-10-19 09:39**MOT test number** 125421114182**Result** ✗ Failed**Pass with rectification** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Advice** Rear Suspension arm attachment bracket/mounting corroded but its strength is not seriously reduced (5.3.3 (b) (i))

**MOT #14**

2020-10-16 12:39

MOT test number

532962080816

Result

✓ Passed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Under trays fitted

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #13

2020-10-15 15:26

MOT test number

781528062489

Result

✗ Failed

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Under trays fitted

MAJOR Windscreen washer not working (3.5 (a))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

DANGEROUS Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MAJOR Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**MOT #12**

2019-05-01 08:44

MOT test number

324631104477

Result

✓ Passed

Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #11

2018-05-16 11:56

MOT test number

636590515226

Result

✓ Passed

MOT #10

2018-05-12 14:48

MOT test number

386402970805

Result

✗ Failed

Fail

Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail

Nearside Rear Tyre tread depth below requirements of 1.6mm bald inner shoulder (4.1.E.1)

Fail

Offside Front front brake excessively fluctuating (3.7.B.3)

Fail

Rear Exhaust system not adequately supported (7.1.1)

Fail

Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail

Offside Rear Tyre tread depth below requirements of 1.6mm bald inner shoulder 235/45/17 (4.1.E.1)

Fail

Front front brake application uneven (3.7.B.2)

Fail

Central Rear Exhaust has a major leak of exhaust gases (7.1.2)

MOT #9

2017-03-08 12:26

MOT test number

966410753287

Result

✓ Passed

Advice

Under trays fitted

Advice

Rear tyres worn inner edge

**MOT #8** 2016-03-16 16:34**MOT test number** 627402031423**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Under trays fitted**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2016-03-10 10:20**MOT test number** 959547928439**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Under trays fitted**Fail** Electronic parking brake warning indicates a malfunction (3.1.7)**MOT #6** 2015-03-16 12:07**MOT test number** 795685375067**Result** ✓ Passed**MOT #5** 2014-03-20 13:30**MOT test number** 227629074083**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Under-trays fitted obscuring some underside components**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Engine covers fitted obscuring some components in the engine bay



MOT #4 2014-02-20 10:41

MOT test number 129881254433

Result ✓ Passed

Notice Engine covers fitted obscuring some components in the engine bay

Notice Under-trays fitted obscuring some underside components

MOT #3 2013-02-27 14:31

MOT test number 878498853073

Result ✓ Passed

MOT #2 2012-03-14 16:43

MOT test number 346534072084

Result ✓ Passed

MOT #1 2011-03-02 16:36

MOT test number 208211861063

Result ✓ Passed

Notice Rear tyres starting to wear unevenly

Notice Small stone chips in windscreen



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
18 October 2024

Tax status	Valid until 1 January
Days left	246
MOT expiry date	18 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-03-19
Last registration	2023-10-09
Complete history	See info



Registration #1	2008-03-19	6 mi
Registration #2	2011-03-02	28.252 mi
Registration #3	2012-03-14	35.959 mi
Registration #4	2013-02-27	50.395 mi
Registration #5	2014-02-20	63.290 mi
Registration #6	2014-03-20	63.426 mi
Registration #7	2015-03-16	69.461 mi
Registration #8	2016-03-10	77.098 mi
Registration #9	2016-03-16	77.185 mi
Registration #10	2017-03-08	81.665 mi
Registration #11	2018-05-12	84.835 mi
Registration #12	2019-05-20	85.277 mi
Registration #13	2020-05-20	85.277 mi
Registration #14	2021-05-20	85.277 mi
Registration #15	2022-05-20	85.277 mi
Registration #16	2023-05-20	85.277 mi
Registration #17	2024-05-20	85.277 mi
Registration #18	2025-05-20	85.277 mi
Registration #19	2026-05-20	85.277 mi
Registration #20	2027-05-20	85.277 mi
Registration #21	2028-05-20	85.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1517 mm
Length	4774 mm
Wheel base	2709 mm
Kerb weight	1510 kg
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Engine number	CBA 067351