



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	PASSAT SEL TDI
Colour	Black
Year of manufacture	2009
Top speed	136 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	170 BHP
Max. torque	350 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	149 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-07-27
Pictures	29
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-23
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	29
Total items failed	7

MOT #16 2023-06-24 11:40

MOT test number 334071922933

Result ✓ Passed

Next expiry date 2024-06-23

- Advice** Nearside Rear Brake pad(s) wearing thin worn very close to minimum (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge tread very low (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge badly worn on inner edge also 2x nails in tread (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge tread very low (5.2.3 (e))

MOT #15 2023-06-24 10:59

MOT test number 295209453452

Result ✗ Failed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge tread very low (5.2.3 (e))
- DANGEROUS** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge tread very low (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge badly worn on inner edge also 2x nails in tread (5.2.3 (e))
- Advice** Nearside Rear Brake pad(s) wearing thin worn very close to minimum (1.1.13 (a) (ii))

**MOT #14** 2022-02-19 08:52**MOT test number** 397707420708**Result** ✓ Passed**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Rear Outer Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #13** 2021-01-26 11:39**MOT test number** 773419015733**Result** ✓ Passed**MOT #12** 2021-01-26 10:21**MOT test number** 441416450885**Result** ✗ Failed**MAJOR** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MAJOR** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #11** 2020-01-23 12:01**MOT test number** 565060053529**Result** ✓ Passed**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #10** 2020-01-23 12:01**MOT test number** 397064886913**Result** ✗ Failed**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Pass with rectification** Offside Windscreen wiper not working (3.4 (a))**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #9** 2019-01-30 12:32**MOT test number** 421102191469**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2018-01-23 10:08**MOT test number** 370335682986**Result** ✓ Passed**MOT #7** 2018-01-23 10:08**MOT test number** 596872140246**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**Pass with rectification** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Pass with rectification** Battery insecure (1.9.1)**MOT #6** 2017-01-16 12:41**MOT test number** 453804468295**Result** ✓ Passed**MOT #5** 2017-01-05 13:45**MOT test number** 224185058829**Result** ✗ Failed**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)

**MOT #4** 2016-01-21 11:54**MOT test number** 205599197885**Result** ✓ Passed**Advice** Child seats fitted**MOT #3** 2015-01-20 12:49**MOT test number** 449950125092**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #2** 2014-01-14 10:45**MOT test number** 986754214099**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Under-trays fitted obscuring some underside components**MOT #1** 2013-02-01 16:25**MOT test number** 178602633004**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
23 June 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	23 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 YP09ZXH
Plate since	2024-03-28
Current registration	 YP09ZXH
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-07-17
Last registration	2023-06-24
Complete history	See info



Registration #1	2009-07-17	20 mi
Registration #2	2013-02-01	43.593 mi
Registration #3	2014-01-14	50.243 mi
Registration #4	2015-01-20	56.890 mi
Registration #5	2016-01-21	64.549 mi
Registration #6	2017-01-05	72.803 mi
Registration #7	2017-01-16	72.911 mi
Registration #8	2018-01-23	79.353 mi
Registration #9	2018-01-23	79.353 mi
Registration #10	2019-01-23	85.795 mi
Registration #11	2019-01-23	85.795 mi
Registration #12	2019-01-23	85.795 mi
Registration #13	2019-01-23	85.795 mi
Registration #14	2019-01-23	85.795 mi
Registration #15	2019-01-23	85.795 mi
Registration #16	2019-01-23	85.795 mi
Registration #17	2019-01-23	85.795 mi
Registration #18	2019-01-23	85.795 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1517 mm
Length	4774 mm
Wheel base	2709 mm
Kerb weight	1499 kg
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	CBB 130364