



report date: 2024-03-28

General information

Make	CITROEN
Model	BERLINGO LX 600 D P/V
Colour	White
Year of manufacture	2005
Gearbox	5 speed Manual

Engine & fuel consumption

Power	71 BHP
Max. torque	125 Nm at 2.500 rpm
Engine capacity	1.868 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



MOT history

MOT expiry date	2022-01-07
MOT pass rate	59 %
MOT passed	13
Failed MOT tests	9
Total advice items	24
Total items failed	28

MOT #22	2020-12-09 17:42
MOT test number	674785884692
Result	✓ Passed
Next expiry date	2022-01-07
Advice	Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))

MOT #21	2020-12-09 09:23
MOT test number	668532505891
Result	✗ Failed
Fail	Rear Emissions not tested box (8.2.2.2 (e))
Fail	Nearside Rear Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))
Fail	Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Fail	Offside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))
Advice	Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))
Fail	Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))
Fail	Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

**MOT #20** 2019-12-09 16:59**MOT test number** 279991840010**Result** ✓ Passed**MOT #19** 2019-12-09 09:31**MOT test number** 865645110662**Result** ✗ Failed**Fail** Rear Exhaust system insecure (6.1.2 (a))**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure 175/65/14 (5.2.3 (d) (ii))**MOT #18** 2019-01-08 15:58**MOT test number** 715886161061**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #17**

2019-01-07 09:46

MOT test number

894519481797

Result**✗ Failed**

- Fail** Nearside Front Direction indicator incorrect colour (4.4.3 (a))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Nearside Rear Suspension arm pin or bush excessively worn axle (5.3.4 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Side repeater incorrect colour (4.4.3 (a))
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #16

2018-01-05 09:59

MOT test number

130353716230

Result**✓ Passed**

- Advice** Oil leak

MOT #15

2018-01-03 12:48

MOT test number

750047249374

Result**✗ Failed**

- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Fail** Central Exhaust system not adequately supported Rubber split (7.1.1)
- Fail** Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)
- Fail** Offside Rear Stop lamp not working (1.2.1b)
- Advice** Oil leak
- Fail** Nearside Front Upper Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

**MOT #14** 2017-01-04 10:07**MOT test number** 341723121547**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened inner faces (3.5.1i)**Advice** Oil leak**MOT #13** 2016-01-07 09:54**MOT test number** 787468730611**Result** ✓ Passed**Advice** Front Inner brake disc worn, pitted or scored, but not seriously weakened faces (3.5.1i)**MOT #12** 2014-12-16 10:15**MOT test number** 747230954391**Result** ✓ Passed**MOT #11** 2014-01-08 11:44**MOT test number** 805978804045**Result** ✓ Passed**MOT #10** 2014-01-08 10:27**MOT test number** 299668204048**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Front front parking (secondary) brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.6b)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Registration plate lamp not working (1.1.C.1d)

**MOT #9** 2013-01-08 10:05**MOT test number** 265618103026**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Exhaust slightly deteriorated**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**MOT #8** 2013-01-08 10:05**MOT test number** 445598503016**Result** ✗ Failed**Pass with rectification** Offside Rear Stop lamp adversely affected by the operation of another lamp (1.2.1f)**Notice** Exhaust slightly deteriorated**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2011-12-07 17:18**MOT test number** 408471041494**Result** ✓ Passed**MOT #6** 2011-12-07 17:18**MOT test number** 317951141372**Result** ✗ Failed**Pass with rectification** Nearside Front Direction indicator not working (1.4.A.2c)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)

**MOT #5** 2010-12-04 11:39**MOT test number** 950108030345**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2009-11-23 14:46**MOT test number** 903867329391**Result** ✓ Passed**MOT #3** 2009-11-23 10:55**MOT test number** 841367629361**Result** ✗ Failed**Fail** Offside Rear Road wheel bead rim badly distorted (4.2.A.1a)**Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)**MOT #2** 2008-11-24 12:27**MOT test number** 812109928389**Result** ✓ Passed**Advice** Offside Front Power steering pipe(s) or hose(s) has slight seepage (2.3.3b)**MOT #1** 2008-11-24 12:27**MOT test number** 620239928337**Result** ✗ Failed**Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)**Advice** Offside Front Power steering pipe(s) or hose(s) has slight seepage (2.3.3b)



Tax & MOT check

✕
Untaxed

Tax expired:
4 February 2021

✕
MOT

Expired:
7 January 2022

Tax status	Expired at 4 February 2021
Days left	1180 days too late
MOT expiry date	7 January 2022
Full MOT history	See MOT history



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1		
Date		
Category		
Type		
Damage 2		
Date		
Category		
Type		



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	WD55E00
Plate since	2019-09-28
Current registration	WD55E00
Plate since	2019-09-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-12-13
Last registration	2020-12-09
Complete history	See info



Registration #1	2005-12-13	15 mi
Registration #2	2008-11-24	35.601 mi
Registration #3	2009-11-23	51.702 mi
Registration #4	2009-11-23	51.702 mi
Registration #5	2010-12-04	67.182 mi
Registration #6	2011-12-07	72.138 mi
Registration #7	2013-01-08	81.823 mi
Registration #8	2014-01-08	90.917 mi
Registration #9	2014-01-08	90.917 mi
Registration #10	2014-12-16	99.898 mi
Registration #11	2015-01-01	100.000 mi
Registration #12	2015-01-01	100.000 mi
Registration #13	2015-01-01	100.000 mi
Registration #14	2015-01-01	100.000 mi
Registration #15	2015-01-01	100.000 mi
Registration #16	2015-01-01	100.000 mi
Registration #17	2015-01-01	100.000 mi
Registration #18	2015-01-01	100.000 mi
Registration #19	2015-01-01	100.000 mi
Registration #20	2015-01-01	100.000 mi

More info >



Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)

Dimensions & weight

Width	1724 mm
Height	1819 mm
Length	4137 mm

Additional information

Fuel tank capacity	60 l
Fuel delivery	Indirect Injection
Number of doors	4
Number of seats	2
Engine number	DXFR6116663