





report date: 2024-03-29

General information

Make	MAZDA
Model	3 SE-L NAV
Colour	Red
Year of manufacture	2017
Top speed	121 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	210 Nm at 4.000 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Petrol
Consumption city	43.5 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2021-08-25

Pictures 27

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history

MOT expiry date	2024-09-12
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	14
Total items failed	1

MOT #6		2023-09-13 11:36
MOT test	number	607614471028
Result		✓ Passed
Next expir	y date	2024-09-12
Advice Front Brake pipe corroded, covered in grease or other material Both corroded (1.1.11 (c))		
Advice	General underside corrosion	
Advice	Undertrays fitted obscuring some components	
Advice	Rear Brake pipe corroded, covered in grease or other material Both cor	rroded (1.1.11 (c))

MOT #5	2023-09-07 1	5:01
MOT test	number 862535460)461
Result	× Fa	ailed
Advice	Rear Tyre worn close to legal limit/worn on edge Both getting low on tread & perishing (5.2.3 (6	<u>;</u>))
Advice	Front Brake pipe corroded, covered in grease or other material Both corroded (1.1.11 (c))	
Advice	Undertrays fitted obscuring some components	
Fail No	learside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
Advice	Rear Brake pipe corroded, covered in grease or other material Both corroded (1.1.11 (c))	
Advice	General underside corrosion	

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #4 2022-08-18 15:15

MOT test number 541409456723

Result ✓ Passed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened Both (inner braking surfaces worse) (1.1.14 (a) (ii))

Advice Undertrays fitted obscuring some components

Advice Offside Rear Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice General underside corrosion

MOT #3 2021-09-03 11:38

MOT test number 104269268682

Result
✓ Passed

MOT #2 2021-03-16 16:23

MOT test number 501606805892

Result \(\sqrt{Passed} \)

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #1 2020-03-10 09:21

MOT test number 709771240588

Result
✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check





Expires: 12 September 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	12 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full it	

	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-03-17
Last registration	2023-09-13
Complete history	See info



Registration #1	2017-03-17	21 mi
Registration #2	2020-03-10	9.879 mi
Registration #3	2021-03-16	12.306 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 10/11



SP17ZTM report date: 2024-03-29

Safety ratings

NCAP rating	****
Adult	93%
Children	86%
Pedestrian	65%
Safety systems	81%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1795 mm
Height	1465 mm
Length	4465 mm
Wheel base	2700 mm
Kerb weight	1351 kg
Max. allowed weight	1815 kg

Additional information

Fuel tank capacity	51 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	PE 20877374

CarCheck.co.uk page 11/11