



report date: 2024-03-28

General information

Make	VOLVO
Model	S40 SE
Colour	Green
Year of manufacture	2004
Top speed	124 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	121 BHP
Max. torque	170 Nm at 4.000 rpm
Engine capacity	1.783 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.2 mpg
CO2 emission	187 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-02-01
MOT pass rate	72 %
MOT passed	18
Failed MOT tests	7
Total advice items	13
Total items failed	13

MOT #25 2024-01-29 14:10

MOT test number 546425876546

Result ✓ Passed

Next expiry date 2025-02-01

Advice Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

MOT #24 2023-01-31 12:41

MOT test number 752208200268

Result ✓ Passed

Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #23 2023-01-30 16:23

MOT test number 200372907455

Result ✗ Failed

Fail Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

**MOT #22** 2022-02-02 10:54**MOT test number** 225657132137**Result** ✓ Passed**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**MOT #21** 2021-03-16 12:43**MOT test number** 582813353255**Result** ✓ Passed**MOT #20** 2020-05-28 15:05**MOT test number** 519268649004**Result** ✓ Passed**MOT #19** 2019-05-15 09:45**MOT test number** 170530319287**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))**MOT #18** 2019-05-15 09:31**MOT test number** 652344767567**Result** ✗ Failed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))**Fail** Offside Rear Direction indicator not working (4.4.1 (a) (ii))**Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure in tread area 205/50R16 (5.2.3 (d) (ii))**MOT #17** 2018-10-04 16:33**MOT test number** 349696047233**Result** ✓ Passed

**MOT #16** 2017-09-18 11:20**MOT test number** 926293447848**Result** ✓ Passed**Advice** Items removed from driver's view prior to test**MOT #15** 2016-09-30 10:06**MOT test number** 826019180775**Result** ✓ Passed**Advice** Offside headlight cleaning device broken**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #14** 2015-09-18 09:13**MOT test number** 215731726297**Result** ✓ Passed**Advice** Nearside Rear Inner sidelight not working**MOT #13** 2014-09-24 11:31**MOT test number** 129567264273**Result** ✓ Passed**MOT #12** 2013-09-19 10:14**MOT test number** 666032363203**Result** ✓ Passed**MOT #11** 2012-09-20 12:23**MOT test number** 326654862275**Result** ✓ Passed

**MOT #10** 2012-09-20 10:11**MOT test number** 638284362219**Result** ✗ Failed**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**MOT #9** 2011-09-20 16:51**MOT test number** 956853261205**Result** ✓ Passed**MOT #8** 2011-09-20 12:25**MOT test number** 318043361476**Result** ✗ Failed**Fail** Nearside Headlamp aim not tested (1.8.A.1c)**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #7** 2010-09-22 10:20**MOT test number** 343535760400**Result** ✓ Passed**Notice** N/s/r outer sidelight not working**MOT #6** 2009-09-22 09:25**MOT test number** 434675369272**Result** ✓ Passed

**MOT #5** 2009-09-21 11:52**MOT test number** 302554069428**Result** ✗ Failed**Fail** Offside Headlamp aim too low (1.8)**MOT #4** 2008-09-18 11:26**MOT test number** 531902468224**Result** ✓ Passed**MOT #3** 2008-09-18 10:12**MOT test number** 570632068212**Result** ✗ Failed**Fail** Offside Headlamp aim too low (1.8)**MOT #2** 2007-09-06 10:20**MOT test number** 583279147264**Result** ✗ Failed**Pass with rectification** Windscreen has a sticker or other obstruction encroaching by more than 10mm within zone 'A' (8.3.1b)**MOT #1** 2007-09-06 10:20**MOT test number** 363659847281**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
1 February 2025

Tax status	Valid until 1 September
Days left	125
MOT expiry date	1 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 WF54VHK
Plate since	2019-09-28
Current registration	 WF54VHK
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2004-09-30
Last registration	2024-01-29
Complete history	See info



Registration #1	2004-09-30	27 mi
Registration #2	2007-09-06	10.494 mi
Registration #3	2008-09-18	12.524 mi
Registration #4	2008-09-18	12.524 mi
Registration #5	2009-09-21	14.365 mi
Registration #6	2009-09-22	14.368 mi
Registration #7	2010-09-22	15.889 mi
Registration #8	2011-09-20	18.493 mi
Registration #9	2011-09-20	18.493 mi
Registration #10	2012-09-20	20.113 mi
Registration #11	2012-09-20	20.113 mi
Registration #12	2013-09-19	21.140 mi
Registration #13	2014-09-24	22.447 mi
Registration #14	2015-09-20	23.777 mi
Registration #15	2016-09-20	25.113 mi
Registration #16	2017-09-20	26.447 mi
Registration #17	2018-09-20	27.777 mi
Registration #18	2019-09-20	29.113 mi
Registration #19	2020-09-20	30.447 mi
Registration #20	2021-09-20	31.777 mi
Registration #21	2022-09-20	33.113 mi
Registration #22	2023-09-20	34.447 mi
Registration #23	2024-01-29	35.777 mi
Registration #24	2024-01-29	35.777 mi
Registration #25	2024-01-29	35.777 mi
Registration #26	2024-01-29	35.777 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1716 mm
Height	1422 mm
Length	4516 mm
Wheel base	2562 mm
Kerb weight	1255 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	B4183386762