



report date: 2024-03-28

General information

|                     |                   |
|---------------------|-------------------|
| Make                | MINI              |
| Model               | MINI COOPER S     |
| Colour              | Bronze            |
| Year of manufacture | 2013              |
| Top speed           | 130 mph           |
| 0 - 60 mph          | 7.9 seconds       |
| Gearbox             | 6 speed automatic |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 184 BHP             |
| Max. torque             | 240 Nm at 1.600 rpm |
| Engine capacity         | 1.598 cc            |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 29.7 mpg            |
| Consumption extra urban | 49.6 mpg            |
| Consumption combined    | 39.8 mpg            |
| CO2 emission            | 166 g/km            |
| CO2 label               | H                   |





Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-07-02                  |
| Pictures      | 66                          |
| Listing price | <a href="#">View report</a> |



source: yesauto.com



MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2025-03-10 |
| MOT pass rate      | 75 %       |
| MOT passed         | 9          |
| Failed MOT tests   | 3          |
| Total advice items | 21         |
| Total items failed | 6          |

|                  |  |
|------------------|--|
| MOT #12          | 2024-03-11 15:02                                   |
| MOT test number  | 138364195563                                       |
| Result           | ✓ Passed   |
| Next expiry date | 2025-03-10   |
| Advice           | Offside Front Coil spring corroded (5.3.1 (b) (i)) |
| Advice           | Oil leak, but not excessive (8.4.1 (a) (i))        |
| Advice           | Offside Rear Coil spring corroded (5.3.1 (b) (i))  |

|                 |  |
|-----------------|--|
| MOT #11         | 2022-07-11 09:15   |
| MOT test number | 364863456799   |
| Result          | ✓ Passed   |
| Advice          | Nearside Front Tyre worn close to legal limit/worn on edge 225/45/18 (5.2.3 (e)) |
| Advice          | Nearside Rear Tyre worn close to legal limit/worn on edge 225/45/18 (5.2.3 (e))  |
| Advice          | Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))                                 |
| Advice          | Offside Front Tyre worn close to legal limit/worn on edge 225/45/18 (5.2.3 (e))  |

**MOT #10** 2021-07-01 13:40**MOT test number** 531601634890**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #9** 2020-12-02 09:04**MOT test number** 888982670800**Result** ✓ Passed**MOT #8** 2019-11-28 09:35**MOT test number** 858669771692**Result** ✓ Passed**MOT #7** 2018-12-03 14:17**MOT test number** 144831011599**Result** ✓ Passed**Advice** Rear Child Seat fitted not allowing full inspection of adult belt both rear seats**Minor** Front Headlamp cleaning device inoperative (4.1.6 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge inner edge at 2mm (5.2.3 (e))**MOT #6** 2017-11-30 12:21**MOT test number** 472085231891**Result** ✓ Passed**Advice** Rear Trailer electrical socket (13 pin) not operating the trailer lamps as intended

**MOT #5** 2017-11-24 10:20**MOT test number** 189587279907**Result** ✗ Failed

**Fail** Nearside Inner Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**Fail** Trailer electrical socket (13 pin) not operating the trailer lamps as intended (1.9.4)

**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

**MOT #4** 2016-12-12 12:56**MOT test number** 733981312067**Result** ✓ Passed

**Advice** O/S/F tyre is badly worn on the edges

**Advice** Rear seats and belts not checked as child seats fitted

**MOT #3** 2016-12-12 11:43**MOT test number** 620898322620**Result** ✗ Failed

**Fail** Trailer electrical socket (13 pin) not operating the trailer lamps as intended (1.9.4)

**Advice** O/S/F tyre is badly worn on the edges

**Advice** Rear seats and belts not checked as child seats fitted

**MOT #2** 2015-12-21 12:00**MOT test number** 845820702547**Result** ✓ Passed

**Advice** Parking brake lever has little reserve travel (3.1.6b)

**Advice** O/S/F tyre is worn smooth on the inside edge



MOT #1 2015-12-21 12:00

MOT test number 269567513556

Result ✗ Failed

**Advice** O/S/F tyre is worn smooth on the inside edge

**Pass with rectification** Offside Headlamp aim too high (1.8)

**Pass with rectification** Nearside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**Advice** Parking brake lever has little reserve travel (3.1.6b)



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 July 2024

✓  
**MOT**  
  
Expires:  
10 March 2025

|                  |                                 |
|------------------|---------------------------------|
| Tax status       | Valid until 1 July              |
| Days left        | 63                              |
| MOT expiry date  | 10 March 2025                   |
| Full MOT history | <a href="#">See MOT history</a> |

Tax calculation

|   |            |
|---|------------|
| Vehicle class                           | 48         |
| Band                                    | H          |
| Single payment (12 months)              | £ 290,00,- |
| Single six month payment                | £ 159,50,- |
| Total payable by 12 monthly instalments | £ 304,50,- |



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |       |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this MINI had different number plates.

|                      |                |
|----------------------|----------------|
| Number of plates     | 1              |
| Current registration | <b>LB62JWX</b> |
| Plate since          | 2019-09-28     |
| Current registration | <b>LB62JWX</b> |
| Plate since          | 2019-09-28     |

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

|                   |          |          |
|-------------------|----------|----------|
| Finance company   | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type    | REDACTED | REDACTED |
| Agreement term    | REDACTED | REDACTED |
| Agreement number  | REDACTED | REDACTED |
| Contact info      | REDACTED | REDACTED |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 14                       |
| First mileage registration | 2013-01-16               |
| Last registration          | 2024-03-11               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2013-01-16 | 29 mi     |
| Registration #2  | 2015-12-21 | 17.332 mi |
| Registration #3  | 2015-12-21 | 17.332 mi |
| Registration #4  | 2016-12-12 | 20.751 mi |
| Registration #5  | 2016-12-12 | 20.751 mi |
| Registration #6  | 2017-11-24 | 28.301 mi |
| Registration #7  | 2017-11-30 | 28.782 mi |
| Registration #8  | 2019-05-29 | 35.277 mi |
| Registration #9  | 2019-05-29 | 35.277 mi |
| Registration #10 | 2019-05-29 | 35.277 mi |
| Registration #11 | 2019-05-29 | 35.277 mi |
| Registration #12 | 2019-05-29 | 35.277 mi |
| Registration #13 | 2019-05-29 | 35.277 mi |
| Registration #14 | 2019-05-29 | 35.277 mi |

More info >



Car features

The MINI factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

|                |                                 |
|----------------|---------------------------------|
| NCAP rating    | ★★★★★                           |
| Adult          | 84%                             |
| Children       | 83%                             |
| Pedestrian     | 63%                             |
| Safety systems | 71%                             |
| Overall rating | 78%                             |
| Video          | <a href="#">see crash video</a> |



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1789 mm |
| Height              | 1561 mm |
| Length              | 4110 mm |
| Wheel base          | 2595 mm |
| Kerb weight         | 1335 kg |
| Max. allowed weight | 1845 kg |

Additional information

|                    |                       |
|--------------------|-----------------------|
| Fuel tank capacity | 47 l                  |
| Fuel delivery      | Multi-Point Injection |
| Number of doors    | 5                     |
| Number of seats    | 5                     |

|                 |          |
|-----------------|----------|
| Number of axles | 2        |
| Engine number   | B193J284 |