



report date: 2024-03-29

General information

Make	VOLVO
Model	S60 D5 R-DESIGN LUX
Colour	Red
Year of manufacture	2013
Top speed	143 mph
0 - 60 mph	6.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	215 BHP
Max. torque	420 Nm at 3.250 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 2

Date	2021-07-25
Pictures	93
Listing price	View report



source: yesauto.com

Entry 1

Date	2021-07-22
Pictures	49
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-18
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	13
Total items failed	1

MOT #9	2023-07-06 10:17
MOT test number	137176428553
Result	✓ Passed
Next expiry date	2024-07-18

MOT #8	2022-07-19 10:31
MOT test number	183749059604
Result	✓ Passed

MOT #7	2021-07-19 15:34
MOT test number	401553552804
Result	✓ Passed

MOT #6	2020-09-04 09:31
MOT test number	493242091260
Result	✓ Passed

MOT #5	2019-09-30 08:40
MOT test number	734852308891
Result	✓ Passed
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #4** 2018-09-18 10:55**MOT test number** 844168271021**Result** ✓ Passed**MOT #3** 2017-09-26 12:13**MOT test number** 308858496443**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #2 2017-09-25 14:07**MOT test number** 915709761658**Result** ✗ Failed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #1 2016-09-01 15:07**MOT test number** 679731584532**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
18 July 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	18 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-09-27
Last registration	2023-07-06
Complete history	See info



Registration #1	2013-09-27	11 mi
Registration #2	2016-09-01	40.341 mi
Registration #3	2017-09-25	54.375 mi
Registration #4	2017-09-26	54.386 mi
Registration #5	2018-09-18	68.712 mi
Registration #6	2019-09-30	74.941 mi
Registration #7	2019-09-30	75.277 mi
Registration #8	2019-09-30	75.277 mi
Registration #9	2019-09-30	75.277 mi
Registration #10	2019-09-30	75.277 mi
Registration #11	2019-09-30	75.277 mi
Registration #12	2019-09-30	75.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4628 mm
Wheel base	2776 mm
Kerb weight	1634 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number	1259023
---------------	---------