



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN FSI S 7 STR
Colour	Blue
Year of manufacture	2003
Top speed	111 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	148 Nm at 3.800 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.7 mpg
Consumption extra urban	43.5 mpg
Consumption combined	34.9 mpg
CO2 emission	180 g/km
CO2 label	I





MOT history

MOT expiry date	2020-09-15
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	27
Total items failed	8

MOT #17 2019-09-12 10:35

MOT test number 842698837045

Result ✓ Passed

Next expiry date 2020-09-15

- Advice** Oil leak
- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #16 2018-09-11 08:53

MOT test number 566906544812

Result ✓ Passed

MOT #15 2017-09-16 05:32

MOT test number 879031462477

Result ✓ Passed

MOT #14 2016-09-14 13:42

MOT test number 887438532167

Result ✓ Passed

- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #13** 2015-09-15 09:36**MOT test number** 367117665219**Result** ✓ Passed**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #12** 2014-08-27 12:26**MOT test number** 845389734229**Result** ✓ Passed**MOT #11** 2014-08-27 11:40**MOT test number** 616049634298**Result** ✗ Failed**Fail** Front Exhaust system not adequately supported (7.1.1)**MOT #10** 2013-09-02 15:55**MOT test number** 458075943209**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Offside rear tyre perished**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #9** 2013-09-02 10:47**MOT test number** 516115143276**Result** ✗ Failed

Fail Offside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

Notice Offside rear tyre perished

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Nearside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #8 2012-09-07 11:29**MOT test number** 356711152478**Result** ✓ Passed

Notice Both front tyres perishing on outer walls

MOT #7 2011-08-30 09:19**MOT test number** 369432341412**Result** ✓ Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

MOT #6 2010-08-17 17:30**MOT test number** 264159320211**Result** ✓ Passed

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Notice Child seat fitted not allowing full inspection of adult belt

**MOT #5** 2010-08-17 10:09**MOT test number** 540089020242**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Rear Stop lamp not working (1.2.1b)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Rear Rear position lamp(s) not working (1.1.A.3b)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Rear registration plate deteriorated (6.3.1d)**MOT #4** 2009-09-02 11:57**MOT test number** 703415449227**Result** ✓ Passed**Notice** Offside front tyre worn on inner edge**Notice** Offside rear seat belt not tested (child seat fitted)**MOT #3** 2008-09-11 17:22**MOT test number** 660635258223**Result** ✓ Passed**MOT #2** 2007-09-04 11:11**MOT test number** 922367347230**Result** ✓ Passed



MOT #1	2006-09-11 12:06
MOT test number	520494256267
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✕
Untaxed

Tax expired:
20 September 2020

✕
MOT

Expired:
15 September 2020

Tax status	Expired at 20 September
Days left	1317 days too late
MOT expiry date	15 September 2020
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 GJ53UJE
Plate since	2020-03-28
Current registration	 GJ53UJE
Plate since	2020-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2003-09-10
Last registration	2019-09-12
Complete history	See info



Registration #1	2003-09-10	19 mi
Registration #2	2006-09-11	19.130 mi
Registration #3	2007-09-04	25.820 mi
Registration #4	2008-09-11	31.726 mi
Registration #5	2009-09-02	40.060 mi
Registration #6	2010-08-17	46.129 mi
Registration #7	2010-08-17	46.129 mi
Registration #8	2011-08-30	52.047 mi
Registration #9	2012-09-07	56.923 mi
Registration #10	2013-09-02	61.800 mi
Registration #11	2014-09-02	66.677 mi
Registration #12	2015-09-02	71.554 mi
Registration #13	2016-09-02	76.431 mi
Registration #14	2017-09-02	81.308 mi
Registration #15	2018-09-02	86.185 mi
Registration #16	2019-09-12	91.062 mi
Registration #17	2020-09-02	95.939 mi
Registration #18	2021-09-02	100.816 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4407 mm
Wheel base	2677 mm

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Engine number	BAG 011877