





General information

Make	MINI
Model	MINI COOPER D ALL4
Colour	Black
Year of manufacture	2013
Top speed	109 mph
0 - 60 mph	11.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	158 g/km
CO2 label	G





Internet history

Entry 1

Date Pictures 2021-07-29

Listing price

View report

12







source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-31
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	20
Total items failed	5

MOT #13	2023-08-18 10:26	
MOT test number	606749894290	
Result	✓ Passed	
Next expiry date	2024-08-31	
Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))		

MOT #12		2022-08-26 10:18
MOT test	number	507107344861
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor	Rear Registration plate lamp inoperative in the case of multiple lamps or ligh	nt sources (4.7.1 (b) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14	(a) (ii))





MOT #11		2022-08-26 09:12	
MOT test	number	626962162914	
Result		🗙 Failed	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.1	4 (a) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice	Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Fail Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))			
Minor Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))			
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))			

MOT #102021-09-01 12:03MOT test number953954533677ResultPassedMinor
(b) (i))Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1AdviceEngine oil level below minimumAdviceOffside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

МОТ #9	2020-12-01 09:18
MOT test number	718504961238
Result	✓ Passed
MOT #8	2019-11-09 10:04
MOT test number	678249652850

Result

Passed





MOT #7		2019-11-09 10:04
MOT test number		459798930536
Result		🗙 Failed
Pass with rectification	Nearside Headlamp aim projected beam image is obviously inc	correct (4.1.2 (c))
МОТ #6		2018-11-16 16:38
MOT test number		316051356594
Result		✓ Passed
MOT #5		2017-11-17 16:54
MOT test number		358804006596
Result		✓ Passed
Advice Nearside Rear Outer Brake pad(s) wearing thin (3.5.1g)		
Advice Offside Headlamp damaged but light output not reduced Fixing broken (1.7.5a)		

MOT #4	2017-11-15 12:13
MOT test number	339645393689
Result	🗙 Failed
Advice Nearside Rear Outer Brake pad(s) wearing thin (3.5.1g)	
Advice Offside Headlamp damaged but light output not reduced Fixing brok	ken (1.7.5a)
Fail Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)	

МОТ #3	2016-11-07 15:37
MOT test number	998249920213
Result	✓ Passed

MOT #2	2016-07-08 11:17
MOT test number	540606919172
Result	✓ Passed





MOT #1		2016-07-08 11:17
MOT test number		554383000161
Result		🗙 Failed
Pass with rectification	Nearside Stop lamp not working (1.2.1b)	



Tax & MOT check

✓ Taxed Tax due: 1 September 2024	✓ MOT Expires: 31 August 2024
Tax status	Valid until 1 September
Days left	125
MOT expiry date	31 August 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	E.S.
Туре	

Extra MINI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-07-16
Last registration	2023-08-18
Complete history	See info



Registration #1	2013-07-16	24 mi
Registration #2	2016-07-08	36.053 mi
Registration #3	2016-07-08	36.053 mi
Registration #4	2016-11-07	38.314 mi
Registration #5	2017-11-15	46.906 mi
Registration #6	2017-11-17	46.907 mi
Registration #7	2018-11-16	55.081 mi
Registration #8	2019-11-09	63.388 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 mi
Registration #15		11.777 mi





Car features

S0225	Air conditioning
\$0295	
S0482	
\$0501	
\$0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight	
Width	1789 mm
Height	1561 mm
Length	4097 mm
Wheel base	2595 mm
Max. allowed weight	1875 kg
Additional information	
Fuel tank capacity	47
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 13/13

Engine number

72778439