



report date: 2024-03-28

General information

| | |
|---------------------|-------------------|
| Make | CITROEN |
| Model | DS3 DSTYLE TECHNO |
| Colour | Silver |
| Year of manufacture | 2015 |
| Top speed | 130 mph |
| 0 - 60 mph | 7.3 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 156 BHP |
| Max. torque | 240 Nm at 1.750 rpm |
| Engine capacity | 1.598 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 34.5 mpg |
| Consumption extra urban | 60.1 mpg |
| Consumption combined | 47.1 mpg |
| CO2 emission | 135 g/km |
| CO2 label | E |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-09-04 |
| Pictures | 12 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-04-24 |
| MOT pass rate | 54 % |
| MOT passed | 7 |
| Failed MOT tests | 6 |
| Total advice items | 31 |
| Total items failed | 14 |

MOT #13 2024-04-25 14:05

MOT test number 169312279422

Result ✓ Passed

Next expiry date 2025-04-24

Advice Brake disc worn, pitted or scored, but not seriously weakened all (1.1.14 (a) (ii))**Minor** Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #12 2024-04-23 15:17

MOT test number 242392931393

Result ✗ Failed**Advice** Brake disc worn, pitted or scored, but not seriously weakened all (1.1.14 (a) (ii))**Minor** Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Front Tyre tread depth below requirements of 1.6mm both (5.2.3 (e))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #11** 2023-01-04 12:14**MOT test number** 711086030543**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Items removed from driver's view prior to test

MOT #10 2023-01-04 09:59**MOT test number** 356291478487**Result** ✗ Failed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Items removed from driver's view prior to test
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #9 2022-01-06 13:17**MOT test number** 735486780309**Result** ✓ Passed

**MOT #8** 2022-01-05 15:35**MOT test number** 410265163534**Result** ✗ Failed**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Exhaust rear bracket broken.**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Oil leaking excessively from engine (8.4.1 (a) (i))**MOT #7** 2020-12-12 08:26**MOT test number** 730366549508**Result** ✓ Passed**Advice** Exhaust support brackett broken**Advice** Damage on offside front wheel**MOT #6** 2020-12-04 16:58**MOT test number** 367763843247**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Advice** Damage on offside front wheel**Advice** Exhaust support brackett broken

**MOT #5** 2019-10-16 10:35**MOT test number** 924035644009**Result** ✓ Passed**Advice** Rear Tyre slightly damaged/cracking or perishing nearside and offside (5.2.3 (d) (ii))**Advice** Nearside front tyre 3 mm**Advice** Rear Exhaust mounting defective (6.1.2 (a))**MOT #4** 2019-10-16 10:35**MOT test number** 438708051772**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Rear Exhaust mounting defective (6.1.2 (a))**Advice** Rear Tyre slightly damaged/cracking or perishing nearside and offside (5.2.3 (d) (ii))**Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))**Advice** Nearside front tyre 3 mm**MOT #3** 2018-10-18 14:53**MOT test number** 313845369390**Result** ✓ Passed**MOT #2** 2018-03-13 14:16**MOT test number** 809381027655**Result** ✓ Passed**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #12018-03-13 14:16

MOT test number641083467779

Result

Failed

- Pass with rectification

Offside Front Windscreen has a sticker or other obstruction encroaching by more than 10mm within zone 'A' (8.3.1b)
- Advice

Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Pass with rectification

Central Front Windscreen has a sticker or other obstruction encroaching by more than 10mm within zone 'A' (8.3.1b)
- Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice

Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
24 April 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 April |
| Days left | 336 |
| MOT expiry date | 24 April 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 48 |
| Band | E |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 15,200 |
| Auction value | £ 15,200 |
| Average private trade value | £ 15,200 |

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this CITROEN had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2024-03-28 |
| Current registration | XXXXXX |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 15 |
| First mileage registration | 2015-03-24 |
| Last registration | 2024-04-25 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2015-03-24 | 17 mi |
| Registration #2 | 2018-03-13 | 25.085 mi |
| Registration #3 | 2018-03-13 | 25.085 mi |
| Registration #4 | 2018-10-18 | 29.050 mi |
| Registration #5 | 2019-10-16 | 35.033 mi |
| Registration #6 | 2019-10-16 | 35.033 mi |
| Registration #7 | 2020-12-04 | 37.366 mi |
| Registration #8 | 2020-12-12 | 37.369 mi |
| Registration #9 | 2020-12-12 | 37.369 mi |
| Registration #10 | 2020-12-12 | 37.369 mi |
| Registration #11 | 2020-12-12 | 37.369 mi |
| Registration #12 | 2020-12-12 | 37.369 mi |
| Registration #13 | 2020-12-12 | 37.369 mi |
| Registration #14 | 2020-12-12 | 37.369 mi |
| Registration #15 | 2020-12-12 | 37.369 mi |

More info >



Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 87% |
| Children | 71% |
| Pedestrian | 35% |
| Safety systems | 83% |
| Overall rating | 73% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1715 mm |
| Height | 1483 mm |
| Length | 3948 mm |
| Wheel base | 2464 mm |
| Kerb weight | 1090 kg |
| Max. allowed weight | 1590 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 48 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 3 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | FJBS2122892 |