





report date: 2024-03-29

General information

Make	FORD
Model	TRANSIT 260 LR P/V
Colour	White
Year of manufacture	2009
Gearbox	5 speed Manual

Engine & fuel consumption

Power	84 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel



CarCheck.co.uk page 1/12



report date: 2024-03-29

	_			
MO	1	hic	to	r\/
				ıv.
				. ,

MOT expiry date	2024-12-23
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	6
Total items failed	10

MOT #16	2023-12-13 13:07
MOT test number	966426751598
Result	✓ Passed
Next expiry date	2024-12-23

MOT #15	2022-12-15 09:54
MOT test number	370338852528
Result	✓ Passed

MOT #14	2021-12-01 13:57
MOT test number	604660864493
Result	✓ Passed
Advice Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))	

MOT #13	2020-12-08 09:38
MOT test number	625939404644
Result	✓ Passed
Advice Nearside Front Inner steering knuckle joint slight play	

MOT #12	2019-12-04 09:31
MOT test number	212047985758
Result	✓ Passed

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT #11	2019-12-03 10:01
MOT test number	723520561272
Result	× Failed
Fail Central Rear Upper Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice Engine slow crancking	
Fail Nearside Rear Wheel bearing play so excessive it is likely to break up (5.1.3 (a) (ii))	
Fail Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))	

Fail Exhaust emissions exceed manufacturer's specified limit (8	s.2.2.2 (a))
MOT #10	2018-11-29 10:58
MOT test number	205211592380
Result	✓ Passed
MOT #9	2017-12-13 09:39
MOT test number	810331088417
Result	✓ Passed
MOT #8	2016-11-28 10:29
MOT test number	823188708241
Result	✓ Passed
MOT #7	2016-11-28 10:29
MOT test number	869565975677
B 11	

MOT test number	869565975677
Result	X Failed
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Pass with rectification	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Pass with rectification	Central Rear Upper Stop lamp not working (1.2.1b)
Pass with rectification	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #6 2015-12-08 13:59

MOT test number 168545577497

Result ✓ Passed

MOT #5 2014-12-01 10:35

MOT test number 447475834482

Result ✓ Passed

MOT #4 2014-12-01 10:35

MOT test number 437595534407

Result X Failed

Pass with rectification

Offside Rear fog lamp has less than 50% of the light sources illuminating

(1.3.2b)

Pass with rectification Centre Re

Centre Rear Stop lamp not working (1.2.1b)

MOT #3 2013-12-05 15:55

MOT test number 468439633473

Result \(\sqrt{Passed} \)

Notice Wear discs

MOT #2 2012-12-20 12:44

MOT test number 725705252377

Advice Nearside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #1 2012-12-20 12:44

MOT test number 865745952306

Result X Failed

Pass with rectification

Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)

Pass with rectification

Centre Stop lamp not working (1.2.1b)

Advice

Nearside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

CarCheck.co.uk page 5/12



report date: 2024-03-29

23 December 2024





MOT expiry date **Full MOT history** See MOT history

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history

Owner mistory	
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	NK UK
Plate since	
Current registration	NE NE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



YE590GD

report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-12-23
Last registration	2023-12-13
Complete history	See info



Registration #1	2009-12-23	21 mi
Registration #2	2012-12-20	22.328 mi
Registration #3	2013-12-05	31.802 mi
Registration #4	2014-12-01	40.038 mi
Registration #5	2015-12-08	50.634 mi
Registration #6	2016-11-28	59.937 mi
Registration #7	2016-11-28	59.937 mi
Registration #8	2017-12-13	68.941 mi
Registration #9		11.777 es
Registration #10		71.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		9.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

50225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Dimensions & weight

Width	2360 mm
Height	1989 mm
Length	4863 mm
Kerb weight	1699 kg
Max. allowed weight	2600 kg

Additional information

Fuel tank capacity	80
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	9R16420

CarCheck.co.uk page 12/12