



TOYOTA



report date: 2024-03-28

General information

| | |
|---------------------|-----------------------|
| Make | TOYOTA |
| Model | COROLLA VERSO D-4D T2 |
| Colour | Grey |
| Year of manufacture | - |
| Top speed | 122 mph |
| 0 - 60 mph | 9.4 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 134 BHP |
| Max. torque | 310 Nm at 2.800 rpm |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 35.3 mpg |
| Consumption extra urban | 53.3 mpg |
| Consumption combined | 44.8 mpg |





LABEL UNKNOWN



Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-09-15 |
| Pictures | 23 |
| Listing price | View report |



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT #18 2021-03-02 16:25**MOT test number** 651411256698**Result** ✓ Passed**Next expiry date** 2022-03-01

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material to flexi (1.1.11 (c))
- Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material to flexi (1.1.11 (c))

MOT #17 2021-03-02 16:25**MOT test number** 976024297141**Result** ✗ Failed

- Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material to flexi (1.1.11 (c))
- Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material to flexi (1.1.11 (c))

**MOT #16**

2020-02-20 13:57

MOT test number

429092001421

Result

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside doors damaged-no sharp edges
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material at flexi (1.1.11 (c))
- Advice** Nearside Front play in top strut mount.
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material at flexi (1.1.11 (c))

MOT #15

2020-02-18 12:14

MOT test number

226387688624

Result

✗ Failed

- Fail** Front Registration plate inscription illegible water damage around both Y letters (0.1 (b))
- Advice** Offside doors damaged-no sharp edges
- Fail** Exhaust emissions exceed level of metered smoke for a turbo charged engine (8.2.2.2 (b))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material at flexi (1.1.11 (c))
- Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front play in top strut mount.
- Fail** Fuel tank leaking (6.1.3 (b) (i))
- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material at flexi (1.1.11 (c))
- Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))

**MOT #14** 2019-04-17 10:46**MOT test number** 407031636381**Result** ✓ Passed**MOT #13** 2018-04-04 08:49**MOT test number** 995353662958**Result** ✓ Passed**MOT #12** 2017-03-30 09:23**MOT test number** 474272970587**Result** ✓ Passed**MOT #11** 2016-03-30 09:07**MOT test number** 512751502417**Result** ✓ Passed**Advice** Registration plate deteriorated but not likely to be misread both (6.3.1d)**Advice** Brake pad(s) wearing thin front and rear (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #10** 2015-04-01 10:52**MOT test number** 935561495098**Result** ✓ Passed**MOT #9** 2014-04-01 14:13**MOT test number** 167961194413**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #8** 2013-04-04 10:47**MOT test number** 839214793091**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2012-04-18 13:31**MOT test number** 579429202101**Result** ✓ Passed**MOT #6** 2012-04-18 09:30**MOT test number** 656659202186**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #5** 2011-04-08 11:28**MOT test number** 216128791030**Result** ✓ Passed**MOT #4** 2010-04-01 10:05**MOT test number** 262051890016**Result** ✓ Passed**MOT #3** 2010-04-01 10:05**MOT test number** 962211890004**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #2** 2009-04-09 09:58**MOT test number** 620789599027**Result** ✓ Passed



| | |
|-------------------------|--------------------------------------|
| MOT #1 | 2009-04-09 09:58 |
| MOT test number | 221929099063 |
| Result | ✗ Failed |
| Pass with rectification | Upper Stop lamp not working (1.2.1b) |



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | GY06YKD |
| Plate since | 2019-09-29 |
| Current registration | GY06YKD |
| Plate since | 2019-09-29 |

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 17 |
| First mileage registration | 2006-04-15 |
| Last registration | 2021-03-02 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2006-04-15 | 24 mi |
| Registration #2 | 2009-04-09 | 20.243 mi |
| Registration #3 | 2010-04-01 | 28.533 mi |
| Registration #4 | 2011-04-08 | 37.462 mi |
| Registration #5 | 2012-04-18 | 45.854 mi |
| Registration #6 | 2013-04-04 | 57.487 mi |
| Registration #7 | 2014-04-01 | 64.351 mi |
| Registration #8 | 2015-04-01 | 73.328 mi |
| Registration #9 | 2016-03-30 | 81.794 mi |
| Registration #10 | 2016-03-30 | 81.794 mi |
| Registration #11 | 2016-03-30 | 81.794 mi |
| Registration #12 | 2016-03-30 | 81.794 mi |
| Registration #13 | 2016-03-30 | 81.794 mi |
| Registration #14 | 2016-03-30 | 81.794 mi |
| Registration #15 | 2016-03-30 | 81.794 mi |
| Registration #16 | 2016-03-30 | 81.794 mi |
| Registration #17 | 2016-03-30 | 81.794 mi |

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1770 mm |
| Height | 1660 mm |
| Length | 4360 mm |
| Wheel base | 2750 mm |
| Kerb weight | 1495 kg |
| Max. allowed weight | 2160 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 60 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 7 |

| | |
|------------------------|------------|
| Number of axles | 2 |
| Engine number | 2AD5091090 |