



report date: 2024-03-29

General information

Make	VOLVO
Model	S40 SE D S40
Colour	Blue
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	11.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	67.3 mpg
Consumption combined	57.7 mpg
CO2 emission	129 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-05-26
Pictures	13
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-09-12
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	12
Total items failed	7

MOT #15	2023-09-11 10:40
MOT test number	367375804706
Result	✓ Passed
Next expiry date	2024-09-12

MOT #14	2022-09-07 15:17
MOT test number	266985141761
Result	✓ Passed
Minor	Battery insecure but not likely to fall from carrier (4.13 (a) (i))

MOT #13	2022-09-07 11:18
MOT test number	964265173528
Result	✗ Failed
Minor	Battery insecure but not likely to fall from carrier (4.13 (a) (i))
Fail	Horn not working (7.7 (a))

MOT #12	2021-09-13 15:15
MOT test number	443363684504
Result	✓ Passed
Advice	Front Brake disc worn, but not excessively both side (1.1.14 (a) (i))

**MOT #11** 2020-09-03 12:40**MOT test number** 488386958302**Result** ✓ Passed

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #10 2019-09-06 08:03**MOT test number** 671797438006**Result** ✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Nail in tyre

MOT #9 2019-07-18 16:07**MOT test number** 167998961352**Result** ✗ Failed

Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #8 2017-09-22 12:35**MOT test number** 417717546350**Result** ✓ Passed

**MOT #7** 2017-09-20 09:26**MOT test number** 975569127762**Result** ✗ Failed**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Advice** Offside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)**Fail** Offside Front Inner Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Nearside Front Inner Tyre worn close to the legal limit Also has side wall damaged (4.1.E.1)**MOT #6** 2017-01-25 10:30**MOT test number** 371762779319**Result** ✓ Passed**MOT #5** 2016-01-12 09:46**MOT test number** 962984089755**Result** ✓ Passed**MOT #4** 2016-01-12 09:46**MOT test number** 679210655843**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #3** 2015-01-23 14:24**MOT test number** 177113225087**Result** ✓ Passed**MOT #2** 2014-01-15 09:43**MOT test number** 715635614031**Result** ✓ Passed



MOT #1	2013-01-02 09:50
MOT test number	835122803062
Result	✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	AX59AZJ
Plate since	2019-09-29
Current registration	AX59AZJ
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-01-25
Last registration	2023-09-11
Complete history	See info



Registration #1	2010-01-25	15 mi
Registration #2	2013-01-02	27.898 mi
Registration #3	2014-01-15	44.960 mi
Registration #4	2015-01-23	53.670 mi
Registration #5	2016-01-12	68.851 mi
Registration #6	2016-01-12	68.851 mi
Registration #7	2017-01-25	80.487 mi
Registration #8	2017-09-20	84.071 mi
Registration #9	2017-09-22	84.081 mi
Registration #10	2018-01-25	84.081 mi
Registration #11	2018-01-25	84.081 mi
Registration #12	2018-01-25	84.081 mi
Registration #13	2018-01-25	84.081 mi
Registration #14	2018-01-25	84.081 mi
Registration #15	2018-01-25	84.081 mi
Registration #16	2018-01-25	84.081 mi
Registration #17	2018-01-25	84.081 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4468 mm
Wheel base	2640 mm
Kerb weight	1403 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	453565