





report date: 2024-03-29

# General information

Make	VOLKSWAGEN
Model	TIGUAN SE TDI 4MOTION
Colour	Silver
Year of manufacture	2010
Top speed	116 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	140 BHP	
Max. torque	320 Nm at 1.750 rpm	
Engine capacity	1.968 сс	
Cylinders	4	
Fuel type	Diesel	
Consumption city	30.1 mpg	
Consumption extra urban	47.9 mpg	
Consumption combined	39.2 mpg	
CO2 emission	167 g/km	
CO2 label	Н	



CarCheck.co.uk page 1/12



MOT history

MOT expiry date	2024-06-27
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	17
Total items failed	10

MOT #14		2023-06-28 15:14
MOT test	number	951796124594
Result		✓ Passed
Next expiry date 2024-06-27		
Advice Supplementary restraint system warning lamp does not illuminate intermittent fault (7.1.6 (a))		
Advice (a))	Nearside Front Direction indicator slightly discoloured mirror indicato	or not bright (dim led) (4.4.3

MOT #13		2022-04-05 09:41
MOT test	number	827415330287
Result		✓ Passed
Advice Rear Lower Suspension arm corroded but not seriously weakened both (5.3.3 (b) (i))		
Advice	Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #12	2021-03-24 16:47
MOT test number	739467034528
Result	✓ Passed

CarCheck.co.uk page 2/12



**MOT #11** 2021-03-19 14:14

MOT test number 108254771634

Result X Failed

Fail Nearside Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Fail Nearside Side repeater not working (4.4.1 (a) (ii))

**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

Fail Offside Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Fail Position lamp not working (4.2.1 (a) (ii))

MOT #10 2020-02-01 12:09

**MOT test number** 425571849120

**Result** 
✓ Passed

**Advice** Underneath trays fitted at time of test

MOT #9 2019-01-21 10:08

**MOT test number** 869055962893

**Result** 
✓ Passed

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #8 2018-01-20 11:36

**MOT test number** 637565917171

**Result** ✓ Passed

CarCheck.co.uk page 3/12



**MOT #7** 2018-01-20 10:20

**MOT test number** 471124819562

**Result** X Failed

Fail Offside Rear coil spring broken (2.4.C.1a)

**Fail** Nearside Rear coil spring broken (2.4.C.1a)

**MOT #6** 2017-01-16 11:50

**MOT test number** 419779230433

**Result** ✓ Passed

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2017-01-16 09:36

**MOT test number** 429487732213

**Result** X Failed

**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Fail** Registration plate lamp not working (1.1.C.1d)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Fail** Offside Side repeater not working (1.4.A.2c)

MOT #4 2016-01-22 10:01

**MOT test number** 167176905794

**Result** 
✓ Passed

**Advice** Chlid seat fitted to rear

**Advice** Tested wet

CarCheck.co.uk page 4/12



Notice

YT10FGK report date: 2024-03-29

MOT #3 2015-01-24 09:01 **MOT test number** 859294525098 Result ✓ Passed 2014-01-18 09:26 MOT #2 **MOT** test number 858798114036 Result ✓ Passed MOT #1 2013-02-01 12:34 **MOT test number** 265122833097 Result ✓ Passed **Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1) **Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Child seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 5/12



# Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	27 June 2024
Full MOT history	See MOT history

# Tax calculation

Vehicle class	49
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 6/12



# Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1

Date


Category

**Type** 

Damage 2

Date

Type Type



#### Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Downere.	
*********	
***************************************	
***************************************	
*********	
***************************************	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	
Current registration	THE UK
Plate since	
Current registration	NK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



#### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-03-25
Last registration	2023-06-28
Complete history	See info



Registration #1	2010-03-25	22 mi
Registration #2	2013-02-01	22.923 mi
Registration #3	2014-01-18	30.687 mi
Registration #4	2015-01-24	47.258 mi
Registration #5	2016-01-22	65.080 mi
Registration #6	2017-01-16	82.163 mi
Registration #7	2017-01-16	82.163 mi
Registration #8	2018-01-20	97.419 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91,700 esi
Registration #12		11.777 es
Registration #13		91,700 esi
Registration #14		11.777 es
Registration #15		11.177 es

More info >

CarCheck.co.uk page 11/12



# Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	87%
Children	79%
Pedestrian	48%
Safety systems	71%
Overall rating	76%
Video	see crash video



# Dimensions & weight

Width	1809 mm
Height	1686 mm
Length	4427 mm
Wheel base	2604 mm
Kerb weight	1590 kg
Max. allowed weight	2240 kg

# Additional information

Fuel tank capacity	64 I
Fuel delivery	Direct Injection
Number of doors	5
CarChack co.uk	nago 12/12

CarCheck.co.uk page 12/12

Number of seats	5
Number of axles	2
Engine number	CBA 652186