



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES
Model	CLK CLK220 CDI SPORT
Colour	Silver
Year of manufacture	2007
Top speed	137 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	148 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	2.149 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.1 mpg
Consumption extra urban	54.3 mpg
Consumption combined	43.5 mpg
CO2 emission	183 g/km
CO2 label	I





Internet history

Entry 1

Date	2022-01-03
Pictures	0
Listing price	<a href="#">View report</a>

source: autotrader.co.uk



## MOT history

MOT expiry date	2024-10-12
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	35
Total items failed	0

MOT #16 2023-10-13 15:59

MOT test number 141666080127

Result ✓ Passed

Next expiry date 2024-10-12

- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #15** 2022-09-28 19:39**MOT test number** 950324611779**Result** ✓ Passed

- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #14** 2021-09-30 15:08**MOT test number** 766499834495**Result** ✓ Passed**MOT #13** 2021-09-23 13:46**MOT test number** 981637527794**Result** ✗ Failed

- MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #12** 2020-09-23 10:00**MOT test number** 813101492616**Result** ✓ Passed**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #11** 2019-09-30 13:02**MOT test number** 918636175985**Result** ✓ Passed**MOT #10** 2018-10-01 14:22**MOT test number** 644493944805**Result** ✓ Passed**MOT #9** 2018-09-24 15:01**MOT test number** 662902295502**Result** ✗ Failed**MAJOR** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MAJOR** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))**MOT #8** 2017-10-09 14:14**MOT test number** 830928006219**Result** ✓ Passed

**MOT #7** 2016-08-31 14:23**MOT test number** 694007826109**Result** ✓ Passed**MOT #6** 2015-08-27 14:43**MOT test number** 157166238694**Result** ✓ Passed**MOT #5** 2014-08-19 14:55**MOT test number** 138541334271**Result** ✓ Passed**MOT #4** 2013-08-29 15:48**MOT test number** 815811643205**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #3** 2012-09-04 11:00**MOT test number** 526978242272**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Notice** O/S/F Tyre wearing on edges**Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #2** 2011-08-25 15:59**MOT test number** 458617731206**Result** ✓ Passed



MOT #1	2010-09-06 12:53
MOT test number	450539540207
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
12 October 2024

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	337
<b>MOT expiry date</b>	12 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-





Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-09-27
Last registration	2023-10-13
Complete history	<a href="#">See info</a>



Registration #1	2007-09-27	10 mi
Registration #2	2010-09-06	23.383 mi
Registration #3	2011-08-25	30.410 mi
Registration #4	2012-09-04	38.832 mi
Registration #5	2013-08-29	46.359 mi
Registration #6	2014-08-19	53.366 mi
Registration #7	2015-08-27	62.208 mi
Registration #8	2016-08-31	69.009 mi
Registration #9	2017-10-09	71.564 mi
Registration #10	2018-09-20	75.377 mi
Registration #11	2019-09-20	75.377 mi
Registration #12	2020-09-20	75.377 mi
Registration #13	2021-09-20	75.377 mi
Registration #14	2022-09-20	75.377 mi
Registration #15	2023-09-20	75.377 mi
Registration #16	2024-09-20	75.377 mi
Registration #17	2025-09-20	75.377 mi
Registration #18	2026-09-20	75.377 mi

More info >



Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2715 mm
Kerb weight	1595 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	64696630591432