





report date: 2024-03-29

## General information

| Make                | LAND ROVER          |
|---------------------|---------------------|
| Model               | DEFENDER TD PICK UP |
| Colour              | Black               |
| Year of manufacture | 2012                |
| Top speed           | 90 mph              |
| 0 - 100 km/h        | 15.8 seconds        |
| Gearbox             | 6 speed Manual      |

## Engine & fuel consumption

| Power                   | 90 kW / 123 HP / 122 BHP |
|-------------------------|--------------------------|
| Max. torque             | 360 Nm at 2.000 rpm      |
| Engine capacity         | 2.198 cc                 |
| Cylinders               | 4                        |
| Fuel type               | Diesel                   |
| Consumption city        | 24.6 mpg                 |
| Consumption extra urban | 31.0 mpg                 |
| Consumption combined    | 28.3 mpg                 |
| CO2 emission            | 266 g/km                 |
| CO2 label               | M                        |



CarCheck.co.uk page 1/13



# Internet history

## Entry 1

Date 2022-06-12

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



# MOT history

| MOT expiry date    | 2024-08-22 |
|--------------------|------------|
| MOT pass rate      | 56 %       |
| MOT passed         | 9          |
| Failed MOT tests   | 7          |
| Total advice items | 15         |
| Total items failed | 11         |

| MOT #16  |  | 2023-08-23 09:16 |
|----------|--|------------------|
| MOT test | number   | 468909667324     |
| Result   |  | ✓ Passed         |
| Next exp | iry date   | 2024-08-22       |
| Minor    | Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) |                  |
| Advice   | Oil leak, but not excessive transfer box (8.4.1 (a) (i))                   |                  |
| Advice   | Offside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))    |                  |
| Advice   | Front swivel seals leaking   |                  |
| Advice   | Nearside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))   |                  |

| MOT #15         | 2022-08-22 16:32 |
|-----------------|------------------|
| MOT test number | 785806569721     |
| Result          | ✓ Passed         |

CarCheck.co.uk page 3/13



BJ62OXB

report date: 2024-03-29

MOT test number

676123493227

Result

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

Minor

Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Fail

Rear Shock absorbers has an excessively worn bush (5.3.2 (c))

Minor

Nearside Front Windscreen wiper blade defective (3.4 (b) (i))

**MOT #13** 2021-12-08 12:07 **MOT** test number 462128898172 Result Passed **MOT #12** 2021-12-08 12:07 **MOT** test number 674337300339 Result × Failed **Pass with rectification** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii)) Pass with rectification Nearside Rear Position lamp not working (4.2.1 (a) (ii))

MOT #11

MOT test number

365519943003

Result

Advice

Offside Front Tyre worn close to legal limit/worn on edge on the legal limit (5.2.3 (e))

CarCheck.co.uk page 4/13



**MOT #10** 2020-12-10 12:49

**MOT test number** 497206627836

**Result** X Failed

Pass with rectification Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge on the legal limit (5.2.3 (e))

Pass with rectification Registration plate lamp does not illuminate simultaneously with the position

lamps (4.7.2 (a))

**MOT #9** 2019-12-17 10:59

MOT test number 872806299762

**Result** 
✓ Passed

MOT #8 2019-01-17 12:42

**MOT test number** 873579817704

**Result** ✓ Passed

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #7 2019-01-16 11:51

MOT test number 703640570514

Result × Failed

Fail Horn not working (7.7 (a) (ii))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Front Position lamp not working both sides (4.2.1 (a))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6 2017-11-24 13:57

**MOT test number** 181978684147

Result \( \sqrt{Passed} \)

CarCheck.co.uk page 5/13



MOT #5

MOT test number

Result

Pass with rectification

Nearside Front position lamp(s) not working (1.1.A.3b)

MOT #4

MOT test number

Result

Advice Offside Front Inner Tyre worn close to the legal limit close at 1.95 mm (4.1.E.1)

MOT test number
777278090276

Result

Fail Offside Front Front position lamp(s) not working (1.1.A.3b)

Fail Nearside Front Inner Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Offside Front Inner Tyre worn close to the legal limit close at 1.95 mm (4.1.E.1)

 MOT #2
 2015-11-16 11:07

 MOT test number
 810884331600

 Result
 ✓ Passed

MOT #1

MOT test number

Failed

Pass with rectification

Offside Front Front position lamp(s) not working (1.1.A.3b)

CarCheck.co.uk page 6/13



## Tax & MOT check



| Tax status       | Valid until 1 September |
|------------------|-------------------------|
| Days left        | 124                     |
| MOT expiry date  | 22 August 2024          |
| Full MOT history | See MOT history         |

### Tax calculation

| Vehicle class             | 39         |
|---------------------------|------------|
| Standard rate (12 months) | £ 275,00,- |
| Standard rate (6 months)  | £ 151,25,- |

CarCheck.co.uk page 7/13



### Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

#### Damage 1


Date
Category
Type

Damage 2

Date

Category

**Type** 



#### Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



### Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

| e when miscory   |                  |
|--|------------------|
| For how long did the current and previous owner(s) have this LAND ROVER? How many of ROVER have? Check it in the premium report and see all owner registrations. Download to |                  |
| **************************************   |                  |
| ***************************************  |                  |
| ***************************************  |                  |
| *********  |                  |
|  |                  |
| ***************************************  |                  |
|  | More info >      |
| Plate changes  |                  |
| See in this check if this LAND ROVER had different number plates.  |                  |
| Number of plates   | ,                |
| Current registration   | UK UK            |
| Plate since  |                  |
| Current registration   | OK<br>SIN<br>SIN |
| Plate since  |                  |
|  | More info >      |

CarCheck.co.uk page 10/13



### Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 11/13



# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 18         |
| First mileage registration | 2012-11-26 |
| Last registration          | 2023-08-23 |
| Complete history           | See info   |



| Registration #1  | 2012-11-26 | 13 mi     |
|------------------|------------|-----------|
| Registration #2  | 2015-11-16 | 26.657 mi |
| Registration #3  | 2015-11-16 | 26.657 mi |
| Registration #4  | 2016-11-29 | 37.858 mi |
| Registration #5  | 2016-11-29 | 37.862 mi |
| Registration #6  | 2017-11-24 | 48.150 mi |
| Registration #7  | 2017-11-24 | 48.150 mi |
| Registration #8  | 2019-01-16 | 60.770 mi |
| Registration #9  | 2019-01-17 | 60.772 mi |
| Registration #10 |            | 71.777 es |
| Registration #11 |            | 11.777 es |
| Registration #12 |            | 71.777 es |
| Registration #13 |            | 11.777 es |
| Registration #14 |            | 11.777 es |
| Registration #15 |            | 11.777 es |
| Registration #16 |            | 11.777 es |
| Registration #17 |            | 11.777 es |
| Registration #18 |            | 11.777 au |

More info >

page 12/13 CarCheck.co.uk



## Dimensions & weight

| Width               | 1790 mm |
|---------------------|---------|
| Height              | 2000 mm |
| Length              | 3722 mm |
| Wheel base          | 2360 mm |
| Kerb weight         | 1738 kg |
| Max. allowed weight | 2505 kg |

## Additional information

| Fuel tank capacity | 60 I              |
|--------------------|-------------------|
| Fuel delivery      | Direct Injection  |
| Number of doors    | 2                 |
| Number of seats    | 2                 |
| Number of axles    | 2                 |
| Engine number      | 120517122408DT224 |

CarCheck.co.uk page 13/13