



Mercedes-Benz




report date: 2024-03-29

General information

Make	MERCEDES
Model	B-CLASS B200 SE
Colour	Silver
Year of manufacture	2006
Top speed	118 mph
0 - 60 mph	10.2 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	134 BHP
Max. torque	185 Nm at 4.000 rpm
Engine capacity	2.035 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.7 mpg
CO2 emission	175 g/km
CO2 label	H





Internet history

Entry 2


Date	2021-09-15
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-08-12
Pictures	42
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2025-03-23
MOT pass rate	65 %
MOT passed	17
Failed MOT tests	9
Total advice items	46
Total items failed	20

MOT #26 2024-02-24 10:09

MOT test number 512646822503

Result ✓ Passed

Next expiry date 2025-03-23

**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #25 2023-03-03 09:44

MOT test number 468334214155

Result ✓ Passed

**Minor** Offside Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #24 2022-03-18 09:51

MOT test number 885602180965

Result ✓ Passed

**MOT #23**

2022-03-16 11:26

**MOT test number**

745455730695

**Result**

✗ Failed

**Fail**

Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**Fail**

Nearside Side repeater not working (4.4.1 (a) (ii))

**Fail**

Offside Steering rack gaiter missing or no longer prevents the ingress of dirt inner clip missing (2.1.3 (g) (ii))

**MOT #22**

2021-03-17 09:40

**MOT test number**

591742656427

**Result**

✓ Passed

**Advice**

Nearside Front Tyre Slightly Scrubbing on outer edges

**MOT #21**

2021-03-15 15:09

**MOT test number**

383720103984

**Result**

✗ Failed

**Fail**

Parking brake efficiency below requirements (1.4.2 (a) (i))

**Advice**

Nearside Front Tyre Slightly Scrubbing on outer edges

**Fail**

Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Advice**

Rear Brake pad(s) wearing thin Both (1.1.13 (a) (ii))

**MOT #20**

2020-03-24 13:00

**MOT test number**

768937615626

**Result**

✓ Passed

**Advice**

Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #19** 2019-03-05 09:57**MOT test number** 860213848130**Result** ✓ Passed**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Park brake lever has little reserve travel**MOT #18** 2019-03-05 09:57**MOT test number** 216775905932**Result** ✗ Failed**Advice** Park brake lever has little reserve travel**Pass with rectification** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #17** 2018-03-12 08:59**MOT test number** 473222558213**Result** ✓ Passed**MOT #16** 2017-03-06 15:01**MOT test number** 354148056390**Result** ✓ Passed**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

**MOT #15** 2017-03-06 09:46**MOT test number** 967246705493**Result** ✗ Failed**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Fail** Offside Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Rear Tyre(s) incorrect because different size tyres are fitted on the same axle. (4.1.A.1a)**MOT #14** 2016-03-15 16:58**MOT test number** 975078151416**Result** ✓ Passed**MOT #13** 2016-03-15 11:30**MOT test number** 293140400678**Result** ✗ Failed**Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #12** 2015-03-04 11:58**MOT test number** 138253965002**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Notice** Engine covers fitted obscuring some components in the engine bay

**MOT #11**

2014-02-19 09:57

**MOT test number**

607230954020

**Result**

✓ Passed

- Notice** Child seat fitted not allowing full inspection of adult belt
- Notice** Slight corrosion on nsr brake pipe//
- Notice** Nsr tyre 3mm on edges//
- Notice** Under-trays fitted obscuring some underside components
- Notice** Slight play in osf steering rack arm//

**MOT #10**

2014-02-19 09:57

**MOT test number**

455340354014

**Result**

✗ Failed

- Notice** Slight play in osf steering rack arm//
- Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)
- Notice** Child seat fitted not allowing full inspection of adult belt
- Notice** Slight corrosion on nsr brake pipe//
- Notice** Nsr tyre 3mm on edges//
- Notice** Under-trays fitted obscuring some underside components

**MOT #9**

2013-03-11 16:56

**MOT test number**

315710873069

**Result**

✓ Passed

- Notice** Off side steering arm slight play
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Unable to see inner rear brake pads
- Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
- Notice** A/c condensor deteriorating

**MOT #8**

2013-03-11 13:21

**MOT test number**

655890073067

**Result**

✗ Failed

- Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
- Notice** Unable to see inner rear brake pads
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Brakes imbalanced across an axle (3.7.B.5b)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** A/c condensor deteriorating
- Notice** Off side steering arm slight play
- Fail** Offside Stop lamp not working (1.2.1b)
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #7**

2012-02-20 15:14

**MOT test number**

179431052060

**Result**

✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



**MOT #6** 2012-02-16 15:52**MOT test number** 138377942495**Result** ✗ Failed

- Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Nail in nearside front tyre
- Fail** Offside Headlamp aim too low (1.8)
- Fail** Nearside Front Coil spring not correctly located (2.4.C.2)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Fail** Nearside Headlamp aim too low (1.8)
- Fail** Nearside Front coil spring incomplete (2.4.C.1a)

**MOT #5** 2011-02-24 10:43**MOT test number** 517125951099**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #4** 2010-02-26 16:21**MOT test number** 353457350089**Result** ✓ Passed**MOT #3** 2010-02-26 10:28**MOT test number** 332627450055**Result** ✗ Failed

- Fail** Offside Front coil spring incomplete (2.4.C.1a)
- Notice** Nail in offside front tyre



MOT #2	2009-02-27 16:03
MOT test number	120428359042
Result	✓ Passed

MOT #1	2009-01-09 08:48
MOT test number	182219509045
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
23 March 2025

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	247
<b>MOT expiry date</b>	23 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history


For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 
Plate since	2019-06-29
Current registration	 
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	28
First mileage registration	2006-01-30
Last registration	2024-02-24
Complete history	<a href="#">See info</a>



Registration #1	2006-01-30	14 mi
Registration #2	2009-01-09	24.447 mi
Registration #3	2009-02-27	25.590 mi
Registration #4	2010-02-26	37.653 mi
Registration #5	2010-02-26	37.657 mi
Registration #6	2011-02-24	47.505 mi
Registration #7	2012-02-16	52.350 mi
Registration #8	2012-02-20	52.353 mi
Registration #9	2013-03-11	55.043 mi
Registration #10	2013-03-11	55.045 mi
Registration #11	2014-02-19	57.278 mi
Registration #12	2015-03-04	59.234 mi
Registration #13	2016-03-15	60.417 mi
Registration #14	2016-03-15	60.417 mi
Registration #15	2016-03-15	60.417 mi
Registration #16	2016-03-15	60.417 mi
Registration #17	2016-03-15	60.417 mi
Registration #18	2016-03-15	60.417 mi
Registration #19	2016-03-15	60.417 mi
Registration #20	2016-03-15	60.417 mi
Registration #21	2016-03-15	60.417 mi
Registration #22	2016-03-15	60.417 mi
Registration #23	2016-03-15	60.417 mi
Registration #24	2016-03-15	60.417 mi
Registration #25	2016-03-15	60.417 mi
Registration #26	2016-03-15	60.417 mi



Registration #27	2025-05-20	25,000,000
Registration #28	2025-05-20	25,000,000

[More info >](#)



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1777 mm
Height	1603 mm
Length	4270 mm
Wheel base	2778 mm
Kerb weight	1345 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	54 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	26696030182089