



report date: 2024-03-29

General information

Make	FIAT
Model	PUNTO ACTIVE
Colour	Blue
Year of manufacture	2009
Top speed	103 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-06-06
Pictures	3
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-11-02
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	24
Total items failed	8

MOT #16	2023-10-31 09:43
MOT test number	267580132738
Result	✓ Passed
Next expiry date	2024-11-02

MOT #15	2022-10-27 14:39
MOT test number	905701871699
Result	✓ Passed

MOT #14	2021-10-25 10:52
MOT test number	303038998702
Result	✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge wear inner edge (5.2.3 (e))
- Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #13**

2021-10-25 08:58

MOT test number

451980963533

Result

✗ Failed

Advice Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge wear inner edge (5.2.3 (e))**Fail** Emissions not tested lambda reading too high. began to overheat. s stopped emission test. (8.2.1.2 (d))**MOT #12**

2020-10-28 11:18

MOT test number

650666515301

Result

✓ Passed

MOT #11

2020-10-26 13:28

MOT test number

781841966091

Result

✗ Failed

Fail Nearside Front Road wheel distorted to the extent the tyre is likely to become detached (5.2.2 (c) (ii))**Fail** Exhaust system insecure (6.1.2 (a))**Advice** Nearside headlamp damaged**Fail** Emissions not tested (8.2.1.2 (d))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**Fail** Exhaust has a major leak of exhaust gases (6.1.2 (a))**Advice** Near side front suspension damaged

**MOT #10** 2019-11-01 09:45**MOT test number** 584051996083**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Center rear seat belt stalk casing missing**Advice** Oily residue on engine**MOT #9** 2018-10-26 12:31**MOT test number** 464603518173**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2018-10-26 08:15**MOT test number** 111781089219**Result** ✗ Failed**Fail** Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2017-11-03 08:56**MOT test number** 906107155334**Result** ✓ Passed**Advice** Nearside Rear Nail in tyre**Advice** Offside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**MOT #6** 2016-09-16 09:45**MOT test number** 597727812077**Result** ✓ Passed

**MOT #5** 2015-09-11 09:12**MOT test number** 334333952496**Result** ✓ Passed**Advice** Direction indicator slightly discoloured both front indicators (1.4.A.2f)**Advice** Tyre worn close to the legal limit both front tyres (4.1.E.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both discs (3.5.1i)**MOT #4** 2015-09-11 09:12**MOT test number** 126277173051**Result** ✗ Failed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both discs (3.5.1i)**Pass with rectification** Windscreen wiper does not clear the windscreen effectively both blades (8.2.2)**Advice** Direction indicator slightly discoloured both front indicators (1.4.A.2f)**Advice** Tyre worn close to the legal limit both front tyres (4.1.E.1)**MOT #3** 2014-09-16 12:01**MOT test number** 335279554281**Result** ✓ Passed**Notice** Oil level low**Notice** Front brake discs slightly worn**MOT #2** 2013-09-09 10:50**MOT test number** 417082953241**Result** ✓ Passed**MOT #1** 2012-09-11 10:37**MOT test number** 358325452292**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
2 November 2024

Tax status	Valid until 1 December
Days left	217
MOT expiry date	2 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-09-04
Last registration	2023-10-31
Complete history	See info



Registration #1	2009-09-04	16 mi
Registration #2	2012-09-11	18.634 mi
Registration #3	2013-09-09	23.184 mi
Registration #4	2014-09-16	27.157 mi
Registration #5	2015-09-11	33.727 mi
Registration #6	2015-09-11	33.727 mi
Registration #7	2016-09-16	39.021 mi
Registration #8	2017-11-03	40.775 mi
Registration #9	2018-10-26	57.374 mi
Registration #10	2019-09-04	58.377 mi
Registration #11	2019-09-04	58.377 mi
Registration #12	2019-09-04	58.377 mi
Registration #13	2019-09-04	58.377 mi
Registration #14	2019-09-04	58.377 mi
Registration #15	2019-09-04	58.377 mi
Registration #16	2019-09-04	58.377 mi
Registration #17	2019-09-04	58.377 mi
Registration #18	2019-09-04	58.377 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9519694