





report date: 2024-03-28

General information

Make	MINI
Model	COUNTRYMAN COOPER D COOPER D
Colour	Grey
Year of manufacture	2011
Top speed	115 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	67.3 mpg
Consumption combined	64.2 mpg
CO2 emission	115 g/km
CO2 label	С



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2022-01-29

Pictures 1

Listing price View report



source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-09-21
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	9
Total items failed	11

MOT #15	2023-09-16 08:53
MOT test number	383540160486
Result	✓ Passed
Next expiry date	2024-09-21

MOT #14	2022-09-22 10:15
MOT test number	901976106263
Result	✓ Passed

MOT #13		2022-09-22 10:15
MOT test number		266363851420
Result		× Failed
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))	

MOT #12	2022-02-10 11:37
MOT test number	319428651638
Result	✓ Passed

MOT #11	2021-10-07 08:21
MOT test number	802644362289
Result	✓ Passed

CarCheck.co.uk page 3/13



MOT #10 2020-10-07 09:37

MOT test number 326249979759

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9 2019-09-06 11:51

MOT test number 189850933602

Result ✓ Passed

MOT #8 2018-11-20 13:54

MOT test number 174594633307

MOT #7 2018-11-19 14:40

MOT test number 200515871313

Result X Failed

MAJOR Electronic stability control warning lamp indicates a fault (7.12 (e))

Minor Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))

DANGEROUS Offside Rear Tyre has a lump, caused by separation or partial failure of its structure 215 55 17 (5.2.3 (d) (ii))

MAJOR Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

MAJOR Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #6 2017-09-13 16:30

MOT test number 283529250907

Result ✓ Passed

CarCheck.co.uk page 4/13



MOT #5 2017-09-13 07:16

MOT test number 353579953630

Result X Failed

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 205 55 17 (4.1.D.1a)

Fail Tyre pressure monitoring system warning lamp indicates a fault (4.1.D.4)

Fail Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #4 2016-09-27 08:21

MOT test number 236180227247

Result ✓ Passed

MOT #3 2015-06-09 09:15

MOT test number 748720665151

Result ✓ Passed

MOT #2 2014-06-06 15:18

MOT test number 175897354139

Result
✓ Passed

Notice Offside front tyre has a cut but not deep enough to reach the ply or cords

CarCheck.co.uk page 5/13



Fail

HN11HZA report date: 2024-03-28

MOT #1 2014-06-05 17:00

MOT test number 778896054145 Result **★** Failed Fail Offside Front Headlamp aim too low (1.8) Fail Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g) Notice Offside front tyre has a cut but not deep enough to reach the ply or cords Fail Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3) Nearside Front Headlamp aim too low (1.8) Fail Fail Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c) Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g) Fail

Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)

CarCheck.co.uk page 6/13



Tax & MOT check





Expires: 21 September 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	21 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category



Extra MINI salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	OK SIN
Plate since	
	Moro info

CarCheck.co.uk page 10/13



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-05-14
Last registration	2023-09-16
Complete history	See info



Registration #1	2011-05-14	7 mi
Registration #2	2014-06-05	16.806 mi
Registration #3	2014-06-06	16.807 mi
Registration #4	2015-06-09	24.193 mi
Registration #5	2016-09-27	36.394 mi
Registration #6	2017-09-13	44.577 mi
Registration #7	2017-09-13	44.577 mi
Registration #8	2018-11-19	57.432 mi
Registration #9	2018-11-20	57.433 mi
Registration #10		11.777 ea
Registration #11		11.117 es
Registration #12		71.777 es
Registration #13		11.117 es
Registration #14		71.777 es
Registration #15		11.117 es
Registration #16		11.177 es
Registration #17		11.177 ms

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
50482	
50501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4097 mm
Wheel base	2595 mm
Kerb weight	1310 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	47 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page 1:	3/13

Number of axles 2

Engine number 73137786