



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	GETZ CDX
Colour	Blue
Year of manufacture	-
Top speed	100 mph
0 - 60 mph	11.5 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	81 BHP
Max. torque	116 Nm at 3.200 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	28.5 mpg
Consumption extra urban	45.6 mpg
Consumption combined	37.2 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-11-27
Pictures	12
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #23	2022-11-22 14:00
MOT test number	528228968152
Result	✓ Passed
Next expiry date	2023-11-23
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #22	2021-11-24 11:35
MOT test number	843012615123
Result	✓ Passed
Advice	Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #21	2021-11-16 13:55
MOT test number	959426311174
Result	✗ Failed
Fail	Oil leaking excessively from engine (8.4.1 (a) (i))
Fail	Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Rear Brake pipe excessively corroded (1.1.11 (c))
Fail	Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #20	2020-10-29 11:03
MOT test number	773226867237
Result	✓ Passed

MOT #19	2020-10-29 11:03
MOT test number	408340406463
Result	✗ Failed
Pass with rectification	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #18** 2019-11-04 11:14**MOT test number** 585644641946**Result** ✓ Passed**MOT #17** 2019-11-04 11:14**MOT test number** 961356551627**Result** ✗ Failed**Pass with rectification** Front Exhaust has a major leak of exhaust gases (6.1.2 (a))**MOT #16** 2018-11-21 12:55**MOT test number** 552279708515**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #15** 2018-11-21 12:55**MOT test number** 433112077101**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**MOT #14** 2017-10-24 15:17**MOT test number** 313164127013**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Vehicle structure has slight corrosion chassis rail (6.1.A.1)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)

**MOT #13** 2017-10-24 11:43**MOT test number** 150980068630**Result** ✗ Failed**Fail** Central Exhaust has a major leak of exhaust gases (7.1.2)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Vehicle structure has slight corrosion chassis rail (6.1.A.1)**MOT #12** 2016-11-22 11:50**MOT test number** 154057007973**Result** ✓ Passed**Advice** Central Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #11** 2016-01-23 12:08**MOT test number** 553166604486**Result** ✓ Passed**Advice** Offside Front Upper Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**Advice** Offside Front Upper Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**MOT #10** 2015-01-19 14:36**MOT test number** 267269315096**Result** ✓ Passed**MOT #9** 2014-01-31 09:15**MOT test number** 988161134098**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #8** 2013-01-29 17:18**MOT test number** 226639723033**Result** ✓ Passed**MOT #7** 2013-01-29 17:18**MOT test number** 856619923058**Result** ✗ Failed**Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)**Pass with rectification** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)**MOT #6** 2011-12-12 10:44**MOT test number** 837446241306**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Notice** Engine management light on**Advice** Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**Notice** Air bag light on**MOT #5** 2010-12-03 11:46**MOT test number** 441257430460**Result** ✓ Passed**MOT #4** 2009-12-10 11:33**MOT test number** 522104349310**Result** ✓ Passed



MOT #3	2008-09-24 14:49
MOT test number	791568868288
Result	✓ Passed
<div>NoticeO/S/F Tyre wearing on inner edge</div>	

MOT #2	2007-10-16 15:30
MOT test number	772379887262
Result	✓ Passed

MOT #1	2006-11-21 17:35
MOT test number	684235526306
Result	✓ Passed



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	LK53KPE
Plate since	2019-03-29
Current registration	LK53KPE
Plate since	2019-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2003-12-01
Last registration	2022-11-22
Complete history	See info



Registration #1	2003-12-01	14 mi
Registration #2	2006-11-21	29.160 mi
Registration #3	2007-10-16	38.405 mi
Registration #4	2008-09-24	44.795 mi
Registration #5	2010-12-03	51.922 mi
Registration #6	2011-12-12	53.858 mi
Registration #7	2013-01-29	56.959 mi
Registration #8	2014-01-31	60.308 mi
Registration #9	2015-01-19	63.901 mi
Registration #10	2016-01-23	64.722 mi
Registration #11	2016-11-22	65.471 mi
Registration #12	2017-10-24	66.879 mi
Registration #13	2018-05-22	68.277 mi
Registration #14	2019-05-22	69.277 mi
Registration #15	2020-05-22	70.277 mi
Registration #16	2021-05-22	71.277 mi
Registration #17	2022-05-22	72.277 mi
Registration #18	2023-05-22	73.277 mi
Registration #19	2024-05-22	74.277 mi
Registration #20	2025-05-22	75.277 mi
Registration #21	2026-05-22	76.277 mi
Registration #22	2027-05-22	77.277 mi
Registration #23	2028-05-22	78.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1665 mm
Height	1490 mm
Length	3810 mm
Wheel base	2455 mm
Kerb weight	1125 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	G4EA2272321