





report date: 2024-03-28

General information

Make	LAND ROVER
Model	FREELANDER SD4 GS
Colour	Blue
Year of manufacture	2014
Top speed	118 mph
0 - 100 km/h	9.5 seconds
0 - 60 mph	8.7 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	140 kW / 191 HP / 190 BHP
Max. torque	420 Nm at 1.750 rpm
Engine capacity	2.179 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.5 mpg
Consumption extra urban	48.7 mpg
Consumption combined	40.4 mpg
CO2 emission	185 g/km
CO2 label	I



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-09-19

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-09-23
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	10
Total items failed	5

MOT #11	2023-09-13 11:08
MOT test number	264719315385
Result	✓ Passed
Next expiry date	2024-09-23
Advice Nearside rear tyre becoming worn. starting to perish/crack	

MOT #10	2022-09-12 10:44
MOT test number	436300332822
Result	✓ Passed
Advice Front brake pads very worn (recommend replacement)	

MOT #9	2021-09-24 10:23
MOT test number	508650725596
Result	✓ Passed

I	мот #	8	2021-09-22 15:25
Ī	MOT te	est number	418934620146
F	Result		X Failed
	Fail	Offside Headlamp not working on main beam (4.1.1 (a) (ii))	
	Fail	Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))	

CarCheck.co.uk page 3/12



MOT #7 2020-09-24 11:14

MOT test number 379624870583

Result \rightarrow Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #6 2019-09-12 15:02

MOT test number 408222956909

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #5 2019-09-12 15:02

MOT test number 954500187533

Result X Failed

Pass with rectification Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #4 2018-09-14 08:16

MOT test number 362817299111

Result \(\sqrt{Passed} \)

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 4/12



MOT #3 2018-09-12 15:19

MOT test number 178762810862

Result

X Failed

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice

Offside Rear Child Seat fitted not allowing full inspection of adult belt

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #2 2017-07-25 15:43

MOT test number 660949270906

MOT #1 2017-07-25 09:37

MOT test number 285736324921

Result

× Failed

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

CarCheck.co.uk page 5/12



Tax & MOT check





Expires: 23 September 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	23 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 6/12



LC14AUN

report date: 2024-03-28

Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category

Type

Date

Damage 2

Category

Type



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

Owner history	
For how long did the current and previous owner(s) have this LAND ROVER? How many or ROVER have? Check it in the premium report and see all owner registrations. Download to	
THE PARTY OF THE P	

	More info >
Plate changes	
See in this check if this LAND ROVER had different number plates.	
Number of plates	,
Current registration	器 UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-06-27
Last registration	2023-09-13
Complete history	See info



Registration #1	2014-06-27	22 mi
Registration #2	2017-07-25	29.543 mi
Registration #3	2017-07-25	29.543 mi
Registration #4	2018-09-12	41.761 mi
Registration #5	2018-09-14	41.762 mi
Registration #6	2019-09-12	55.171 mi
Registration #7	2019-09-12	55.171 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.177 es
Registration #11		11.177 ms
Registration #12		11.777 es
Registration #13		D.777 es

More info >

CarCheck.co.uk page 11/12



Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2005 mm
Height	1740 mm
Length	4500 mm
Wheel base	2660 mm
Kerb weight	1745 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	68 I
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	DZ784181354224DT

CarCheck.co.uk page 12/12